



Technical Report: (5205) 333-0526(A)

Date: 5 December 2005

Page 1 of 4


**Photographs:**

**EUT Interior**

Sample Description: Malibu Boats  
Vehicle (49.860 MHz Receiver)

FCC ID (if applicable): SZ23267R49

Photo No. 1: PCB Solder Side





Technical Report: (5205) 333-0526(A)

Date: 5 December 2005

Page 2 of 4


**Photographs:**

**EUT Interior**

Sample Description: Malibu Boats  
Vehicle (49.860 MHz Receiver)

FCC ID (if applicable): SZ23267R49

**Photo No. 2: PCB Component Side**





Technical Report: (5205) 333-0526(A)

Date: 5 December 2005

Page 3 of 4


**Photographs:**

**EUT Interior**

Sample Description: Malibu Boats  
Vehicle (49.860 MHz Receiver)

FCC ID (if applicable): **SZ23267R49**

**Photo No. 3: The component placement and the assembly**





Technical Report: (5205) 333-0526(A)

Date: 5 December 2005

Page 4 of 4

**Photographs:**

**EUT Interior**

Sample Description: Malibu Boats  
Vehicle (49.860 MHz Receiver)

FCC ID (if applicable): **SZ23267R49**

**Photo No. 4: The component placement and the assembly**

