



**FUSIONSOFT Co.,Ltd.**

969-7, Dongcheon-Dong, Buk-Gu, Daegu, 702-250, KOREA  
Tel. +82-2-571-8283 Fax +82-2-573-7710

---

March 17, 2007

Federal Communications Commission  
Equipment Authorization Branch  
7435 Oakland Mills Road  
Columbia, MD 21046

**Cover letter**  
**In re : FUSIONSOFT Co.,Ltd.**  
**FCC ID : T76N700D**

Gentlemen:

Q) Please explain the new test report. Why does one test report show non-compliance? Was the device modified? If so, how?

A) The device is not modified. I confirmed what were the problem. I found the problem.

It was the reason that the junction of an audio filtering part fell off. This device is opened for the internal photo in the laboratory. I think that The problem seems to come into being in the course.

Sincerely,

A handwritten signature in black ink, appearing to read '김승환' (Kim Seung-hwan).

**Seung-Hwan Kim**  
**Associate Research Engineer**