

Application Letter

Date: Apr 18, 2007

American Telecommunications Certification Body, Inc.
6371 Whittier Avenue
Suite C110
McLean, VA 22101

RE: Class change II for TL-WA501G

FCC ID: TE7WA50XG

Dear Sir/Madam,


We would like to have a class change II on TL-WA501G, this ID has granted last year. We are going to delete a LDO which Designator is VR2, and change some layout as follow.

1. Change the position (Designators: R48, D12, D13, R187,)
2. Delete the component (Designator: VR2)
3. Change the encapsulation (16pin to 8pin, Designator: U24)
4. Change the encapsulation of crystal (RF only)

The necessary test data were performed in the new test report SZ070320B09-RP. Please review.

Thank you for your attention on these matters.

Sincerely yours,


Xudong Liu
TP-LINK Technologies Co., Ltd.