

# Internal Photos of EUT



Report No.: CCISE190707101

Model No. : MBP50APU

Page: 1 of 8





# Internal Photos of EUT



Report No.: CCISE190707101

Model No. : MBP50APU

Page: 2 of 8




# Internal Photos of EUT



Report No.: CCISE190707101

Model No. : MBP50APU

Page: 3 of 8




# Internal Photos of EUT



Report No.: CCISE190707101

Model No. : MBP50APU

Page: 4 of 8





# Internal Photos of EUT



Report No.: CCISE190707101

Model No. : MBP50APU

Page: 5 of 8



# Internal Photos of EUT



Report No.: CCISE190707101

Model No. : MBP50APU

Page: 6 of 8




# Internal Photos of EUT



Report No.: CCISE190707101

Model No. : MBP50APU

Page: 7 of 8




# Internal Photos of EUT



Report No.: CCISE190707101

Model No. : MBP50APU

Page: 8 of 8



--THE END--