


Spurious Emissions at Antenna Terminal

FCC Part 22H


B5 , Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 09:23:20

1.4MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 09:23:56

1.4MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 09:24:31

3MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 09:25:34

3MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 09:26:09

3MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 09:26:44

5MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:28:00

5MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:28:34

5MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:29:06

10MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:31:07

10MHz_Middle_QPSK_1@0



ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:31:40

10MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:32:14

FCC Part 24E


B2 , Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 19_JUL.2024 23:50:27

1.4MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 19_JUL.2024 23:51:05

1.4MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 19_JUL.2024 23:51:43

3MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 19_JUL.2024 23:53:12

3MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 19_JUL.2024 23:53:52

3MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 19_JUL.2024 23:54:30

5MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 19_JUL.2024 23:55:44

5MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 19_JUL.2024 23:56:23

5MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 19_JUL.2024 23:57:00

10MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 19_JUL.2024 23:59:22

10MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 19_JUL.2024 23:59:59

10MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 00:00:34

15MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 00:03:36

15MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 00:04:18

15MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 00:04:57

20MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 00:06:08

20MHz_Middle_QPSK_1@0



ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 00:06:48

20MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 00:07:25

FCC Part 27


B4 , Normal

1.4MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 09:09:48

1.4MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 00:09:24

1.4MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 09:10:00

3MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 00:11:03

3MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 09:11:40

3MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 00:12:18

5MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:13:37

5MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:14:17

5MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:14:55

10MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:16:09

10MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:16:47

10MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:17:27

15MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:18:41

15MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:19:19

15MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:19:56

20MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:21:26

20MHz_Middle_QPSK_1@0



ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:22:03


20MHz_High_QPSK_1@0



ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:22:39


B7 , Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:33:01

5MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:33:46

5MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:34:30

10MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:35:57

10MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:36:42

10MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:37:28

15MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:38:44

15MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:39:29

15MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:40:13

20MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:41:33

20MHz_Middle_QPSK_1@0



ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:42:18


20MHz_High_QPSK_1@0



ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:43:02


B38 , Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:44:09

5MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:44:56

5MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:45:41

10MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:47:58

10MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:48:44

10MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:49:31

15MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 00:50:44

15MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 00:51:29

15MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 00:52:15

20MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 00:53:36

20MHz_Middle_QPSK_1@0



ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 00:54:21


20MHz_High_QPSK_1@0



ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20_JUL.2024 00:55:04


B41 , Normal

5MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:55:55

5MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:56:43

5MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:57:30

10MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:58:45

10MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 00:59:30

10MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 01:00:15

15MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 01:01:48

15MHz_Middle_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 01:02:35

15MHz_High_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 01:03:20

20MHz_Low_QPSK_1@0




ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 01:04:36

20MHz_Middle_QPSK_1@0



ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 01:05:22

20MHz_High_QPSK_1@0



ProjectNo.:2402V85163E-RF Tester:Loge Long
Date: 20.JUL.2024 01:06:08