











NTNV\_N78-3450-3550\_PC2\_30\_40\_H\_TID5\_N/A  
\_30\_1000\_#1NTNV\_N78-3450-3550\_PC2\_30\_40\_H\_TID5\_N/A  
\_1000\_3000\_#1NTNV\_N78-3450-3550\_PC2\_30\_40\_H\_TID5\_N/A  
\_3000\_12000\_#1NTNV\_N78-3450-3550\_PC2\_30\_40\_H\_TID5\_N/A  
\_12000\_20000\_#1NTNV\_N78-3450-3550\_PC2\_30\_40\_H\_TID6\_N/A  
\_0.009\_0.15\_#1NTNV\_N78-3450-3550\_PC2\_30\_40\_H\_TID6\_N/A  
\_0.15\_30\_#1




NTNV\_N78-3450-3550\_PC2\_30\_40\_H\_TID16\_N/  
A\_0.009\_0.15\_#1




NTNV\_N78-3450-3550\_PC2\_30\_40\_H\_TID16\_N/  
A\_0.15\_30\_#1



NTNV\_N78-3450-3550\_PC2\_30\_40\_H\_TID16\_N/  
A\_30\_1000\_#1





NTNV\_N78-3450-3550\_PC2\_30\_40\_H\_TID16\_N/  
A\_1000\_3000\_#1








NTNV\_N78-3450-3550\_PC2\_30\_40\_H\_TID16\_N/  
A\_3000\_12000\_#1

NTNV\_N78-3450-3550\_PC2\_30\_40\_H\_TID16\_N/  
A\_12000\_20000\_#1







NTNV\_N78-3450-3550\_PC2\_30\_50\_L\_TID4\_N/A  
\_30\_1000\_#1NTNV\_N78-3450-3550\_PC2\_30\_50\_L\_TID4\_N/A  
\_1000\_3000\_#1NTNV\_N78-3450-3550\_PC2\_30\_50\_L\_TID4\_N/A  
\_3000\_12000\_#1NTNV\_N78-3450-3550\_PC2\_30\_50\_L\_TID4\_N/A  
\_12000\_20000\_#1NTNV\_N78-3450-3550\_PC2\_30\_50\_L\_TID5\_N/A  
\_0.009\_0.15\_#1NTNV\_N78-3450-3550\_PC2\_30\_50\_L\_TID5\_N/A  
\_0.15\_30\_#1

