













NTNV_N78-3450-3550_PC2_30_90_H_TID5_N/A
_0.009_0.15_#1




NTNV_N78-3450-3550_PC2_30_90_H_TID5_N/A
_0.15_30_#1



NTNV_N78-3450-3550_PC2_30_90_H_TID5_N/A
_30_1000_#1



NTNV_N78-3450-3550_PC2_30_90_H_TID5_N/A
_1000_3000_#1



NTNV_N78-3450-3550_PC2_30_90_H_TID5_N/A
_3000_12000_#1

NTNV_N78-3450-3550_PC2_30_90_H_TID5_N/A
_12000_20000_#1

