



SIEMIC, INC.
Accessing global markets


Title: EMC Test Report for dianxiaobao
Main Model: UP2
Serial Model: N/A
To: FCC Part 18 Subpart C, FCC Measurement Procedure MP-5 (1986)

Report No.: 13070483-FCC-E1-18
Issue Date: November 26, 2013
Page: 30 of 37
www.siemic.com.cn

Annex B.iii. Photograph 3: Test Setup Photo



Conducted Emissions Test Setup Front View



Conducted Emissions Test Setup Side View




SIEMIC, INC.
Accessing global markets

Title: EMC Test Report for dianxiaobao
Main Model: UP2
Serial Model: N/A
To: FCC Part 18 Subpart C, FCC Measurement Procedure MP-5 (1986)

Report No.: 13070483-FCC-E1-18
Issue Date: November 26, 2013
Page: 31 of 37
www.siemic.com.cn



Radiated Spurious Emissions Test Setup Below 30 MHz - Front View



Radiated Spurious Emissions Test Setup Above 30 MHz - Front View