



INTERTEK TESTING SERVICES

CDMA 850
1x RTT




INTERTEK TESTING SERVICES


EV-DO Rev.0



*RBW 100 kHz Marker 2 [T1]
*VBW 300 kHz -34.18 dBm
SWT 90 ms 729.556089744 MHz



*RBW 100 kHz Marker 2 [T1]
*VBW 300 kHz -30.84 dBm
SWT 820 ms 3.559615385 GHz




INTERTEK TESTING SERVICES


EV-DO Rev.A



*RBW 100 kHz Marker 2 [T1]
*VBW 300 kHz -32.94 dBm
SWT 90 ms 565.756410256 MHz





*RBW 100 kHz Marker 2 [T1]
*VBW 300 kHz -31.39 dBm
SWT 820 ms 2.613461538 GHz



INTERTEK TESTING SERVICES

CDMA 1900
1x RTT




INTERTEK TESTING SERVICES


EV-DO Rev.0



*RBW 1 MHz Marker 2 [T1]
*VBW 3 MHz -24.98 dBm
SWT 5 ms 1.618919872 GHz



*RBW 1 MHz Marker 2 [T1]
*VBW 3 MHz -21.72 dBm
SWT 105 ms 17.656250000 GHz




INTERTEK TESTING SERVICES

EV-DO Rev.A



*RBW 1 MHz
*VBW 3 MHz
SWT 5 ms

Marker 2 [T1]
-24.67 dBm
1.622043269 GHz



*RBW 1 MHz
*VBW 3 MHz
SWT 105 ms

Marker 2 [T1]
-22.27 dBm
12.975961538 GHz

