FCC Part 96.47 TEST REPORT

FCC ID : 2ABZ2-EE143 **Equipment** : Smart Phone : ONEPLUS **Brand Name Model Name** : HD1925

Applicant : OnePlus Technology (shenzhen) Co., Ltd

18C02, 18C03, 18C04 and 18C05, Shum Yip Terra

Building, Binhe Avenue North, Futian District, Shenzhen

Report No.: FG982715

Manufacturer : OnePlus Technology (shenzhen) Co., Ltd

18C02, 18C03, 18C04 and 18C05, Shum Yip Terra

Building, Binhe Avenue North, Futian District, Shenzhen

Standard : FCC Part 96.47

The product was received on Aug. 27, 2019 and testing was started from Oct. 09, 2019 and completed on Oct. 09, 2019. We, SPORTON INTERNATIONAL INC., would like to declare that the tested sample has been evaluated in accordance with the test procedures and has been in compliance with the applicable technical standards.

The report must not be used by the client to claim product certification, approval, or endorsement by TAF or any agency of government.

The test results in this report apply exclusively to the tested model / sample. Without written approval of SPORTON INTERTIONAL INC. EMC & Wireless Communications Laboratory, the test report shall not be reproduced except in full.

Approved by: Jones Tsai

SPORTON INTERTIONAL INC. EMC & Wireless Communications Laboratory

No. 52, Huaya 1st Rd., Guishan Dist., Taoyuan City, Taiwan (R.O.C.)

TEL: 886-3-327-3456 : 1 of 10 Page Number FAX: 886-3-328-4978 Report Issued Date: Oct. 24, 2019 Report Version : 01

Table of Contents

Report No. : FG982715

His	story o	of this test report	3
		ry of Test Result	
		eral Description	
	1.1	Product Feature of Equipment Under Test	F.
	1.3	Testing Location	Ę
		Applicable Standards	
2		Configuration of Equipment Under Test	
		Connection Diagram of Test System	
3	End	User Device additional requirement	
		Test Requirement	
	3.2	Test Procedure	7
	3.3	Test Result	8
4	List	of Measuring Equipment	10
Αp	pendi	ix A Test Setup Photo	

TEL: 886-3-327-3456 Page Number : 2 of 10
FAX: 886-3-328-4978 Report Issued Date : Oct. 24, 2019

Report Version

: 01

History of this test report

Report No. : FG982715

: 01

Report No.	Version	Description	Issued Date
FG982715	01	Initial issue of report	Oct. 24, 2019

TEL: 886-3-327-3456 Page Number : 3 of 10
FAX: 886-3-328-4978 Report Issued Date : Oct. 24, 2019

Report Template No.: BU5- CR247WL5G AC MA Version 2.1 Report Version

Summary of Test Result

Report No. : FG982715

Report Clause	Ref Std. Clause	Test Items	Result (PASS/FAIL)	Remark	
3	96.47	End User Device additional requirement	Pass	-	

Declaration of Conformity:

The test results with all measurement uncertainty excluded are presented in accordance with the regulation limits or requirements declared by manufacturers.

Comments and Explanations:

The declared of product specification for EUT presented in the report are provided by the manufacturer, and the manufacturer takes all the responsibilities for the accuracy of product specification.

Reviewed by: William Chen Report Producer: Jessie Ho

TEL: 886-3-327-3456 Page Number : 4 of 10
FAX: 886-3-328-4978 Report Issued Date : Oct. 24, 2019

Report Version

: 01

1 General Description

1.1 Product Feature of Equipment Under Test

GSM/WCDMA/CDMA/LTE, Bluetooth, Wi-Fi 2.4GHz 802.11b/g/n, Wi-Fi 5GHz 802.11a/n/ac, 5G NR, NFC, and GNSS.

Report No.: FG982715

THE O, AND CITED.				
Product Specification subjective to this standard				
	WWAN: PIFA Antenna			
	WLAN			
	<ant. 1="">: PIFA Antenna</ant.>			
Antenna Type	<ant. 2="">: PIFA Antenna</ant.>			
Antenna Type	Bluetooth: PIFA Antenna			
	GPS / Glonass / Galileo / BDS / SBAS : PIFA Antenna			
	NFC: Coil Inductive type Antenna			
	5G NR: PIFA Antenna			

1.2 Modification of EUT

No modifications are made to the EUT during all test items.

1.3 Testing Location

Sporton Lab is accredited to ISO 17025 by Taiwan Accreditation Foundation (TAF code: 1190) and the FCC designation No. TW1190 under the FCC 2.948(e) by Mutual Recognition Agreement (MRA) in FCC Test.

Test Site	SPORTON INTERNATIONAL INC. EMC & Wireless Communications Laboratory
Test Site Location	No.52, Huaya 1st Rd., Guishan Dist., Taoyuan City, Taiwan (R.O.C.) TEL: +886-3-327-3456 FAX: +886-3-328-4978
Test Site No.	Sporton Site No.
	DFS02-HY

Note: The test site complies with ANSI C63.4 2014 requirement.

1.4 Applicable Standards

- FCC Part 96.47
- FCC KDB 940660 D01 Part 96 CBRS Eqpt v02
- WINNF-TS-0122-V1.0.1 CBRS CBSD Test Specification


Remark: All test items were verified and recorded according to the standards and without any deviation during the test.

TEL: 886-3-327-3456 Page Number : 5 of 10
FAX: 886-3-328-4978 Report Issued Date : Oct. 24, 2019

Report Template No.: BU5- CR247WL5G AC MA Version 2.1 Report Version : 01

2 Test Configuration of Equipment Under Test

2.1 Connection Diagram of Test System



Report No.: FG982715

The companion device is certified CBRS (FCC ID: S9GQ910US00)

TEL: 886-3-327-3456 Page Number : 6 of 10
FAX: 886-3-328-4978 Report Issued Date : Oct. 24, 2019

Report Version

: 01

3 End User Device additional requirement

3.1 Test Requirement

FCC Part 96.47

(a) End User Devices may operate only if they can positively receive and decode an authorization signal transmitted by a CBSD, including the frequencies and power limits for their operation.

Report No.: FG982715

(1) An End User Device must discontinue operations, change frequencies, or change its operational power level within 10 seconds of receiving instructions from its associated CBSD.

3.2 Test Procedure


Following procedure can be done by applying WINNF-TS-0122-V1.0.1 CBRS CBSD Test Specification, use the certified Ruckus CBSD (FCC ID: S9GQ910US00) as companion device to show compliance with Part 96.47 requirement for End User Device (EUD):

- 1. Setup with frequency 3600-3620MHz and power level 17dBm/MHz
- 2. Enable AP service from Ruckus Cloud management
- 3. Check EUD Tx Frequency and power
- 4. Disable AP service from Ruckus Cloud management
 - a. Check EUD stops transmission within 10seconds.
- 5. Setup with 3670-3690MHz & power level 7dBm/MHz
- 6. Enable AP service from Ruckus Cloud management
- 7. Check EUD Tx Frequency and power
- 8. Disable AP service from Ruckus Cloud management
 - a. Check EUD stops transmission within 10seconds.

TEL: 886-3-327-3456 Page Number: 7 of 10
FAX: 886-3-328-4978 Report Issued Date: Oct. 24, 2019


Report Template No.: BU5- CR247WL5G AC MA Version 2.1 Report Version : 01

3.3 Test Result



Report No. : FG982715


: 01



TEL: 886-3-327-3456 Page Number : 8 of 10
FAX: 886-3-328-4978 Report Issued Date : Oct. 24, 2019


Report Template No.: BU5- CR247WL5G AC MA Version 2.1 Report Version





Report No. : FG982715

: 01



TEL: 886-3-327-3456 Page Number : 9 of 10
FAX: 886-3-328-4978 Report Issued Date : Oct. 24, 2019

Report Template No.: BU5- CR247WL5G AC MA Version 2.1 Report Version

4 List of Measuring Equipment

Instrument	Manufacturer	Model No.	Serial No.	Characteristics	Calibration Date	Test Date	Due Date	Remark
Spectrum Analyzer	Rohde & Schwarz	FSV30	103738	9kHz ~ 30GHz	May 23, 2019	Oct. 09, 2019	May 22, 2020	DFS02-HY

Report No. : FG982715

TEL: 886-3-327-3456 Page Number : 10 of 10 FAX: 886-3-328-4978 Report Issued Date : Oct. 24, 2019

Report Template No.: BU5- CR247WL5G AC MA Version 2.1 Report Version : 01

Appendix A Test Setup Photo



Report No. : FG982715

———THE END———

TEL: 886-3-327-3456 Page Number : A1 of A1

FAX: 886-3-328-4978