

Audit Mode Request Letter

TIMCO Engineering, Inc.

This is to request audit mode of FCC ID: 2ACCJH105,

RF output power, radiated spurious emission and radiated band-edge were verified and retested by Tianjin Dongdian Testing Service Co., Ltd.

The EUT is operating at the same power level with the original testing of SGS-CSTC Standards Technical Services, Co., Ltd. Shenzhen Branch.


Other data are referred from the original reports issued by SGS-CSTC Standards Technical Services, Co., Ltd. Shenzhen Branch.

All the test detail data in the test reports which we will upload after audit mode.

The major change filed under this application and the relevant report numbers are as below:

Equipment class	Original report number	Date of test	Retest report number	Date of test for retest items	Revise content
PCE	ZR/2019/2000801	2019/2/22 ~2019/3/7	DDT-B22030103-1E01	2022/03/01 ~2022/03/09	<ol style="list-style-type: none">1. Retest the Field Strength of Spurious Radiation2. Verify RF output power
DSS	ZR/2019/2000803	2019/2/22 ~ 2019/3/7	DDT-B22030103-1E02	2022/03/01 ~2022/03/09	<ol style="list-style-type: none">1. Retest the radiated spurious emission and Radiated band-edge.2. Verify RF output power
DTS	ZR/2019/2000804	2019/2/22 ~ 2019/3/7	DDT-B22030103-1E03	2022/03/01 ~2022/03/09	<ol style="list-style-type: none">1. Retest the radiated spurious emission and Radiated band-edge.2. Verify RF output power
DTS	ZR/2019/2000802	2019/2/22 ~2019/3/15	DDT-B22030103-1E04	2022/03/01 ~2022/03/09	<ol style="list-style-type: none">1. Retest the radiated spurious emission and Radiated band-edge.2. Verify RF output power

Sincerely,


(signature)
(printed name) Derek Yang