



# TEST REPORT

No.I20N02478-HAC

For

**TCL Communication Ltd.**

**GSM/UMTS/LTE Mobile phone**

**Model Name: 5007S**

**With**

**Hardware Version: 03**

**Software Version: v2D23UZ31**

**FCC ID: 2ACCJH130**

**Note:**

The test results in this test report relate only to the devices specified in this report. This report shall not be reproduced except in full without the written approval of SAICT.

**Test Laboratory:**

**SAICT, Shenzhen Academy of Information and Communications Technology**


Building G, Shenzhen International Innovation Center, No.1006 Shennan Road, Futian District, Shenzhen, Guangdong, P. R. China 518026.

Tel:+86(0)755-33322000, Fax:+86(0)755-33322001

Email: [yewu@caict.ac.cn](mailto:yewu@caict.ac.cn) [www.saict.ac.cn](http://www.saict.ac.cn)



**Picture 1: Constituents of the sample**



**Picture 2: EUT Positioning for RF/T-coil**