




n41_30kHz_SISO_NTNV_10MHz_CP-OFDM 16 QAM 2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_10MHz_CP-OFDM 64 QAM 2592.99MHz_Outer_Full_Ant4







3.2.2 30k_SISO_15MHz_NTNV




n41_30kHz_SISO_NTNV_15MHz_DFT-s-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_15MHz_DFT-s-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_15MHz_DFT-s-OFDM_256_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_15MHz_CP-OFDM_QPSK_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_15MHz_CP-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_15MHz_CP-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant4







3.2.3 30k_SISO_20MHz_NTNV




n41_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_20MHz_DFT-s-OFDM_256_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_20MHz_CP-OFDM_QPSK_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_20MHz_CP-OFDM 16 QAM 2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_20MHz_CP-OFDM 64 QAM 2592.99MHz_Outer_Full_Ant4







3.2.4 30k_SISO_25MHz_NTNV




n41_30kHz_SISO_NTNV_25MHz_DFT-s-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_25MHz_DFT-s-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_25MHz_DFT-s-OFDM_256_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_25MHz_CP-OFDM_QPSK_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_25MHz_CP-OFDM 16 QAM 2592.99MHz Outer Full Ant4




n41_30kHz_SISO_NTNV_25MHz_CP-OFDM 64 QAM 2592.99MHz Outer Full Ant4







3.2.5 30k_SISO_30MHz_NTNV




n41_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_30MHz_DFT-s-OFDM_256_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_30MHz_CP-OFDM_QPSK_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_30MHz_CP-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_30MHz_CP-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_30MHz_CP-OFDM_256_QAM_2592.99MHz_Outer_Full_Ant4




3.2.6 30k_SISO_35MHz_NTNV




n41_30kHz_SISO_NTNV_35MHz_DFT-s-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_35MHz_DFT-s-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_35MHz_DFT-s-OFDM_256_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_35MHz_CP-OFDM_QPSK_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_35MHz_CP-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_35MHz_CP-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant4







3.2.7 30k_SISO_40MHz_NTNV




n41_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_40MHz_CP-OFDM 16 QAM 2592.99MHz Outer Full Ant4




n41_30kHz_SISO_NTNV_40MHz_CP-OFDM 64 QAM 2592.99MHz Outer Full Ant4




n41_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_2592.99MHz_Outer_Full_Ant4




3.2.8 30k_SISO_45MHz_NTNV




n41_30kHz_SISO_NTNV_45MHz_DFT-s-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_45MHz_DFT-s-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_45MHz_DFT-s-OFDM_256_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_45MHz_CP-OFDM_QPSK_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_45MHz_CP-OFDM 16 QAM 2592.99MHz Outer Full Ant4




n41_30kHz_SISO_NTNV_45MHz_CP-OFDM 64 QAM 2592.99MHz Outer Full Ant4







3.2.9 30k_SISO_50MHz_NTNV




n41_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_50MHz_DFT-s-OFDM_256_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_50MHz_CP-OFDM_QPSK_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_50MHz_CP-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_50MHz_CP-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_50MHz_CP-OFDM_256_QAM_2592.99MHz_Outer_Full_Ant4




3.2.10 30k_SISO_60MHz_NTNV




n41_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_16_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_64_QAM_2592.99MHz_Outer_Full_Ant4




n41_30kHz_SISO_NTNV_60MHz_DFT-s-OFDM_256_QAM_2592.99MHz_Outer_Full_Ant4



n41_30kHz_SISO_NTNV_60MHz_CP-OFDM_QPSK_2592.99MHz_Outer_Full_Ant4



n41_30kHz_SISO_NTNV_60MHz_CP-OFDM 16 QAM 2592.99MHz Outer Full Ant4



n41_30kHz_SISO_NTNV_60MHz_CP-OFDM 64 QAM 2592.99MHz Outer Full Ant4

