

TCL Communication Ltd.

5F, C-Tower, No.232, Liangjing Road, Zhangjiang High-tech Park, Pudong, Shanghai, China
Tel: +86 21 51798260 ; Fax: +86 21 61460600


Date: August 27, 2015

FCC Laboratory
7435 Oakland Mills Rd.
Columbia, MD 21046

SUBJECT: FCC Application for FCC ID: 2ACCJN005

In accordance with §15.407(j), we acknowledge that should any harmful interference generated by FCC ID: 2ACCJN005 to licensed services in 5.15-5.25 GHz, corrective action is required to be taken. Corrective actions may include reducing power, turning off devices, changing frequency bands, and/or further reducing power radiated in the vertical direction.

Sincerely yours,



Zhizhou GONG
Product Certification Manager
TCL Communication Ltd.

Zhizhou Gong
zhizhou.gong@tcl.com