



n38_15MHz_30kHz_2595MHz_CP-OFDM 64
QAM_RB38@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:28:54

n38_15MHz_30kHz_2595MHz_CP-OFDM 256
QAM_RB38@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:29:26

n38_15MHz_30kHz_2595MHz_CP-OFDM 256
QAM_RB38@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:29:34

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:30:35

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:30:43

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB50@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:31:21

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB50@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 09:31:29

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM 16
QAM_RB50@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 09:32:00

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM 16
QAM_RB50@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 09:32:09

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM 64
QAM_RB50@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 09:32:40

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM 64
QAM_RB50@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 09:32:48

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM 256
QAM_RB50@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 09:33:21

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM 256
QAM_RB50@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:33:30

n38_20MHz_30kHz_2595MHz_CP-OFDM
QPSK_RB51@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:34:05

n38_20MHz_30kHz_2595MHz_CP-OFDM QPSK_RB51@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:34:14

n38_20MHz_30kHz_2595MHz_CP-OFDM 16
QAM_RB51@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:34:45

n38_20MHz_30kHz_2595MHz_CP-OFDM 16
QAM_RB51@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:34:53

n38_20MHz_30kHz_2595MHz_CP-OFDM 64
QAM_RB51@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:35:24

n38_20MHz_30kHz_2595MHz_CP-OFDM 64
QAM_RB51@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 09:35:33

n38_20MHz_30kHz_2595MHz_CP-OFDM 256
QAM_RB51@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 09:36:05

n38_20MHz_30kHz_2595MHz_CP-OFDM 256
QAM_RB51@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 09:36:14

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM $\pi/2$
BPSK_RB64@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 09:37:16

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM $\pi/2$
BPSK_RB64@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 09:37:26

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB64@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 09:38:04

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB64@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaeter Liang
Date: 31.DEC.2024 09:38:14

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM 16
QAM_RB64@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaeter Liang
Date: 31.DEC.2024 09:38:46

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM 16
QAM_RB64@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaeter Liang
Date: 31.DEC.2024 09:38:55

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM 64
QAM_RB64@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaeter Liang
Date: 31.DEC.2024 09:39:27

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM 64
QAM_RB64@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaeter Liang
Date: 31.DEC.2024 09:39:36

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM 256
QAM_RB64@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaeter Liang
Date: 31.DEC.2024 09:40:10

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM 256
QAM_RB64@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 09:40:20

n38_25MHz_30kHz_2595MHz_CP-OFDM
QPSK_RB65@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 09:40:57

n38_25MHz_30kHz_2595MHz_CP-OFDM QPSK_RB65@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 09:41:06

n38_25MHz_30kHz_2595MHz_CP-OFDM 16
QAM_RB65@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 09:41:38

n38_25MHz_30kHz_2595MHz_CP-OFDM 16
QAM_RB65@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 09:41:48

n38_25MHz_30kHz_2595MHz_CP-OFDM 64
QAM_RB65@0




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 09:42:20

n38_25MHz_30kHz_2595MHz_CP-OFDM 64
QAM_RB65@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:42:30

n38_25MHz_30kHz_2595MHz_CP-OFDM 256
QAM_RB65@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:43:06

n38_25MHz_30kHz_2595MHz_CP-OFDM 256
QAM_RB65@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:43:15

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:44:30

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:44:40

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:45:21

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:45:31

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM 16
QAM_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:46:06

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM 16
QAM_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:46:16

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM 64
QAM_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:46:50

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM 64
QAM_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:47:00

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM 256
QAM_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:47:36

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM 256
QAM_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:47:46

n38_30MHz_30kHz_2595MHz_CP-OFDM
QPSK_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:48:24

n38_30MHz_30kHz_2595MHz_CP-OFDM QPSK_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:48:35

n38_30MHz_30kHz_2595MHz_CP-OFDM 16
QAM_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:49:08

n38_30MHz_30kHz_2595MHz_CP-OFDM 16
QAM_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:49:19

n38_30MHz_30kHz_2595MHz_CP-OFDM 64
QAM_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:49:53

n38_30MHz_30kHz_2595MHz_CP-OFDM 64
QAM_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:50:03

n38_30MHz_30kHz_2595MHz_CP-OFDM 256
QAM_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:50:38

n38_30MHz_30kHz_2595MHz_CP-OFDM 256
QAM_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:50:49

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:52:08

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:52:20

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 09:53:03

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaeter Liang
Date: 31.DEC.2024 09:53:15

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM 16
QAM_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaeter Liang
Date: 31.DEC.2024 09:53:52

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM 16
QAM_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaeter Liang
Date: 31.DEC.2024 09:54:04

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM 64
QAM_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaeter Liang
Date: 31.DEC.2024 09:54:40

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM 64
QAM_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaeter Liang
Date: 31.DEC.2024 09:54:52

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM 256
QAM_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaeter Liang
Date: 31.DEC.2024 09:55:31

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM 256
QAM_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:55:43

n38_40MHz_30kHz_2595MHz_CP-OFDM
QPSK_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:56:24

n38_40MHz_30kHz_2595MHz_CP-OFDM QPSK_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:56:36

n38_40MHz_30kHz_2595MHz_CP-OFDM 16
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:57:12

n38_40MHz_30kHz_2595MHz_CP-OFDM 16
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:57:24

n38_40MHz_30kHz_2595MHz_CP-OFDM 64
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 09:58:01

n38_40MHz_30kHz_2595MHz_CP-OFDM 64
QAM_RB106@0



ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 09:58:13


n38_40MHz_30kHz_2595MHz_CP-OFDM 256
QAM_RB106@0



ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 09:58:51


n41

n38_40MHz_30kHz_2595MHz_CP-OFDM 256
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 09:59:03

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 10:01:09

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 10:01:17

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 10:01:56

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:02:03

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:02:35

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:02:42

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:03:15

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:03:23

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 10:03:57

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:04:05

n41_10MHz_30kHz_2592.99MHz_CP-OFDM
QPSK_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:04:42

n41_10MHz_30kHz_2592.99MHz_CP-OFDM
QPSK_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:04:49

n41_10MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:05:22

n41_10MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:05:30

n41_10MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 10:06:02

n41_10MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 10:06:10

n41_10MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 10:06:43

n41_10MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 10:06:51

n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB36@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 10:07:54

n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM $\pi/2$
BPSK_RB36@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 10:08:02

n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB36@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaater Liang
Date: 31.DEC.2024 10:08:42


n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB36@0




n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB36@0




n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM 16
QAM_RB36@0



n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB36@0



n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM_RB36@0



n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM 256
QAM_RB36@0

