



n77_3_30MHz_30kHz_3840MHz_DFT-s-OFDM 256
QAM_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JAN.2025 17:01:41

n77_3_30MHz_30kHz_3840MHz_CP-OFDM
QPSK_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JAN.2025 17:02:18

n77_3_30MHz_30kHz_3840MHz_CP-OFDM
QPSK_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JAN.2025 17:02:28

n77_3_30MHz_30kHz_3840MHz_CP-OFDM 16
QAM_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JAN.2025 17:03:01

n77_3_30MHz_30kHz_3840MHz_CP-OFDM 16
QAM_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JAN.2025 17:03:11

n77_3_30MHz_30kHz_3840MHz_CP-OFDM 64
QAM_RB78@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JAN.2025 17:03:44

n77_3_30MHz_30kHz_3840MHz_CP-OFDM 64
QAM_RB78@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:03:54

n77_3_30MHz_30kHz_3840MHz_CP-OFDM 256
QAM_RB78@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:04:29

n77_3_30MHz_30kHz_3840MHz_CP-OFDM 256
QAM_RB78@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:04:38

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:05:41

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:05:53

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:06:35

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 17:06:46

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM 16
QAM_RB100@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 17:07:22

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM 16
QAM_RB100@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 17:07:33

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM 64
QAM_RB100@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 17:08:09

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM 64
QAM_RB100@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 17:08:21

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM 256
QAM_RB100@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 17:08:58

n77_3_40MHz_30kHz_3840MHz_DFT-s-OFDM 256
QAM_RB100@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 17:09:10

n77_3_40MHz_30kHz_3840MHz_CP-OFDM
QPSK_RB106@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 17:09:49

n77_3_40MHz_30kHz_3840MHz_CP-OFDM
QPSK_RB106@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 17:10:01

n77_3_40MHz_30kHz_3840MHz_CP-OFDM 16
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 17:10:36

n77_3_40MHz_30kHz_3840MHz_CP-OFDM 16
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 17:10:48

n77_3_40MHz_30kHz_3840MHz_CP-OFDM 64
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 17:11:23

n77_3_40MHz_30kHz_3840MHz_CP-OFDM 64
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JFN.2025 17:11:36

n77_3_40MHz_30kHz_3840MHz_CP-OFDM 256
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JFN.2025 17:12:12

n77_3_40MHz_30kHz_3840MHz_CP-OFDM 256
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JFN.2025 17:12:24

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JFN.2025 17:13:29

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JFN.2025 17:13:43

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JFN.2025 17:14:26

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JPN.2025 17:14:39

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM 16
QAM_RB128@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JPN.2025 17:15:16

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM 16
QAM_RB128@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JPN.2025 17:15:29

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM 64
QAM_RB128@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JPN.2025 17:16:06

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM 64
QAM_RB128@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JPN.2025 17:16:19

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM 256
QAM_RB128@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JPN.2025 17:16:58

n77_3_50MHz_30kHz_3840MHz_DFT-s-OFDM 256
QAM_RB128@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:17:11

n77_3_50MHz_30kHz_3840MHz_CP-OFDM
QPSK_RB133@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:17:52

n77_3_50MHz_30kHz_3840MHz_CP-OFDM
QPSK_RB133@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:18:05

n77_3_50MHz_30kHz_3840MHz_CP-OFDM 16
QAM_RB133@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:18:42

n77_3_50MHz_30kHz_3840MHz_CP-OFDM 16
QAM_RB133@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:18:56

n77_3_50MHz_30kHz_3840MHz_CP-OFDM 64
QAM_RB133@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:19:33

n77_3_50MHz_30kHz_3840MHz_CP-OFDM 64
QAM_RB133@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 2..JFN.2025 17:19:46

n77_3_50MHz_30kHz_3840MHz_CP-OFDM 256
QAM_RB133@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 2..JFN.2025 17:20:25

n77_3_50MHz_30kHz_3840MHz_CP-OFDM 256
QAM_RB133@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 2..JFN.2025 17:20:38

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM $\pi/2$
BPSK_RB162@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 2..JFN.2025 17:22:16

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM $\pi/2$
BPSK_RB162@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 2..JFN.2025 17:22:31

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 2..JFN.2025 17:23:16

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2-JUN-2025 17:23:31

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM 16
QAM_RB162@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2-JUN-2025 17:24:09

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM 16
QAM_RB162@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2-JUN-2025 17:24:24

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM 64
QAM_RB162@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2-JUN-2025 17:25:03

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM 64
QAM_RB162@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2-JUN-2025 17:25:18

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM 256
QAM_RB162@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2-JUN-2025 17:25:59

n77_3_60MHz_30kHz_3840MHz_DFT-s-OFDM 256
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:26:14

n77_3_60MHz_30kHz_3840MHz_CP-OFDM
QPSK_RB162@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:26:56

n77_3_60MHz_30kHz_3840MHz_CP-OFDM
QPSK_RB162@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:27:11

n77_3_60MHz_30kHz_3840MHz_CP-OFDM 16
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:27:51

n77_3_60MHz_30kHz_3840MHz_CP-OFDM 16
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:28:05

n77_3_60MHz_30kHz_3840MHz_CP-OFDM 64
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:28:44

n77_3_60MHz_30kHz_3840MHz_CP-OFDM 64
QAM_RB162@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:28:59

n77_3_60MHz_30kHz_3840MHz_CP-OFDM 256
QAM_RB162@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:29:39

n77_3_60MHz_30kHz_3840MHz_CP-OFDM 256
QAM_RB162@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:29:54

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM $\pi/2$
BPSK_RB180@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:31:02

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM $\pi/2$
BPSK_RB180@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:31:18

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:32:06

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 17:32:23

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM 16
QAM_RB180@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 17:33:03

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM 16
QAM_RB180@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 17:33:20

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM 64
QAM_RB180@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 17:34:00

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM 64
QAM_RB180@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 17:34:16

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM 256
QAM_RB180@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 17:34:59

n77_3_70MHz_30kHz_3840MHz_DFT-s-OFDM 256
QAM_RB180@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JUN.2025 17:35:15

n77_3_70MHz_30kHz_3840MHz_CP-OFDM
QPSK_RB189@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JUN.2025 17:36:00

n77_3_70MHz_30kHz_3840MHz_CP-OFDM
QPSK_RB189@0



ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JUN.2025 17:36:16

n77_3_70MHz_30kHz_3840MHz_CP-OFDM 16
QAM_RB189@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JUN.2025 17:36:57

n77_3_70MHz_30kHz_3840MHz_CP-OFDM 16
QAM_RB189@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JUN.2025 17:37:13

n77_3_70MHz_30kHz_3840MHz_CP-OFDM 64
QAM_RB189@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JUN.2025 17:37:53

n77_3_70MHz_30kHz_3840MHz_CP-OFDM 64
QAM_RB189@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:38:10

n77_3_70MHz_30kHz_3840MHz_CP-OFDM 256
QAM_RB189@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:38:52

n77_3_70MHz_30kHz_3840MHz_CP-OFDM 256
QAM_RB189@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:39:08

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM $\pi/2$
BPSK_RB216@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:40:19

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM $\pi/2$
BPSK_RB216@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:40:37

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:41:25

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 17:41:43

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM 16
QAM_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 17:42:26

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM 16
QAM_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 17:42:44

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM 64
QAM_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 17:43:25

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM 64
QAM_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 17:43:43

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM 256
QAM_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 17:44:27

n77_3_80MHz_30kHz_3840MHz_DFT-s-OFDM 256
QAM_RB216@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:44:45

n77_3_80MHz_30kHz_3840MHz_CP-OFDM
QPSK_RB217@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:45:31

n77_3_80MHz_30kHz_3840MHz_CP-OFDM
QPSK_RB217@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:45:49

n77_3_80MHz_30kHz_3840MHz_CP-OFDM 16
QAM_RB217@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:46:31

n77_3_80MHz_30kHz_3840MHz_CP-OFDM 16
QAM_RB217@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:46:49

n77_3_80MHz_30kHz_3840MHz_CP-OFDM 64
QAM_RB217@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JPN.2025 17:47:32

n77_3_80MHz_30kHz_3840MHz_CP-OFDM 64
QAM_RB217@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:47:50

n77_3_80MHz_30kHz_3840MHz_CP-OFDM 256
QAM_RB217@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:48:34

n77_3_80MHz_30kHz_3840MHz_CP-OFDM 256
QAM_RB217@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:48:52

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM $\pi/2$
BPSK_RB243@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:50:04

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM $\pi/2$
BPSK_RB243@0



ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:50:24

n77_3_90MHz_30kHz_3840MHz_DFT-s-OFDM
QPSK_RB243@0



ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 2..JFN.2025 17:51:15