



n78_1_30MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB78@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:38:16

n78_1_30MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB78@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:38:53

n78_1_30MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB78@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:39:04

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:40:10

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:40:22

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:41:06


n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB100@0




n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB100@0




n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB100@0




n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB100@0




n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB100@0



n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB100@0




n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB100@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 18:43:52

n78_1_40MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB106@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 18:44:34

n78_1_40MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB106@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 18:44:47

n78_1_40MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 18:45:25

n78_1_40MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 18:45:38

n78_1_40MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB106@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 18:46:16

n78_1_40MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB106@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:46:29

n78_1_40MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB106@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:47:08

n78_1_40MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB106@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:47:21

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:48:29

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:48:43

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:49:29

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 18:49:43

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB128@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 18:50:23

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB128@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 18:50:37

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB128@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 18:51:17

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB128@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 18:51:31

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB128@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2..JAN.2025 18:52:13

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB128@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 18:52:26

n78_1_50MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB133@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 18:53:10

n78_1_50MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB133@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 18:53:23

n78_1_50MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB133@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 18:54:04

n78_1_50MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB133@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 18:54:18

n78_1_50MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB133@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 18:54:58

n78_1_50MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB133@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:55:12

n78_1_50MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB133@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:55:54

n78_1_50MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB133@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:56:08

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB162@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:57:20

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB162@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:57:35

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 18:58:22

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2-JUN-2025 18:58:37

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB162@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2-JUN-2025 18:59:19

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB162@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2-JUN-2025 18:59:34

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB162@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2-JUN-2025 19:00:15

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB162@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2-JUN-2025 19:00:30

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB162@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 2-JUN-2025 19:01:13

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:01:28

n78_1_60MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB162@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:02:14

n78_1_60MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB162@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:02:29

n78_1_60MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:03:11

n78_1_60MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:03:26

n78_1_60MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:04:09

n78_1_60MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JAN.2025 19:04:24

n78_1_60MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JAN.2025 19:05:07

n78_1_60MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB162@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JAN.2025 19:05:22

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB180@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JAN.2025 19:06:36

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB180@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JAN.2025 19:06:53

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 2..JAN.2025 19:07:43

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:08:00

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB180@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:08:43

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB180@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:09:00

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB180@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:09:43

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB180@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:10:00

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB180@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:10:45

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB180@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:11:02

n78_1_70MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB189@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:11:49

n78_1_70MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB189@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:12:06

n78_1_70MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB189@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:12:50

n78_1_70MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB189@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:13:07

n78_1_70MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB189@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:13:51

n78_1_70MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB189@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:14:08

n78_1_70MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB189@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:14:53

n78_1_70MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB189@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:15:09

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:16:26

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:16:44

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:17:35

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:17:53

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:18:38

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:18:56

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:19:41

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:19:59

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:20:45

n78_1_80MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB216@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:21:03

n78_1_80MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB217@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:21:52

n78_1_80MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB217@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:22:11

n78_1_80MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB217@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:22:56

n78_1_80MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB217@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:23:15

n78_1_80MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB217@0




ProjectNo.:2401A43118E-RF Tester:Mingfumeister Liang
Date: 2..JFN.2025 19:24:00

n78_1_80MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB217@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 19:24:18

n78_1_80MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB217@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 19:25:04

n78_1_80MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB217@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 19:25:22

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB243@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 19:26:41

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB243@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 19:27:01

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB243@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeester Liang
Date: 2..JFN.2025 19:27:55

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB243@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:28:16

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB243@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:29:03

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB243@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:29:24

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB243@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:30:12

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB243@0



ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:30:32

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB243@0



ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JAN.2025 19:31:22