



n38_20MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB50@0 -36.14dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JFN.2025 08:04:50

n38_20MHz_30kHz_2610MHz_DFT-s-OFDM
QPSK_RB1@0 -37.37dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JFN.2025 08:05:46

n38_20MHz_30kHz_2610MHz_DFT-s-OFDM
QPSK_RB1@50 -37.32dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JFN.2025 08:06:38

n38_20MHz_30kHz_2610MHz_DFT-s-OFDM
QPSK_RB50@0 -37.35dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JFN.2025 08:07:29

n38_25MHz_30kHz_2582.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.29dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JFN.2025 08:17:36

n38_25MHz_30kHz_2582.5MHz_DFT-s-OFDM
QPSK_RB1@64 -36.76dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JFN.2025 08:18:27

n38_25MHz_30kHz_2582.5MHz_DFT-s-OFDM
QPSK_RB64@0 -37.45dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 08:19:17

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -36.62dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 08:20:14

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@64 -37.07dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 08:21:06

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB64@0 -37.40dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 08:21:57

n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.13dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 08:22:54

n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM
QPSK_RB1@64 -37.19dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 08:23:45

n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM
QPSK_RB64@0 -37.26dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 08:24:35

n38_30MHz_30kHz_2585MHz_DFT-s-OFDM
QPSK_RB1@0 -37.32dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 08:29:16

n38_30MHz_30kHz_2585MHz_DFT-s-OFDM
QPSK_RB1@77 -37.55dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 08:30:08

n38_30MHz_30kHz_2585MHz_DFT-s-OFDM
QPSK_RB75@0 -37.42dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 08:30:57

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -36.36dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 08:50:50

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@77 -37.51dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 08:51:44

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB75@0 -37.18dBm




ProjectNo.:2401A43118E-RF Testee:Kungfumeester Liang
Date: 2..JPN.2025 08:52:36

n38_30MHz_30kHz_2605MHz_DFT-s-OFDM
QPSK_RB1@0 -37.50dBm




ProjectNo.:2401A43118E-RF Testee:Kungfumeester Liang
Date: 2..JPN.2025 10:01:14

n38_30MHz_30kHz_2605MHz_DFT-s-OFDM
QPSK_RB1@77 -37.17dBm




ProjectNo.:2401A43118E-RF Testee:Kungfumeester Liang
Date: 2..JPN.2025 10:02:00

n38_30MHz_30kHz_2605MHz_DFT-s-OFDM
QPSK_RB75@0 -37.41dBm




ProjectNo.:2401A43118E-RF Testee:Kungfumeester Liang
Date: 2..JPN.2025 09:02:27

n38_40MHz_30kHz_2590MHz_DFT-s-OFDM
QPSK_RB100@0 -36.80dBm




ProjectNo.:2401A43118E-RF Testee:Kungfumeester Liang
Date: 2..JPN.2025 09:08:02

n38_40MHz_30kHz_2590MHz_DFT-s-OFDM
QPSK_RB1@0 -37.05dBm




ProjectNo.:2401A43118E-RF Testee:Kungfumeester Liang
Date: 2..JPN.2025 09:06:14

n38_40MHz_30kHz_2590MHz_DFT-s-OFDM
QPSK_RB1@105 -36.43dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 2..JPN.2025 09:07:10

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB100@0 -37.03dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 2..JPN.2025 09:10:51

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@0 -37.49dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 2..JPN.2025 09:09:02

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB1@105 -36.90dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 2..JPN.2025 09:09:58

n38_40MHz_30kHz_2600MHz_DFT-s-OFDM
QPSK_RB100@0 -37.11dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 2..JPN.2025 09:13:40


n38_40MHz_30kHz_2600MHz_DFT-s-OFDM
QPSK_RB1@0 -37.40dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumeester Liang
Date: 2..JPN.2025 09:11:51


n41

n38_40MHz_30kHz_2600MHz_DFT-s-OFDM
QPSK_RB1@105 -37.41dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 2..F.N.2025 09:12:47

n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB1@0 -37.22dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 11:21:13

n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB1@23 -37.14dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 14:22:05

n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB24@0 -37.63dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 11:22:57

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -36.98dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 14:23:54

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@23 -37.15dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 11:24:45

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB24@0 -36.90dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 14:25:37

n41_10MHz_30kHz_2685MHz_DFT-s-OFDM
QPSK_RB1@0 -37.21dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 14:26:34

n41_10MHz_30kHz_2685MHz_DFT-s-OFDM
QPSK_RB1@23 -36.86dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 14:27:26

n41_10MHz_30kHz_2685MHz_DFT-s-OFDM
QPSK_RB24@0 -36.79dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 14:28:18

n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.51dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 14:32:19

n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM
QPSK_RB1@37 -37.03dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 14:33:03

n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM
QPSK_RB36@0 -36.91dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 14:33:56

n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -36.71dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 11:34:56

n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@37 -37.28dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 14:35:48

n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB36@0 -37.60dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 11:36:41

n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM
QPSK_RB1@0 -37.62dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 14:37:40

n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM
QPSK_RB1@37 -36.64dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 11:38:33

n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM
QPSK_RB36@0 -37.36dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 14:39:26

n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM
QPSK_RB1@0 -37.25dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 11:42:33

n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM
QPSK_RB1@50 -36.70dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 14:43:26

n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM
QPSK_RB50@0 -37.60dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 11:44:19

n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -36.99dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 14:45:18

n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@50 -35.81dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 11:46:12

n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB50@0 -37.79dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 14:47:05

n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.02dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 14:48:05

n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM
QPSK_RB1@50 -37.22dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 14:48:58

n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM
QPSK_RB50@0 -37dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 14:49:52

n41_30MHz_30kHz_2511MHz_DFT-s-OFDM
QPSK_RB1@0 -37.40dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 14:51:51

n41_30MHz_30kHz_2511MHz_DFT-s-OFDM
QPSK_RB1@77 -36.17dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 14:52:44

n41_30MHz_30kHz_2511MHz_DFT-s-OFDM
QPSK_RB75@0 -36.71dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 14:53:37

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.10dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 11:54:36

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@77 -37.14dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 14:55:31

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB75@0 -37.17dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 11:56:24

n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM
QPSK_RB1@0 -37.45dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 14:57:25

n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM
QPSK_RB1@77 -37.03dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 11:58:19