



n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM
QPSK_RB75@0 -37.12dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 14:59:11

n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM
QPSK_RB100@0 -37.09dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 15:04:10

n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM
QPSK_RB1@0 -37.49dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 15:02:22

n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM
QPSK_RB1@105 -37.57dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 15:03:17

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB100@0 -37.29dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 15:06:57

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -36.39dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 15:05:10

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@105 -37.13dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 15:06:04

n41_40MHz_30kHz_2670MHz_DFT-s-OFDM
QPSK_RB100@0 -37.26dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 15:09:48

n41_40MHz_30kHz_2670MHz_DFT-s-OFDM
QPSK_RB1@0 -36.78dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 15:07:59

n41_40MHz_30kHz_2670MHz_DFT-s-OFDM
QPSK_RB1@105 -37.48dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 15:08:53

n41_50MHz_30kHz_2521.02MHz_DFT-s-OFDM
QPSK_RB128@0 -36.90dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 15:14:08

n41_50MHz_30kHz_2521.02MHz_DFT-s-OFDM
QPSK_RB1@0 -37.22dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 31.DEC.2024 15:12:20

n41_50MHz_30kHz_2521.02MHz_DFT-s-OFDM
QPSK_RB1@132 -36.70dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:13:15

n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB128@0 -36.43dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:17:04

n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.09dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:15:14

n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@132 -37.15dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:16:10

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM
QPSK_RB128@0 -37.17dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:20:15

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.03dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:18:26

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM
QPSK_RB1@132 -37.35dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 15:19:21

n41_60MHz_30kHz_2526MHz_DFT-s-OFDM
QPSK_RB162@0 -37.45dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 15:25:28

n41_60MHz_30kHz_2526MHz_DFT-s-OFDM
QPSK_RB1@0 -37.17dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 15:23:39

n41_60MHz_30kHz_2526MHz_DFT-s-OFDM
QPSK_RB1@161 -37.16dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 15:24:34

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB162@0 -36.81dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 15:28:23

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.44dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 15:26:33

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@161 -36.85dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:27:29

n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM
QPSK_RB162@0 -37.46dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:31:14

n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM
QPSK_RB1@0 -36.30dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:29:23

n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM
QPSK_RB1@161 -36.88dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:30:19

n41_80MHz_30kHz_2536.02MHz_DFT-s-OFDM
QPSK_RB1@0 -37.59dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 17:23:58

n41_80MHz_30kHz_2536.02MHz_DFT-s-OFDM
QPSK_RB1@216 -37.22dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:36:34

n41_80MHz_30kHz_2536.02MHz_DFT-s-OFDM
QPSK_RB216@0 -37.27dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:37:28

n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -36.98dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:38:29

n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@216 -36.49dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:39:24

n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB216@0 -37.37dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:40:18

n41_80MHz_30kHz_2649.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.29dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:41:20

n41_80MHz_30kHz_2649.99MHz_DFT-s-OFDM
QPSK_RB1@216 -37.42dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:42:14

n41_80MHz_30kHz_2649.99MHz_DFT-s-OFDM
QPSK_RB216@0 -37.31dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:43:08

n41_90MHz_30kHz_2541MHz_DFT-s-OFDM
QPSK_RB1@0 -36.96dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:45:12

n41_90MHz_30kHz_2541MHz_DFT-s-OFDM
QPSK_RB1@244 -37.01dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:46:07

n41_90MHz_30kHz_2541MHz_DFT-s-OFDM
QPSK_RB243@0 -37.21dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:47:01

n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.35dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:48:08

n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@244 -36.72dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 15:49:05


n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB243@0 -37.25dBm




n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM
QPSK_RB1@0 -37.52dBm




n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM
QPSK_RB1@244 -36.47dBm




n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM
QPSK_RB243@0 -37.44dBm




n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM
QPSK_RB1@0 -37.83dBm



n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM
QPSK_RB1@272 -37.16dBm




n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM
QPSK_RB270@0 -37.22dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 16:03:03

n41_100MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.65dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 16:04:04

n41_100MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@272 -37.46dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 16:05:00

n41_100MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB270@0 -37.16dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 16:05:55

n41_100MHz_30kHz_2640MHz_DFT-s-OFDM
QPSK_RB1@0 -37.56dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 16:06:58


n41_100MHz_30kHz_2640MHz_DFT-s-OFDM
QPSK_RB1@272 -37.39dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaister Liang
Date: 31.DEC.2024 16:07:53

n66


n41_100MHz_30kHz_2640MHz_DFT-s-OFDM
QPSK_RB270@0 -36.95dBm




n66_5MHz_15kHz_1712.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.55dBm




n66_5MHz_15kHz_1712.5MHz_DFT-s-OFDM
QPSK_RB1@24 -38.59dBm




n66_5MHz_15kHz_1712.5MHz_DFT-s-OFDM
QPSK_RB25@0 -38.21dBm




n66_5MHz_15kHz_1745MHz_DFT-s-OFDM QPSK_RB1@0
-38.31dBm



n66_5MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@24 -38.10dBm




n66_5MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB25@0 -38dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 16:21:52

n66_5MHz_15kHz_1777.5MHz_DFT-s-OFDM
QPSK_RB1@0 -38.10dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 16:23:11

n66_5MHz_15kHz_1777.5MHz_DFT-s-OFDM
QPSK_RB1@24 -38.07dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 16:24:01

n66_5MHz_15kHz_1777.5MHz_DFT-s-OFDM
QPSK_RB25@0 -37.90dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 16:24:50

n66_10MHz_15kHz_1715MHz_DFT-s-OFDM
QPSK_RB1@0 -37.61dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 17:35:44

n66_10MHz_15kHz_1715MHz_DFT-s-OFDM
QPSK_RB1@51 -37.58dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 17:36:36