



n7_10MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB50@0 -36.55dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 13:26:18

n7_10MHz_15kHz_2565MHz_DFT-s-OFDM
QPSK_RB1@0 -37.01dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 11:27:31

n7_10MHz_15kHz_2565MHz_DFT-s-OFDM
QPSK_RB1@51 -37.03dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 13:28:19

n7_10MHz_15kHz_2565MHz_DFT-s-OFDM
QPSK_RB50@0 -37.14dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 11:29:07

n7_15MHz_15kHz_2507.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.39dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 14:07:00

n7_15MHz_15kHz_2507.5MHz_DFT-s-OFDM
QPSK_RB1@78 -37.36dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaester Liang
Date: 31.DEC.2024 11:07:53

n7_15MHz_15kHz_2507.5MHz_DFT-s-OFDM
QPSK_RB75@0 -37.41dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 14:08:45

n7_15MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@0 -37.39dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 11:10:02

n7_15MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@78 -36.78dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 14:10:54

n7_15MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB75@0 -37.06dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 11:51:36

n7_15MHz_15kHz_2562.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.27dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 13:52:53

n7_15MHz_15kHz_2562.5MHz_DFT-s-OFDM
QPSK_RB1@78 -36.67dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumaaster Liang
Date: 31.DEC.2024 13:53:45

n7_15MHz_15kHz_2562.5MHz_DFT-s-OFDM
QPSK_RB75@0 -36.75dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 13:54:37

n7_20MHz_15kHz_2510MHz_DFT-s-OFDM
QPSK_RB100@0 -37.23dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 11:13:38

n7_20MHz_15kHz_2510MHz_DFT-s-OFDM
QPSK_RB1@0 -37.50dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 14:11:54

n7_20MHz_15kHz_2510MHz_DFT-s-OFDM
QPSK_RB1@105 -37.15dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 11:12:46

n7_20MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB100@0 -37.18dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 14:16:19

n7_20MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@0 -37.35dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumastr Liang
Date: 31.DEC.2024 11:14:35

n7_20MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@105 -36.68dBm




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 14:15:27

n7_20MHz_15kHz_2560MHz_DFT-s-OFDM
QPSK_RB100@0 -36.74dBm




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 14:19:01

n7_20MHz_15kHz_2560MHz_DFT-s-OFDM
QPSK_RB1@0 -37.29dBm



ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 14:17:16


n7_20MHz_15kHz_2560MHz_DFT-s-OFDM
QPSK_RB1@105 -37.36dBm



ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 31.DEC.2024 14:18:08


n77_1

n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@0 -34.66dBm




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 2..JAN.2025 23:38:24

n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@23 -34.90dBm




ProjectNo.:2401A43118E-RF Tester:Kungfmaster Liang
Date: 2..JAN.2025 23:39:43

n77_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB24@0 -37.79dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 23:41:01

n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -33.62dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 23:42:24

n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@23 -37.58dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 23:43:43

n77_1_10MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB24@0 -37.83dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 23:45:01

n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@0 -37.75dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 23:46:24

n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@23 -37.21dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 23:47:42

n77_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB24@0 -38.39dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 23:48:56

n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@0 -35.27dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 23:50:15

n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@37 -36.27dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 23:51:29

n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0 -37.73dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 23:52:41

n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.09dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 23:53:58

n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@37 -37.83dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 23:55:08

n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB36@0 -36.96dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 2..JPN.2025 23:56:20

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.98dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 07:04:14

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@37 -37dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 07:05:05

n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0 -38.18dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 07:05:55

n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@0 -34.35dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 07:06:54

n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@50 -34.06dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 07:07:46

n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB50@0 -37.57dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 07:08:37

n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -37.41dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 00:34:05

n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@50 -37.31dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 00:35:21

n77_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB50@0 -38.19dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 00:36:34

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@0 -38.05dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 07:09:34

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@50 -37.96dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 00:46:09

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB50@0 -38.33dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 00:47:22

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@0 -33.49dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 00:48:14

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@77 -35.88dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 00:50:00

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB75@0 -37.44dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 00:51:12

n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -36.73dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 00:52:32

n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@77 -37.76dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 00:53:48

n77_1_30MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB75@0 -38.06dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN,2025 00:55:01

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@0 -38.04dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN,2025 00:56:21

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@77 -37.64dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN,2025 00:57:37

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB75@0 -38.10dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN,2025 00:58:52

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0 -37.61dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN,2025 01:02:44

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@0 -33.43dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN,2025 01:00:15

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@105 -35.47dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 01:01:32

n77_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB100@0 -37.68dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 01:06:37

n77_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -36.46dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 01:04:05

n77_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@105 -37.30dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 01:05:23

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0 -37.96dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 01:10:31

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@0 -37.48dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 01:07:59