



n78_3_20MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB50@0 -36.95dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:01:52

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB1@0 -36.15dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:03:15

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB1@50 -36.41dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:04:33

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB50@0 -36.15dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:05:51

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB1@0 -36.59dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:08:43

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB1@77 -35.88dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:10:01

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB75@0 -36.53dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:11:19

n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -36.75dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:12:43

n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@77 -36.88dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:14:01

n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB75@0 -36.27dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:15:20

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB1@0 -36.09dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:16:43

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB1@77 -36.67dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:18:02

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB75@0 -36.01dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:19:20

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB100@0 -36.30dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:24:48

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@0 -36.01dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:22:11

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@105 -36.53dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:23:29

n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB100@0 -35.66dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:28:50

n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -36.76dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:26:12

n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@105 -35.66dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:27:31

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB100@0 -36.36dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:32:58

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB1@0 -36.31dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:30:28

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB1@105 -35.52dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:31:41

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB128@0 -36.44dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:38:14

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@0 -36.45dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:35:48

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@132 -36.42dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:37:01

n78_3_50MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB128@0 -35.95dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:41:57

n78_3_50MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -36.89dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:39:32

n78_3_50MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@132 -36.76dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:40:44

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB128@0 -36.42dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:45:41

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB1@0 -36.13dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:43:15

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB1@132 -35.84dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:44:28

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB162@0 -36.57dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:50:57

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@0 -36.22dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:48:25

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@161 -35.78dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:49:44

n78_3_60MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB162@0 -36.26dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:54:41

n78_3_60MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -36.61dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:52:15

n78_3_60MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@161 -36.11dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:53:28

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB162@0 -36.40dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:58:26

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB1@0 -36.42dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:55:59

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB1@161 -36.43dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 22:57:12

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB180@0 -36.87dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:03:37

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@0 -35.79dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:01:11

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@188 -36.14dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:02:24

n78_3_70MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB180@0 -36.40dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:07:22

n78_3_70MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -36.58dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:04:56

n78_3_70MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@188 -36.35dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:06:09

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB180@0 -36.35dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:11:08

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB1@0 -35.91dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:08:41

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB1@188 -36.46dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:09:55

n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@0 -36.63dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:13:52

n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@216 -36.09dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:15:07

n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB216@0 -36.61dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:16:21

n78_3_80MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -36.77dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:17:39

n78_3_80MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@216 -36.52dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:18:53

n78_3_80MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB216@0 -35.24dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:20:06

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB1@0 -36.58dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:21:25

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB1@216 -36.52dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:22:38

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB216@0 -36.77dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 3..JPN.2025 23:23:51

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@0 -36.26dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:48:43

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@244 -36.40dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:49:36

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB243@0 -35.79dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:50:30

n78_3_90MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -36.36dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:51:29

n78_3_90MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@244 -36.53dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:52:22

n78_3_90MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB243@0 -36.39dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:53:16

n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB1@0 -36.34dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:54:15

n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB1@244 -36.62dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 07:55:09

n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB243@0 -36.58dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JFN.2025 07:56:02

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -36.16dBm




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JFN.2025 08:13:59

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@272 -36.34dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JFN.2025 08:14:54

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0 -36.35dBm



ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JFN.2025 08:15:49