



n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JFN.2025 10:34:38

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@37




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JFN.2025 10:35:23

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JFN.2025 10:35:56

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JFN.2025 10:36:38

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB50@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JFN.2025 10:37:15

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@50




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JFN.2025 10:37:53

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB50@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 4_JUN.2025 10:38:26

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 4_JUN.2025 10:39:09

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB75@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 4_JUN.2025 10:39:45

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@77




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 4_JUN.2025 10:40:24

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB75@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 4_JUN.2025 10:40:58

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401A43118E-RF Testee:Kungfumeister Liang
Date: 4_JUN.2025 10:42:17

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JPN.2025 10:41:41

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JPN.2025 10:43:30

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JPN.2025 10:42:56

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JPN.2025 10:44:54

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JPN.2025 10:44:16

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JPN.2025 10:46:16

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@132




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JFN,2025 10:45:41

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JFN,2025 10:47:42

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JFN,2025 10:47:07

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JFN,2025 10:49:04

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@161




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JFN,2025 10:48:29

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JFN,2025 10:50:29

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JUN.2025 10:49:53

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JUN.2025 10:51:51

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@188




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JUN.2025 10:51:16

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JUN.2025 10:52:37

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JUN.2025 10:53:13

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@216




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JUN.2025 10:53:52

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4.JUN.2025 10:54:26

n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4.JUN.2025 10:55:11

n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB243@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4.JUN.2025 10:55:48

n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@244




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4.JUN.2025 10:56:28

n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB243@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4.JUN.2025 10:57:02

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 12.JAN.2025 11:24:44

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB270@0




ProjectNo.:2401A43118E-RF Tester:Kungfaster Liang
Date: 12.JAN.2025 11:25:23

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@272




ProjectNo.:2401A43118E-RF Tester:Kungfaster Liang
Date: 12.JAN.2025 11:26:15

n78_3
n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Tester:Kungfaster Liang
Date: 4.JAN.2025 11:46:02

n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfaster Liang
Date: 4.JAN.2025 11:46:32

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB1@23




ProjectNo.:2401A43118E-RF Tester:Kungfaster Liang
Date: 4.JAN.2025 11:47:08

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB24@0




ProjectNo.:2401A43118E-RF Tester:Kungfaster Liang
Date: 4.JAN.2025 11:47:37

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 4..JFN.2025 12:07:25

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB36@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 4..JFN.2025 12:07:53

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB1@37




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 4..JFN.2025 12:08:26

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB36@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 4..JFN.2025 12:08:53

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 4..JFN.2025 12:21:25

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB50@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeister Liang
Date: 4..JFN.2025 12:21:54

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB1@50




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 4..JPN.2025 12:22:32

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB50@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 4..JPN.2025 12:23:01

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 4..JPN.2025 12:27:10

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 4..JPN.2025 12:27:40

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB1@77




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 4..JPN.2025 12:28:15

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB75@0




ProjectNo.:2401A43118E-RF Tester:Kungfamester Liang
Date: 4..JPN.2025 12:28:45

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 12:33:07

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 12:33:37

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 12:34:13

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB1@105




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 12:33:42

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 12:37:04

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Tester:Kungfumeister Liang
Date: 4..JPN.2025 12:36:33

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JPN.2025 12:38:11

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB1@132




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JPN.2025 12:37:41

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JPN.2025 12:41:35

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JPN.2025 12:41:05

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JPN.2025 12:42:41

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB1@161




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JPN.2025 12:42:11

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JFN.2025 12:47:55

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JFN.2025 12:47:24

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JFN.2025 12:49:16

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB1@188




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JFN.2025 12:48:46

n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JFN.2025 12:57:44

n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2401A43118E-RF Testert:Kungfumeaster Liang
Date: 4..JFN.2025 12:58:15

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB1@216




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JPN.2025 12:58:52

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JPN.2025 12:59:22

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JPN.2025 13:01:18

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB243@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JPN.2025 13:01:50

n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB1@244




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JPN.2025 13:02:26

n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB243@0




ProjectNo.:2401A43118E-RF Testert:Kungfamester Liang
Date: 4..JPN.2025 13:02:57

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 12.JAN.2025 12:06:33

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0



ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 12.JAN.2025 12:37:00

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@272



ProjectNo.:2401A43118E-RF Tester:Kungfumaster Liang
Date: 12.JAN.2025 12:38:12