



n66_40MHz_15kHz_1730MHz_DFT-s-OFDM
QPSK_RB1@0 -38.47dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 15:58:15

n66_40MHz_15kHz_1730MHz_DFT-s-OFDM
QPSK_RB1@215 -37.79dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 15:59:17

n66_40MHz_15kHz_1730MHz_DFT-s-OFDM
QPSK_RB216@0 -38.14dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 16:00:15

n66_40MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -38.13dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 16:01:17

n66_40MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@215 -38.19dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 16:02:16

n66_40MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB216@0 -37.94dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 18.DEC.2024 16:03:14

n66_40MHz_15kHz_1760MHz_DFT-s-OFDM
QPSK_RB1@0 -37.36dBm



ProjectNo.: 2401Z104805E-RF Tester: Rungfumeister, Liang
Date: 18.DEC.2024 16:09:45


n66_40MHz_15kHz_1760MHz_DFT-s-OFDM
QPSK_RB1@215 -38.34dBm



ProjectNo.: 2401Z104805E-RF Tester: Rungfumeister, Liang
Date: 18.DEC.2024 15:10:49


n7

n66_40MHz_15kHz_1760MHz_DFT-s-OFDM
QPSK_RB216@0 -37.89dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfumeister, Liang
Date: 18.DEC.2024 16:11:48

n7_5MHz_15kHz_2502.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.12dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfumeister, Liang
Date: 18.DEC.2024 08:34:13

n7_5MHz_15kHz_2502.5MHz_DFT-s-OFDM
QPSK_RB1@24 -36.16dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfumeister, Liang
Date: 18.DEC.2024 08:34:57

n7_5MHz_15kHz_2502.5MHz_DFT-s-OFDM
QPSK_RB25@0 -37.03dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfumeister, Liang
Date: 18.DEC.2024 08:35:42

n7_5MHz_15kHz_2535MHz_DFT-s-OFDM QPSK_RB1@0
-36.06dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 08:40:00

n7_5MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@24 -36.31dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 08:40:45

n7_5MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB25@0 -36.38dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 08:41:30

n7_5MHz_15kHz_2567.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.90dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 08:47:36

n7_5MHz_15kHz_2567.5MHz_DFT-s-OFDM
QPSK_RB1@24 -37.17dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 08:48:21

n7_5MHz_15kHz_2567.5MHz_DFT-s-OFDM
QPSK_RB25@0 -36.72dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunaster Liang
Date: 18.DEC.2024 08:49:06

n7_10MHz_15kHz_2505MHz_DFT-s-OFDM
QPSK_RB1@0 -36.91dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 08:56:33

n7_10MHz_15kHz_2505MHz_DFT-s-OFDM
QPSK_RB1@51 -36.92dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 08:57:19

n7_10MHz_15kHz_2505MHz_DFT-s-OFDM
QPSK_RB50@0 -37.25dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 08:58:06

n7_10MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@0 -36.59dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 08:59:57

n7_10MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@51 -36.87dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:00:43

n7_10MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB50@0 -36.36dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:01:29

n7_10MHz_15kHz_2565MHz_DFT-s-OFDM
QPSK_RB1@0 -36.11dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:02:54

n7_10MHz_15kHz_2565MHz_DFT-s-OFDM
QPSK_RB1@51 -37.01dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:03:41

n7_10MHz_15kHz_2565MHz_DFT-s-OFDM
QPSK_RB50@0 -36.95dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:04:28

n7_15MHz_15kHz_2507.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.04dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:10:25

n7_15MHz_15kHz_2507.5MHz_DFT-s-OFDM
QPSK_RB1@78 -36.78dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:11:12

n7_15MHz_15kHz_2507.5MHz_DFT-s-OFDM
QPSK_RB75@0 -36.52dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:11:59

n7_15MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@0 -37.02dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:14:03

n7_15MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@78 -37.38dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:14:49

n7_15MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB75@0 -36.74dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:15:36

n7_15MHz_15kHz_2562.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.34dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:17:44

n7_15MHz_15kHz_2562.5MHz_DFT-s-OFDM
QPSK_RB1@78 -37.24dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:18:32

n7_15MHz_15kHz_2562.5MHz_DFT-s-OFDM
QPSK_RB75@0 -36.48dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:19:20

n7_20MHz_15kHz_2510MHz_DFT-s-OFDM
QPSK_RB100@0 -36.50dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:27:04

n7_20MHz_15kHz_2510MHz_DFT-s-OFDM
QPSK_RB1@0 -29.95dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:25:29

n7_20MHz_15kHz_2510MHz_DFT-s-OFDM
QPSK_RB1@105 -31.04dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:26:16

n7_20MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB100@0 -36.26dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:29:33

n7_20MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@0 -36.46dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:27:57

n7_20MHz_15kHz_2535MHz_DFT-s-OFDM
QPSK_RB1@105 -36.35dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 18.DEC.2024 09:28:45

n7_20MHz_15kHz_2560MHz_DFT-s-OFDM
QPSK_RB100@0 -36.35dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 18.DEC.2024 09:32:56


n7_20MHz_15kHz_2560MHz_DFT-s-OFDM
QPSK_RB1@0 -28.95dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 18.DEC.2024 09:31:20


n71

n7_20MHz_15kHz_2560MHz_DFT-s-OFDM
QPSK_RB1@105 -28.47dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 18.DEC.2024 09:32:07

n71_5MHz_15kHz_665.5MHz_DFT-s-OFDM
QPSK_RB1@0 -34.33dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:12:42

n71_5MHz_15kHz_665.5MHz_DFT-s-OFDM
QPSK_RB1@24 -33.95dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:13:03

n71_5MHz_15kHz_665.5MHz_DFT-s-OFDM
QPSK_RB25@0 -34.97dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:13:41

n71_5MHz_15kHz_680.5MHz_DFT-s-OFDM
QPSK_RB1@0 -29.03dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:15:33

n71_5MHz_15kHz_680.5MHz_DFT-s-OFDM
QPSK_RB1@24 -33.92dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:15:54

n71_5MHz_15kHz_680.5MHz_DFT-s-OFDM
QPSK_RB25@0 -34.72dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:16:17

n71_5MHz_15kHz_695.5MHz_DFT-s-OFDM
QPSK_RB1@0 -34.28dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:17:34

n71_5MHz_15kHz_695.5MHz_DFT-s-OFDM
QPSK_RB1@24 -34.58dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:17:55

n71_5MHz_15kHz_695.5MHz_DFT-s-OFDM
QPSK_RB25@0 -33.62dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:18:18

n71_10MHz_15kHz_668MHz_DFT-s-OFDM
QPSK_RB1@0 -31.62dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:19:50

n71_10MHz_15kHz_668MHz_DFT-s-OFDM
QPSK_RB1@51 -33.94dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:20:40

n71_10MHz_15kHz_668MHz_DFT-s-OFDM
QPSK_RB50@0 -34.57dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:21:03

n71_10MHz_15kHz_680.5MHz_DFT-s-OFDM
QPSK_RB1@0 -30.66dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:22:10

n71_10MHz_15kHz_680.5MHz_DFT-s-OFDM
QPSK_RB1@51 -34.82dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:22:34

n71_10MHz_15kHz_680.5MHz_DFT-s-OFDM
QPSK_RB50@0 -34.45dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:23:24

n71_10MHz_15kHz_693MHz_DFT-s-OFDM
QPSK_RB1@0 -33.06dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:24:34

n71_10MHz_15kHz_693MHz_DFT-s-OFDM
QPSK_RB1@51 -31.83dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:24:58

n71_10MHz_15kHz_693MHz_DFT-s-OFDM
QPSK_RB50@0 -34.25dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:25:21

n71_15MHz_15kHz_670.5MHz_DFT-s-OFDM
QPSK_RB1@0 -30.24dBm




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:28:29

n71_15MHz_15kHz_670.5MHz_DFT-s-OFDM
QPSK_RB1@78 -31.99dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:28:53

n71_15MHz_15kHz_670.5MHz_DFT-s-OFDM
QPSK_RB75@0 -24.49dBm



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 17.DEC.2024 19:29:17