



n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -36.40dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 11:07:13

n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@77 -36.27dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 11:08:07

n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB75@0 -36.30dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 11:09:00

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB1@0 -36.38dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 11:10:03

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB1@77 -36.44dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 11:10:57

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB75@0 -35.95dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 11:11:49

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB100@0 -35.25dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:07:42

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@0 -35.41dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:05:54

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@105 -35.61dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:06:47

n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB100@0 -34.68dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:10:46

n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -35.96dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:08:57

n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@105 -35.45dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:09:53

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB100@0 -35.96dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 12:22:54

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB1@0 -35.36dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 12:21:06

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB1@105 -35.20dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 12:22:01

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB128@0 -35.04dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 12:34:55

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@0 -35.12dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 12:33:04

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@132 -35.67dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester Liang
Date: 16.DEC.2024 12:33:58

n78_3_50MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB128@0 -35.76dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:37:53

n78_3_50MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -35.60dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:36:01

n78_3_50MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@132 -35.83dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:36:58

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB128@0 -35.32dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:45:51

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB1@0 -35.48dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:43:56

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB1@132 -36.15dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:44:55

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB162@0 -35.09dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:52:25

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@0 -35.59dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:50:29

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@161 -35.14dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:51:30

n78_3_60MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB162@0 -36.01dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:55:24

n78_3_60MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -35.51dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:53:28

n78_3_60MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@161 -35.45dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 12:54:29

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB162@0 -35.70dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 12:58:19

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB1@0 -35.18dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 12:56:30

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB1@161 -35.51dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 12:57:25

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB180@0 -35.55dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:03:21

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@0 -35.55dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:01:31

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@188 -35.90dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:02:27

n78_3_70MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB180@0 -35.40dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 13:06:16

n78_3_70MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -35.62dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 13:04:24

n78_3_70MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@188 -35.20dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 13:05:20

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB180@0 -35.34dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 13:09:13

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB1@0 -35.82dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 13:07:18

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB1@188 -35.14dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunmeter Liang
Date: 16.DEC.2024 13:08:17

n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@0 -35.79dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:19:20

n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@216 -35.77dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:20:18

n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB216@0 -35.41dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:21:17

n78_3_80MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -35.57dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:22:26

n78_3_80MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@216 -35.75dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:23:25

n78_3_80MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB216@0 -35.20dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:24:24

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB1@0 -35.67dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:25:32

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB1@216 -35.70dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:26:33

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB216@0 -35.39dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:27:33

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@0 -36.22dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:32:17

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@244 -35.20dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:33:18

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB243@0 -35.80dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:34:17

n78_3_90MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -35.89dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:35:25

n78_3_90MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@244 -36.06dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:36:24

n78_3_90MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB243@0 -34.69dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:37:22

n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB1@0 -35.88dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:38:30

n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB1@244 -35.89dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:39:30

n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB243@0 -35.28dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfunester, Liang
Date: 16.DEC.2024 13:40:28

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -35.65dBm




ProjectNo.: 2401Z104805E-RF Tester: Rungfumeater Liang
Date: 16.DEC.2024 13:44:40

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@272 -36.13dBm



ProjectNo.: 2401Z104805E-RF Tester: Rungfumeater Liang
Date: 16.DEC.2024 13:45:40

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0 -35.33dBm



ProjectNo.: 2401Z104805E-RF Tester: Rungfumeater Liang
Date: 16.DEC.2024 13:46:40