



n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@50




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 18:21:58

n77_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB50@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 18:22:45

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 18:23:41

n77_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB75@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 18:24:29

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@77




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 18:25:22

n77_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB75@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 18:26:10

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 18:27:56

n77_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 18:27:07

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 18:29:38

n77_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 18:28:49

n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 18:31:25

n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 18:30:36

n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 18:33:12

n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@132




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 18:32:23

n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 18:34:54

n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 18:34:07

n77_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 18:36:36

n77_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@161




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 18:35:49

n77_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 18:38:25

n77_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 18:37:37

n77_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 18:40:08

n77_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@188




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 18:39:20

n77_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 16.DEC.2024 13:53:07

n77_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 18:41:52

n77_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@216




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 16.DEC.2024 13:54:37

n77_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 18:43:32

n77_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 16.DEC.2024 13:55:54

n77_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB243@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 18:45:17

n77_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@244




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 16.DEC.2024 13:56:52

n77_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB243@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 18:46:58

n77_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Kungfumeister LiJiang
Date: 16.DEC.2024 14:18:07

n77_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB270@0




ProjectNo.:2401Z104805E-RF Tester:Kungfumeister LiJiang
Date: 30.DEC.2024 13:24:05

n77_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@272




ProjectNo.:2401Z104805E-RF Tester:Kungfumeister LiJiang
Date: 16.DEC.2024 13:58:42

n77_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Kungfumeister LiJiang
Date: 7.DEC.2024 19:41:30

n77_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB24@0




ProjectNo.:2401Z104805E-RF Tester:Kungfumeister LiJiang
Date: 7.DEC.2024 19:42:22

n77_3_10MHz_30kHz_3975MHz_DFT-s-OFDM
QPSK_RB1@23




ProjectNo.:2401Z104805E-RF Tester:Kungfumeister LiJiang
Date: 7.DEC.2024 19:43:19

n77_3_10MHz_30kHz_3975MHz_DFT-s-OFDM
QPSK_RB24@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:44:10

n77_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:45:10

n77_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB36@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:46:02

n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM
QPSK_RB1@37




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:47:00

n77_3_15MHz_30kHz_3972.5MHz_DFT-s-OFDM
QPSK_RB36@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:47:52

n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:49:00

n77_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB50@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:49:51

n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM
QPSK_RB1@50




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:50:49

n77_3_20MHz_30kHz_3970MHz_DFT-s-OFDM
QPSK_RB50@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:51:41

n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:52:42

n77_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB75@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:53:35

n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM
QPSK_RB1@77




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:54:33

n77_3_30MHz_30kHz_3965MHz_DFT-s-OFDM
QPSK_RB75@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:55:26

n77_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:57:21

n77_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:56:29

n77_3_40MHz_30kHz_3960MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:59:12

n77_3_40MHz_30kHz_3960MHz_DFT-s-OFDM
QPSK_RB1@105




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 19:58:19

n77_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:01:08

n77_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:00:15

n77_3_50MHz_30kHz_3955MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:03:01

n77_3_50MHz_30kHz_3955MHz_DFT-s-OFDM
QPSK_RB1@132




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:02:07

n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:04:54

n77_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:04:02

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:06:44

n77_3_60MHz_30kHz_3950MHz_DFT-s-OFDM
QPSK_RB1@161




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:05:51

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:08:37

n77_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:07:44

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:10:27

n77_3_70MHz_30kHz_3945MHz_DFT-s-OFDM
QPSK_RB1@188




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:09:34

n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 16.DEC.2024 14:10:09

n77_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 20:12:20

n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB1@216




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 16.DEC.2024 11:23:35

n77_3_80MHz_30kHz_3940MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 20:14:15

n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 16.DEC.2024 11:12:06

n77_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB243@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 20:16:09

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB1@244




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 16.DEC.2024 11:13:04

n77_3_90MHz_30kHz_3935MHz_DFT-s-OFDM
QPSK_RB243@0




ProjectNo.:2401Z104805E-RF Testset:Rungfumeister: L.Jiang
Date: 7.DEC.2024 20:18:07

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Testset:Rungfumeister: L.Jiang
Date: 16.DEC.2024 11:14:02

n77_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0




ProjectNo.:2401Z104805E-RF Testset:Rungfumeister: L.Jiang
Date: 7.DEC.2024 20:20:01

n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB1@272



ProjectNo.:2401Z104805E-RF Testset:Rungfumeister: L.Jiang
Date: 16.DEC.2024 11:24:32


n77_3_100MHz_30kHz_3930MHz_DFT-s-OFDM
QPSK_RB270@0



ProjectNo.:2401Z104805E-RF Testset:Rungfumeister: L.Jiang
Date: 16.DEC.2024 14:25:28


n78_1

n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Testset:Rungfumeister: L.Jiang
Date: 7.DEC.2024 20:29:54

n78_1_10MHz_30kHz_3455MHz_DFT-s-OFDM
QPSK_RB24@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7 DEC.2024 20:30:48

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB1@23




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7 DEC.2024 20:31:47

n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM
QPSK_RB24@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7 DEC.2024 20:32:40

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7 DEC.2024 20:33:42

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0



ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7 DEC.2024 20:34:37

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@37



ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7 DEC.2024 20:35:36