



n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0




ProjectNo.:2401Z104805E-RF Testear:Kungfamester Liang
Date: 7.DEC.2024 20:36:30

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Testear:Kungfamester Liang
Date: 7.DEC.2024 20:37:33

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB50@0




ProjectNo.:2401Z104805E-RF Testear:Kungfamester Liang
Date: 7.DEC.2024 20:38:28

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB1@50




ProjectNo.:2401Z104805E-RF Testear:Kungfamester Liang
Date: 7.DEC.2024 20:39:27

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB50@0




ProjectNo.:2401Z104805E-RF Testear:Kungfamester Liang
Date: 7.DEC.2024 20:40:21

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Testear:Kungfamester Liang
Date: 7.DEC.2024 20:41:30

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM
QPSK_RB75@0




ProjectNo.:2401Z104805E-RF Tester:Kungfamester Liang
Date: 7.DEC.2024 20:42:26

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB1@77




ProjectNo.:2401Z104805E-RF Tester:Kungfamester Liang
Date: 7.DEC.2024 20:43:27

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM
QPSK_RB75@0




ProjectNo.:2401Z104805E-RF Tester:Kungfamester Liang
Date: 7.DEC.2024 20:44:22

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401Z104805E-RF Tester:Kungfamester Liang
Date: 7.DEC.2024 20:46:22

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Kungfamester Liang
Date: 7.DEC.2024 20:45:26

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401Z104805E-RF Tester:Kungfamester Liang
Date: 7.DEC.2024 20:48:19

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 20:47:23

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 20:50:21

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 20:49:24

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 20:52:35

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@132




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 20:51:39

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 20:54:40

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:53:45

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:56:39

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@161




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:55:44

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:58:36

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 20:57:42

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 21:00:34

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@188




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 20:59:40

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 16.DEC.2024 11:27:50

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 21:02:50

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB1@216




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 16.DEC.2024 11:31:00

n78_1_80MHz_30kHz_3510MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 21:05:05

n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 16.DEC.2024 11:31:56

n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB243@0




ProjectNo.:2401Z104805E-RF Tester:Rungfamester Liang
Date: 7.DEC.2024 21:07:24

n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@244




ProjectNo.:2401Z104805E-RF Tester:Rungfamester Liang
Date: 16.DEC.2024 14:33:22

n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB243@0




ProjectNo.:2401Z104805E-RF Tester:Rungfamester Liang
Date: 7.DEC.2024 21:09:38

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfamester Liang
Date: 16.DEC.2024 14:34:20

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB270@0



ProjectNo.:2401Z104805E-RF Tester:Rungfamester Liang
Date: 30.DEC.2024 13:25:24


n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@272



ProjectNo.:2401Z104805E-RF Tester:Rungfamester Liang
Date: 16.DEC.2024 14:35:14


n78_3

n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Mingfamester Liang
Date: 7.DEC.2024 22:19:37

n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB24@0




ProjectNo.:2401Z104805E-RF Tester:Mingfamester Liang
Date: 7.DEC.2024 22:20:46

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB1@23




ProjectNo.:2401Z104805E-RF Tester:Mingfamester Liang
Date: 7.DEC.2024 22:22:02

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB24@0




ProjectNo.:2401Z104805E-RF Tester:Mingfamester Liang
Date: 7.DEC.2024 22:23:11

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Mingfamester Liang
Date: 7.DEC.2024 22:25:51

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB36@0




ProjectNo.:2401Z104805E-RF Tester:Mingfamester Liang
Date: 7.DEC.2024 22:27:00

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB1@37




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 22:28:15

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB36@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 22:29:24

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 22:32:05

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB50@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 22:33:14

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB1@50




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 22:34:30

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB50@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 22:35:40

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Mingfumeister Liang
Date: 7.DEC.2024 22:38:23

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB75@0




ProjectNo.:2401Z104805E-RF Tester:Mingfumeister Liang
Date: 7.DEC.2024 22:39:33

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB1@77




ProjectNo.:2401Z104805E-RF Tester:Mingfumeister Liang
Date: 7.DEC.2024 22:40:50

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB75@0




ProjectNo.:2401Z104805E-RF Tester:Mingfumeister Liang
Date: 7.DEC.2024 22:42:01

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401Z104805E-RF Tester:Mingfumeister Liang
Date: 7.DEC.2024 22:45:54

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Mingfumeister Liang
Date: 7.DEC.2024 22:44:44

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB100@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 22:48:24

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB1@105




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 22:47:12

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 22:52:19

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 22:51:08

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB128@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 22:54:50

n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB1@132




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter Liang
Date: 7.DEC.2024 22:53:37

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 22:58:43

n78_3_60MHz_30kHz_3730MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 22:57:32

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB162@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 23:01:09

n78_3_60MHz_30kHz_3770MHz_DFT-s-OFDM
QPSK_RB1@161




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 22:59:58

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 23:05:02

n78_3_70MHz_30kHz_3735MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Testset:Rungfunmeter: Liang
Date: 7.DEC.2024 23:03:52

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB180@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 23:07:34

n78_3_70MHz_30kHz_3765MHz_DFT-s-OFDM
QPSK_RB1@188




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 23:06:23

n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 16.DEC.2024 14:47:58

n78_3_80MHz_30kHz_3740MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 23:11:26

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB1@216




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 16.DEC.2024 14:48:58

n78_3_80MHz_30kHz_3760MHz_DFT-s-OFDM
QPSK_RB216@0




ProjectNo.:2401Z104805E-RF Tester:Rungfunmeter Liang
Date: 7.DEC.2024 23:13:53

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB1@0




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 16.DEC.2024 14:51:50

n78_3_90MHz_30kHz_3745MHz_DFT-s-OFDM
QPSK_RB243@0




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 7.DEC.2024 23:17:48

n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB1@244




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 16.DEC.2024 14:52:44

n78_3_90MHz_30kHz_3755MHz_DFT-s-OFDM
QPSK_RB243@0




ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 7.DEC.2024 23:20:21

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 16.DEC.2024 14:55:52

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0



ProjectNo.:2401Z104805E-RF Tester:Kungfumaster Liang
Date: 30.DEC.2024 1:27:23

n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM QPSK_RB1@272

