



Please refer to following plots:


Band 2_1.4 MHz_Low_QPSK_RB6#0



Band 2_1.4 MHz_Low_16QAM_RB6#0




Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 28.MAR.2022 17:55:56

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 28.MAR.2022 17:56:20

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 28.MAR.2022 17:56:44

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 28.MAR.2022 17:57:01


Band 2_3 MHz_Low_QPSK_RB15#0




Band 2_3 MHz_Low_16QAM_RB15#0




Band 2_3 MHz_Middle_QPSK_RB15#0




Band 2_3 MHz_Middle_16QAM_RB15#0




Band 2_3 MHz_High_QPSK_RB15#0



Band 2_3 MHz_High_16QAM_RB15#0




Band 2_5 MHz_Low_QPSK_RB25#0




Date: 28.MAR.2022 17:59:49

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 28.MAR.2022 18:00:19

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 28.MAR.2022 18:00:46

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 28.MAR.2022 18:01:12


Band 2_5 MHz_High_QPSK_RB25#0



Band 2_5 MHz_High_16QAM_RB25#0




Band 2_10 MHz_Low_QPSK_RB50#0




Date: 28.MAR.2022 18:02:36

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 28.MAR.2022 18:03:01

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 28.MAR.2022 18:03:34

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 28.MAR.2022 18:03:59

Band 2_10 MHz_High_QPSK_RB50#0




Date: 28.MAR.2022 18:04:32

Band 2_10 MHz_High_16QAM_RB50#0




Date: 28.MAR.2022 18:05:03

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 28.MAR.2022 18:05:45

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 28.MAR.2022 18:06:21

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 28.MAR.2022 18:06:55

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 28.MAR.2022 18:07:31

Band 2_15 MHz_High_QPSK_RB75#0




Date: 28.MAR.2022 18:08:05

Band 2_15 MHz_High_16QAM_RB75#0




Date: 28.MAR.2022 18:08:35


Band 2_20 MHz_Low_QPSK_RB100#0




Band 2_20 MHz_Low_16QAM_RB100#0




Band 2_20 MHz_Middle_QPSK_RB100#0



Band 2_20 MHz_Middle_16QAM_RB100#0




Band 2_20 MHz_High_QPSK_RB100#0




Date: 28.MAR.2022 18:11:57

Band 2_20 MHz_High_16QAM_RB100#0




Date: 28.MAR.2022 18:12:36


Band 4_1.4 MHz_Low_QPSK_RB6#0




Band 4_1.4 MHz_Low_16QAM_RB6#0




Band 4_1.4 MHz_Middle_QPSK_RB6#0



Band 4_1.4 MHz_Middle_16QAM_RB6#0




Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 28.MAR.2022 18:14:20

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 28.MAR.2022 18:14:44

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 28.MAR.2022 18:15:10

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 28.MAR.2022 18:15:30


Band 4_3 MHz_High_QPSK_RB15#0



Band 4_3 MHz_High_16QAM_RB15#0




Band 4_5 MHz_Low_QPSK_RB25#0




Date: 28.MAR.2022 18:17:25

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 28.MAR.2022 18:17:46


Band 4_5 MHz_Middle_QPSK_RB25#0



Band 4_5 MHz_Middle_16QAM_RB25#0




Band 4_5 MHz_High_QPSK_RB25#0




Date: 28.MAR.2022 18:19:15

Band 4_5 MHz_High_16QAM_RB25#0




Date: 28.MAR.2022 18:19:42


Band 4_10 MHz_Low_QPSK_RB50#0



Band 4_10 MHz_Low_16QAM_RB50#0




Band 4_10 MHz_Middle_QPSK_RB50#0




Date: 28.MAR.2022 18:21:15

Band 4_10 MHz_Middle_16QAM_RB50#0




Date: 28.MAR.2022 18:21:44


Band 4_10 MHz_High_QPSK_RB50#0



Band 4_10 MHz_High_16QAM_RB50#0




Band 4_15 MHz_Low_QPSK_RB75#0




Date: 28.MAR.2022 18:23:29

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 28.MAR.2022 18:24:06


Band 4_15 MHz_Middle_QPSK_RB75#0



Band 4_15 MHz_Middle_16QAM_RB75#0




Band 4_15 MHz_High_QPSK_RB75#0




Date: 28.MAR.2022 18:25:52

Band 4_15 MHz_High_16QAM_RB75#0




Date: 28.MAR.2022 18:26:25

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 28.MAR.2022 18:27:12

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 28.MAR.2022 18:27:54

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 28.MAR.2022 18:28:28

Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 28.MAR.2022 18:29:04

Band 4_20 MHz_High_QPSK_RB100#0




Date: 28.MAR.2022 18:29:41

Band 4_20 MHz_High_16QAM_RB100#0




Date: 28.MAR.2022 18:30:20

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 28.MAR.2022 18:30:43

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 28.MAR.2022 18:31:04

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 28.MAR.2022 18:31:21

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 28.MAR.2022 18:31:42

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 28.MAR.2022 18:32:03

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 28.MAR.2022 18:32:23


Band 5_3 MHz_Low_QPSK_RB15#0



Band 5_3 MHz_Low_16QAM_RB15#0




Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 28.MAR.2022 18:33:17

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 28.MAR.2022 18:33:38

Band 5_3 MHz_High_QPSK_RB15#0




Date: 28.MAR.2022 18:33:55

Band 5_3 MHz_High_16QAM_RB15#0




Date: 28.MAR.2022 18:34:16

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 28.MAR.2022 18:34:41

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 28.MAR.2022 18:35:02

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 28.MAR.2022 18:35:23

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 28.MAR.2022 18:35:49

Band 5_5 MHz_High_QPSK_RB25#0




Date: 28.MAR.2022 18:36:19

Band 5_5 MHz_High_16QAM_RB25#0




Date: 28.MAR.2022 18:36:49

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 28.MAR.2022 18:37:20

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 28.MAR.2022 18:37:46

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 28.MAR.2022 18:38:21

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 28.MAR.2022 18:38:56

Band 5_10 MHz_High_QPSK_RB50#0




Date: 28.MAR.2022 18:39:25

Band 5_10 MHz_High_16QAM_RB50#0




Date: 28.MAR.2022 18:39:54


Band 7_5 MHz_Low_QPSK_RB25#0



Band 7_5 MHz_Low_16QAM_RB25#0




Band 7_5 MHz_High_QPSK_RB25#0




Date: 28.MAR.2022 18:41:54

Band 7_5 MHz_High_16QAM_RB25#0




Date: 28.MAR.2022 18:42:18

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 28.MAR.2022 18:42:58

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 28.MAR.2022 18:43:30


Band 7_10 MHz_Middle_QPSK_RB50#0




Band 7_10 MHz_Middle_16QAM_RB50#0




Band 7_10 MHz_High_QPSK_RB50#0




Band 7_10 MHz_High_16QAM_RB50#0




Band 7_15 MHz_Low_QPSK_RB75#0




Band 7_15 MHz_Low_16QAM_RB75#0




Band 7_15 MHz_Middle_QPSK_RB75#0




Band 7_15 MHz_Middle_16QAM_RB75#0




Band 7_15 MHz_High_QPSK_RB75#0




Band 7_15 MHz_High_16QAM_RB75#0



Band 7_20 MHz_Low_QPSK_RB100#0




Band 7_20 MHz_Low_16QAM_RB100#0



Date: 28.MAR.2022 18:51:31

Date: 28.MAR.2022 18:52:04

Band 7_20 MHz_High_QPSK_RB100#0



Band 7_20 MHz_High_16QAM_RB100#0

