



## Band 17\_5 MHz\_Low\_QPSK\_RB25#0




Date: 12.MAR.2022 11:23:13

## Band 17\_5 MHz\_Low\_16QAM\_RB25#0




Date: 12.MAR.2022 11:23:34

## Band 17\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 12.MAR.2022 11:23:52

## Band 17\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 12.MAR.2022 11:24:13

## Band 17\_5 MHz\_High\_QPSK\_RB25#0




Date: 12.MAR.2022 11:24:37

## Band 17\_5 MHz\_High\_16QAM\_RB25#0




Date: 12.MAR.2022 11:24:54


## Band 17\_10 MHz\_Low\_QPSK\_RB50#0



## Band 17\_10 MHz\_Low\_16QAM\_RB50#0




## Band 17\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 12.MAR.2022 11:26:18

## Band 17\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 12.MAR.2022 11:26:40

## Band 17\_10 MHz\_High\_QPSK\_RB50#0




Date: 12.MAR.2022 11:27:08

## Band 17\_10 MHz\_High\_16QAM\_RB50#0




Date: 12.MAR.2022 11:27:27

Band 38\_5 MHz\_Low\_QPSK\_RB25#0




Date: 12.MAR.2022 14:42:51

Band 38\_5 MHz\_Low\_16QAM\_RB25#0




Date: 12.MAR.2022 14:43:05

## Band 38\_5 MHz\_Middle\_QPSK\_RB25#0



Date: 12.MAR.2022 14:43:27

## Band 38\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 12.MAR.2022 14:43:44







## Band 38\_10 MHz\_Low\_QPSK\_RB50#0



## Band 38\_10 MHz\_Low\_16QAM\_RB50#0




## Band 38\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 12.MAR.2022 14:45:28

## Band 38\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 12.MAR.2022 14:45:50

## Band 38\_10 MHz\_High\_QPSK\_RB50#0




Date: 12.MAR.2022 14:46:12

## Band 38\_10 MHz\_High\_16QAM\_RB50#0




Date: 12.MAR.2022 14:46:34

## Band 38\_15 MHz\_Low\_QPSK\_RB75#0




Date: 12.MAR.2022 14:47:00

## Band 38\_15 MHz\_Low\_16QAM\_RB75#0




Date: 12.MAR.2022 14:47:24

## Band 38\_15 MHz\_Middle\_QPSK\_RB75#0




Date: 12.MAR.2022 14:47:48

## Band 38\_15 MHz\_Middle\_16QAM\_RB75#0




Date: 12.MAR.2022 14:48:15

## Band 38\_15 MHz\_High\_QPSK\_RB75#0




Date: 12.MAR.2022 14:48:37

## Band 38\_15 MHz\_High\_16QAM\_RB75#0




Date: 12.MAR.2022 14:49:04

## Band 38\_20 MHz\_Low\_QPSK\_RB100#0



Date: 12.MAR.2022 14:49:27


## Band 38\_20 MHz\_Low\_16QAM\_RB100#0



Date: 12.MAR.2022 14:50:00




## Band 38\_20 MHz\_Middle\_QPSK\_RB100#0




Date: 12.MAR.2022 14:50:27

## Band 38\_20 MHz\_Middle\_16QAM\_RB100#0




Date: 12.MAR.2022 14:50:58

## Band 38\_20 MHz\_High\_QPSK\_RB100#0




Date: 12.MAR.2022 14:51:22

## Band 38\_20 MHz\_High\_16QAM\_RB100#0




Date: 12.MAR.2022 14:51:49

Band 41\_5 MHz\_Low\_QPSK\_RB25#0




Date: 12.MAR.2022 15:38:25

Band 41\_5 MHz\_Low\_16QAM\_RB25#0




Date: 12.MAR.2022 15:38:39

## Band 41\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 12.MAR.2022 15:38:55

## Band 41\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 12.MAR.2022 15:39:12

## Band 41\_5 MHz\_High\_QPSK\_RB25#0




Date: 12.MAR.2022 15:39:30

## Band 41\_5 MHz\_High\_16QAM\_RB25#0




Date: 12.MAR.2022 15:39:48

## Band 41\_10 MHz\_Low\_QPSK\_RB50#0




Date: 12.MAR.2022 15:40:11

## Band 41\_10 MHz\_Low\_16QAM\_RB50#0




Date: 12.MAR.2022 15:40:33

Band 41 10 MHz Middle QPSK RB50#0




Date: 12.MAR.2022 15:40:55

Band 41\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 12.MAR.2022 15:41:17

Band 41\_10 MHz\_High\_QPSK\_RB50#0



Date: 12.MAR.2022 15:41:33

Band 41\_10 MHz\_High\_16QAM\_RB50#0



Date: 12.MAR.2022 15:41:54