



Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:31:53

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:32:21

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:32:57

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:33:19

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:33:52

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:34:14

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:34:51

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:35:14

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:35:46

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:36:15

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:36:47

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:37:13

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:37:43

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:38:09

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:38:44

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:39:13

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:39:49

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:40:08

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:40:38

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:41:04

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:41:30

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:41:53

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:42:22

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:42:44

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:43:15

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:43:37

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:45:01

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:45:24

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:45:58

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:46:24

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:46:58

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:47:24

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:47:57

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:48:20

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.MAR.2022 09:46:37

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 31.MAR.2022 09:47:00

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.MAR.2022 09:47:37

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 31.MAR.2022 09:47:56

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 31.MAR.2022 09:48:28

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 31.MAR.2022 09:48:56

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.MAR.2022 09:50:15

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 31.MAR.2022 09:50:47

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.MAR.2022 09:51:21

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 31.MAR.2022 09:51:43

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 31.MAR.2022 09:52:14

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 31.MAR.2022 09:52:42

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.MAR.2022 09:53:27

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 31.MAR.2022 09:53:49

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.MAR.2022 09:54:26

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 31.MAR.2022 09:54:54

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 31.MAR.2022 09:55:33

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 31.MAR.2022 09:55:58

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.MAR.2022 09:56:43

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 31.MAR.2022 09:57:08

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 31.MAR.2022 09:57:43

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 31.MAR.2022 09:58:09

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 31.MAR.2022 09:58:50

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 31.MAR.2022 09:59:16