



15MHz_Low_QPSK_1@0 -24.41dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:31:19

15MHz_Low_QPSK_75@0 -24.76dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:31:37

15MHz_Middle_QPSK_1@0 -24.73dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:31:55

15MHz_Middle_QPSK_75@0 -24.20dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:32:13

15MHz_High_QPSK_1@0 -24.16dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:32:32

15MHz_High_QPSK_75@0 -24.38dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:32:50

20MHz_Low_QPSK_1@0 -24.45dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:33:49

20MHz_Low_QPSK_100@0 -24.65dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:34:06

20MHz_Middle_QPSK_1@0 -24.76dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:34:23

20MHz_Middle_QPSK_100@0 -24.68dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:34:41

20MHz_High_QPSK_1@0 -24.54dBm



ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:34:59

20MHz_High_QPSK_100@0 -23.99dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:35:16

FCC Part 27


B4, Normal

1.4MHz_Low_QPSK_1@0 -23.97dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:35:48

1.4MHz_Low_QPSK_6@0 -24.65dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:36:07

1.4MHz_Middle_QPSK_1@0 -24.82dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:36:25

1.4MHz_Middle_QPSK_6@0 -24.61dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:36:43

1.4MHz_High_QPSK_1@0 -23.64dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:37:01

1.4MHz_High_QPSK_6@0 -23.96dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:37:19

3MHz_Low_QPSK_1@0 -24.84dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:38:04

3MHz_Low_QPSK_15@0 -24.65dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:38:22

3MHz_Middle_QPSK_1@0 -23.69dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:38:40

3MHz_Middle_QPSK_15@0 -24.46dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:38:58

3MHz_High_QPSK_1@0 -24.29dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:39:16

3MHz_High_QPSK_15@0 -24.97dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:39:35

5MHz_Low_QPSK_1@0 -24.34dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:40:24

5MHz_Low_QPSK_25@0 -24.54dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:40:42

5MHz_Middle_QPSK_1@0 -24.29dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:41:00

5MHz_Middle_QPSK_25@0 -24.82dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:41:19

5MHz_High_QPSK_1@0 -23.15dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:41:37

5MHz_High_QPSK_25@0 -24.77dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:41:55

10MHz_Low_QPSK_1@0 -24.33dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:42:43

10MHz_Low_QPSK_50@0 -23.54dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:43:01

10MHz_Middle_QPSK_1@0 -24.97dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:43:19

10MHz_Middle_QPSK_50@0 -24.68dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:43:38

10MHz_High_QPSK_1@0 -24.11dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:43:57

10MHz_High_QPSK_50@0 -24.48dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:44:15

15MHz_Low_QPSK_1@0 -24.06dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:45:04

15MHz_Low_QPSK_75@0 -24.28dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:45:23

15MHz_Middle_QPSK_1@0 -24.37dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:45:42

15MHz_Middle_QPSK_75@0 -24.72dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:46:01

15MHz_High_QPSK_1@0 -24.84dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:46:20

15MHz_High_QPSK_75@0 -24.88dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 14:46:40

20MHz_Low_QPSK_1@0 -24.41dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:47:38

20MHz_Low_QPSK_100@0 -23.86dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:47:56

20MHz_Middle_QPSK_1@0 -23.96dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:48:15

20MHz_Middle_QPSK_100@0 -24.81dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:48:33

20MHz_High_QPSK_1@0 -24.44dBm



ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:48:51


20MHz_High_QPSK_100@0 -24.55dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 14:49:10

B7, Normal


5MHz_Low_QPSK_1@0 -34.69dBm




5MHz_Low_QPSK_25@0 -34.62dBm




5MHz_Middle_QPSK_1@0 -34.54dBm




5MHz_Middle_QPSK_25@0 -34.41dBm




5MHz_High_QPSK_1@0 -34.08dBm



5MHz_High_QPSK_25@0 -35.03dBm




10MHz_Low_QPSK_1@0 -34.89dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:01:02

10MHz_Low_QPSK_50@0 -34.72dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:01:24

10MHz_Middle_QPSK_1@0 -34.77dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:01:46

10MHz_Middle_QPSK_50@0 -34.65dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:02:08

10MHz_High_QPSK_1@0 -34.41dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:02:30

10MHz_High_QPSK_50@0 -34.43dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:02:52

15MHz_Low_QPSK_1@0 -34.65dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:03:45

15MHz_Low_QPSK_75@0 -34.88dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:04:07

15MHz_Middle_QPSK_1@0 -35.09dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:04:29

15MHz_Middle_QPSK_75@0 -33.92dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:04:51

15MHz_High_QPSK_1@0 -33.99dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:05:13

15MHz_High_QPSK_75@0 -34.48dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:05:35


20MHz_Low_QPSK_1@0 -34.84dBm




20MHz_Low_QPSK_100@0 -34.69dBm




20MHz_Middle_QPSK_1@0 -34.94dBm




20MHz_Middle_QPSK_100@0 -35.00dBm



20MHz_High_QPSK_1@0 -34.79dBm




20MHz_High_QPSK_100@0 -35.26dBm




B12 , Normal


1.4MHz_Low_QPSK_1@0 -24.22dBm




1.4MHz_Low_QPSK_6@0 -25.02dBm




1.4MHz_Middle_QPSK_1@0 -25.24dBm




1.4MHz_Middle_QPSK_6@0 -25.14dBm




1.4MHz_High_QPSK_1@0 -25.29dBm



1.4MHz_High_QPSK_6@0 -25.50dBm




3MHz_Low_QPSK_1@0 -25.64dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:11:18

3MHz_Low_QPSK_15@0 -25.58dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:11:37

3MHz_Middle_QPSK_1@0 -25.65dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:11:56

3MHz_Middle_QPSK_15@0 -25.27dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:12:15

3MHz_High_QPSK_1@0 -25.21dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:12:34

3MHz_High_QPSK_15@0 -24.83dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:12:52

5MHz_Low_QPSK_1@0 -25.46dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:13:42

5MHz_Low_QPSK_25@0 -25.33dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:14:01

5MHz_Middle_QPSK_1@0 -24.87dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:14:21

5MHz_Middle_QPSK_25@0 -25.29dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:14:40

5MHz_High_QPSK_1@0 -24.87dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:15:00

5MHz_High_QPSK_25@0 -25.26dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:15:19

10MHz_Low_QPSK_1@0 -25.14dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:17:52

10MHz_Low_QPSK_50@0 -25.46dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:18:12

10MHz_Middle_QPSK_1@0 -25.28dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:18:31

10MHz_Middle_QPSK_50@0 -24.29dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:18:51

10MHz_High_QPSK_1@0 -25.23dBm



ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:19:12


10MHz_High_QPSK_50@0 -24.76dBm



ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:19:31


B17, Normal

5MHz_Low_QPSK_1@0 -25.43dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:20:12

5MHz_Low_QPSK_25@0 -25.69dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:20:31

5MHz_Middle_QPSK_1@0 -24.32dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:20:49

5MHz_Middle_QPSK_25@0 -24.93dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:21:08

5MHz_High_QPSK_1@0 -25.55dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:21:27

5MHz_High_QPSK_25@0 -24.85dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
 Date: 16.JUL.2024 15:21:46


10MHz_Low_QPSK_1@0 -24.62dBm




10MHz_Low_QPSK_50@0 -24.48dBm




10MHz_Middle_QPSK_1@0 -25.22dBm




10MHz_Middle_QPSK_50@0 -25.57dBm



10MHz_High_QPSK_1@0 -25.20dBm




10MHz_High_QPSK_50@0 -25.63dBm




B38 , Normal

5MHz_Low_QPSK_1@0 -33.99dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:25:57

5MHz_Low_QPSK_25@0 -34.49dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:26:17

5MHz_Middle_QPSK_1@0 -34.38dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:26:39

5MHz_Middle_QPSK_25@0 -33.54dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:27:00

5MHz_High_QPSK_1@0 -33.19dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:27:22

5MHz_High_QPSK_25@0 -33.85dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:27:44

10MHz_Low_QPSK_1@0 -34.91dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:29:24

10MHz_Low_QPSK_50@0 -35.20dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:29:47

10MHz_Middle_QPSK_1@0 -34.22dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:30:08

10MHz_Middle_QPSK_50@0 -34.23dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:30:31

10MHz_High_QPSK_1@0 -34.85dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:30:53

10MHz_High_QPSK_50@0 -35.01dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:31:16


15MHz_Low_QPSK_1@0 -34.07dBm




15MHz_Low_QPSK_75@0 -33.66dBm




15MHz_Middle_QPSK_1@0 -34.60dBm




15MHz_Middle_QPSK_75@0 -35.19dBm




15MHz_High_QPSK_1@0 -35.46dBm




15MHz_High_QPSK_75@0 -34.59dBm




20MHz_Low_QPSK_1@0 -33.82dBm




20MHz_Low_QPSK_100@0 -34.12dBm




20MHz_Middle_QPSK_1@0 -34.53dBm




20MHz_Middle_QPSK_100@0 -34.81dBm



20MHz_High_QPSK_1@0 -34.88dBm




20MHz_High_QPSK_100@0 -34.59dBm




B66 , Normal

1.4MHz_Low_QPSK_1@0 -24.22dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:50:08

1.4MHz_Low_QPSK_6@0 -24.08dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:50:29

1.4MHz_Middle_QPSK_1@0 -24.49dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:50:50

1.4MHz_Middle_QPSK_6@0 -24.54dBm




ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:51:11

1.4MHz_High_QPSK_1@0 -24.10dBm



ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:51:33

1.4MHz_High_QPSK_6@0 -23.84dBm



ProjectNo.:2402V85515E-RF Tester:Karl Liang
Date: 16.JUL.2024 15:51:55