




n78_2_15MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB38@0 13.578MHz




n78_2_15MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB38@0 13.573MHz




n78_2_15MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB38@0 13.527MHz




n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.088MHz




n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB50@0 18.026MHz




n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB50@0 18.037MHz




n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB50@0 18.023MHz




n78_2_20MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB50@0 18.012MHz




n78_2_20MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB51@0 18.110MHz




n78_2_20MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB51@0 18.174MHz




n78_2_20MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB51@0 18.167MHz




n78_2_20MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB51@0 18.181MHz




n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.535MHz




n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB75@0 27.536MHz




n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB75@0 27.739MHz




n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB75@0 27.737MHz



n78_2_30MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB75@0 27.510MHz




n78_2_30MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB78@0 27.854MHz




n78_2_30MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB78@0 27.765MHz




n78_2_30MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB78@0 27.753MHz




n78_2_30MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB78@0 27.757MHz




n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0 37.459MHz



n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB100@0 37.605MHz




n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB100@0 37.289MHz




n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB100@0 37.155MHz




n78_2_40MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB100@0 37.191MHz



n78_2_40MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB106@0 37.667MHz




n78_2_40MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB106@0 37.782MHz




n78_2_40MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB106@0 37.809MHz




n78_2_40MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB106@0 37.761MHz




n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0 46.892MHz




n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB128@0 47.235MHz




n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB128@0 46.898MHz



n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB128@0 46.876MHz



n78_2_50MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB128@0 47.030MHz



n78_2_50MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB133@0 47.426MHz

