



n78_2_90MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB245@0 87.182MHz




n78_2_90MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB245@0 87.174MHz




n78_2_90MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB245@0 87.226MHz



n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB270@0 96.509MHz




n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB270@0 96.962MHz




n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB270@0 96.102MHz




n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB270@0 96.402MHz




n78_2_100MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB270@0 96.108MHz



n78_2_100MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB273@0 97.256MHz



n78_2_100MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB273@0 96.986MHz



n78_2_100MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB273@0 97.279MHz



n78_2_100MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB273@0 96.973MHz

