




n41\_100MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 64  
QAM\_RB270@0 96.198MHz




n41\_100MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM 256  
QAM\_RB270@0 96.155MHz




n41\_100MHz\_30kHz\_2592.99MHz\_CP-OFDM  
QPSK\_RB273@0 97.337MHz




n41\_100MHz\_30kHz\_2592.99MHz\_CP-OFDM 16  
QAM\_RB273@0 97.210MHz



n41\_100MHz\_30kHz\_2592.99MHz\_CP-OFDM 64  
QAM\_RB273@0 97.232MHz




n41\_100MHz\_30kHz\_2592.99MHz\_CP-OFDM 256  
QAM\_RB273@0 97.226MHz




n66


n66\_5MHz\_15kHz\_1745MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB25@0 4.445MHz




n66\_5MHz\_15kHz\_1745MHz\_DFT-s-OFDM  
QPSK\_RB25@0 4.481MHz




n66\_5MHz\_15kHz\_1745MHz\_DFT-s-OFDM 16  
QAM\_RB25@0 4.484MHz




n66\_5MHz\_15kHz\_1745MHz\_DFT-s-OFDM 64  
QAM\_RB25@0 4.489MHz




n66\_5MHz\_15kHz\_1745MHz\_DFT-s-OFDM 256  
QAM\_RB25@0 4.465MHz




n66\_5MHz\_15kHz\_1745MHz\_CP-OFDM QPSK\_RB25@0  
4.468MHz




n66\_5MHz\_15kHz\_1745MHz\_CP-OFDM 16  
QAM\_RB25@0 4.466MHz




n66\_5MHz\_15kHz\_1745MHz\_CP-OFDM 64  
QAM\_RB25@0 4.483MHz




n66\_5MHz\_15kHz\_1745MHz\_CP-OFDM 256  
QAM\_RB25@0 4.466MHz




n66\_10MHz\_15kHz\_1745MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB50@0 9.203MHz




n66\_10MHz\_15kHz\_1745MHz\_DFT-s-OFDM  
QPSK\_RB50@0 9.246MHz



n66\_10MHz\_15kHz\_1745MHz\_DFT-s-OFDM 16  
QAM\_RB50@0 9.215MHz




n66\_10MHz\_15kHz\_1745MHz\_DFT-s-OFDM 64  
QAM\_RB50@0 9.214MHz




n66\_10MHz\_15kHz\_1745MHz\_DFT-s-OFDM 256  
QAM\_RB50@0 9.206MHz




n66\_10MHz\_15kHz\_1745MHz\_CP-OFDM  
QPSK\_RB52@0 9.283MHz




n66\_10MHz\_15kHz\_1745MHz\_CP-OFDM 16  
QAM\_RB52@0 9.299MHz




n66\_10MHz\_15kHz\_1745MHz\_CP-OFDM 64  
QAM\_RB52@0 9.289MHz




n66\_10MHz\_15kHz\_1745MHz\_CP-OFDM 256  
QAM\_RB52@0 9.281MHz




n66\_15MHz\_15kHz\_1745MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB75@0 14MHz




n66\_15MHz\_15kHz\_1745MHz\_DFT-s-OFDM  
QPSK\_RB75@0 13.950MHz




n66\_15MHz\_15kHz\_1745MHz\_DFT-s-OFDM 16  
QAM\_RB75@0 14.043MHz



n66\_15MHz\_15kHz\_1745MHz\_DFT-s-OFDM 64  
QAM\_RB75@0 13.991MHz



n66\_15MHz\_15kHz\_1745MHz\_DFT-s-OFDM 256  
QAM\_RB75@0 13.984MHz



n66\_15MHz\_15kHz\_1745MHz\_CP-OFDM  
QPSK\_RB79@0 14.065MHz

