


n78_2_50MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB133@0 47.402MHz




n78_2_50MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB133@0 47.461MHz



n78_2_50MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB133@0 47.404MHz



n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB162@0 57.683MHz




n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB162@0 57.704MHz



n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB162@0 57.618MHz




n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB162@0 57.910MHz




n78_2_60MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB162@0 57.658MHz



n78_2_60MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB162@0 57.611MHz



n78_2_60MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB162@0 57.712MHz




n78_2_60MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB162@0 57.712MHz




n78_2_60MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB162@0 57.691MHz




n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB180@0 66.961MHz




n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB180@0 66.623MHz



n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB180@0 66.367MHz




n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB180@0 66.570MHz




n78_2_70MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB180@0 66.242MHz




n78_2_70MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB189@0 67.322MHz




n78_2_70MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB189@0 67.347MHz




n78_2_70MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB189@0 67.226MHz




n78_2_70MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB189@0 67.530MHz




n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB216@0 77.210MHz




n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB216@0 76.872MHz




n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB216@0 76.911MHz




n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB216@0 76.950MHz




n78_2_80MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB216@0 76.852MHz




n78_2_80MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB217@0 77.264MHz



n78_2_80MHz_30kHz_3625MHz_CP-OFDM 16
QAM_RB217@0 77.134MHz




n78_2_80MHz_30kHz_3625MHz_CP-OFDM 64
QAM_RB217@0 77.443MHz




n78_2_80MHz_30kHz_3625MHz_CP-OFDM 256
QAM_RB217@0 77.447MHz




n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM $\pi/2$
BPSK_RB243@0 86.543MHz




n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM
QPSK_RB243@0 86.536MHz



n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM 16
QAM_RB243@0 86.456MHz



n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM 64
QAM_RB243@0 86.765MHz



n78_2_90MHz_30kHz_3625MHz_DFT-s-OFDM 256
QAM_RB243@0 86.412MHz



n78_2_90MHz_30kHz_3625MHz_CP-OFDM
QPSK_RB245@0 87.166MHz

