



n38_5MHz_15kHz_2595MHz_DFT-s-OFDM QPSK_RB1@0
-32.89dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaster Liang
Date: 24.FEB.2025 14:12:02

n38_5MHz_15kHz_2595MHz_DFT-s-OFDM QPSK_RB1@24
-36.42dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaster Liang
Date: 24.FEB.2025 11:28:31

n38_5MHz_15kHz_2595MHz_DFT-s-OFDM QPSK_RB25@0
-36.58dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaster Liang
Date: 24.FEB.2025 14:19:11

n38_5MHz_15kHz_2617.5MHz_DFT-s-OFDM QPSK_RB1@0
-37.22dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaster Liang
Date: 24.FEB.2025 11:21:29

n38_5MHz_15kHz_2617.5MHz_DFT-s-OFDM QPSK_RB1@24
-36.76dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaster Liang
Date: 24.FEB.2025 14:22:04

n38_5MHz_15kHz_2617.5MHz_DFT-s-OFDM QPSK_RB25@0
-37.05dBm




ProjectNo.:2501P28739E-RF Tester:Kungfumaster Liang
Date: 24.FEB.2025 11:22:39

n38_10MHz_30kHz_2575MHz_DFT-s-OFDM QPSK_RB1@0
-37.11dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 25.FEB.2025 05:37:14

n38_10MHz_30kHz_2575MHz_DFT-s-OFDM QPSK_RB1@23
-37.39dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 25.FEB.2025 05:38:11

n38_10MHz_30kHz_2575MHz_DFT-s-OFDM QPSK_RB24@0
-37.18dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 25.FEB.2025 05:39:05

n38_10MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB1@0
-37.11dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 25.FEB.2025 05:40:13

n38_10MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB1@23
-37.02dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 25.FEB.2025 05:41:11

n38_10MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB24@0
-37.15dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 25.FEB.2025 05:42:08

n38_10MHz_30kHz_2615MHz_DFT-s-OFDM QPSK_RB1@0
-37.10dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 25.FEB.2025 05:43:12

n38_10MHz_30kHz_2615MHz_DFT-s-OFDM QPSK_RB1@23
-37.26dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 25.FEB.2025 05:44:09

n38_10MHz_30kHz_2615MHz_DFT-s-OFDM QPSK_RB24@0
-36.82dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 25.FEB.2025 05:45:06

n38_15MHz_30kHz_2577.5MHz_DFT-s-OFDM QPSK_RB1@0
-37.53dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 25.FEB.2025 05:48:50

n38_15MHz_30kHz_2577.5MHz_DFT-s-OFDM QPSK_RB1@37
-37.10dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 25.FEB.2025 05:49:50

n38_15MHz_30kHz_2577.5MHz_DFT-s-OFDM QPSK_RB36@0
-36.81dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 25.FEB.2025 05:50:48

n38_15MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB1@0
-37.72dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 05:51:50

n38_15MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB1@37
-37.04dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 05:52:46

n38_15MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB36@0
-37.50dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 05:53:43

n38_15MHz_30kHz_2612.5MHz_DFT-s-OFDM QPSK_RB1@0
-37.71dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 05:54:47

n38_15MHz_30kHz_2612.5MHz_DFT-s-OFDM QPSK_RB1@37
-37.32dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 05:55:47

n38_15MHz_30kHz_2612.5MHz_DFT-s-OFDM QPSK_RB36@0
-37.31dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 05:56:45

n38_20MHz_30kHz_2580MHz_DFT-s-OFDM QPSK_RB1@0
-37.55dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:00:24

n38_20MHz_30kHz_2580MHz_DFT-s-OFDM QPSK_RB1@50
-36.93dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:01:23

n38_20MHz_30kHz_2580MHz_DFT-s-OFDM QPSK_RB50@0
-37.07dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:02:22

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB1@0
-37.19dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:03:27

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB1@50
-37.09dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:04:25

n38_20MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB50@0
-36.96dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:05:23

n38_20MHz_30kHz_2610MHz_DFT-s-OFDM QPSK_RB1@0
-37.63dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:06:25

n38_20MHz_30kHz_2610MHz_DFT-s-OFDM QPSK_RB1@50
-37.03dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:07:28

n38_20MHz_30kHz_2610MHz_DFT-s-OFDM QPSK_RB50@0
-37.27dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:08:26

n38_25MHz_30kHz_2582.5MHz_DFT-s-OFDM QPSK_RB1@0
-37.63dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:11:52

n38_25MHz_30kHz_2582.5MHz_DFT-s-OFDM QPSK_RB1@64
-37.21dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:12:51

n38_25MHz_30kHz_2582.5MHz_DFT-s-OFDM QPSK_RB64@0
-36.87dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:13:49

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB1@0
-37.11dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfamester Liang
Date: 25.FEB.2025 06:14:54

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB1@64
-36.45dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfamester Liang
Date: 25.FEB.2025 06:15:53

n38_25MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB64@0
-37.24dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfamester Liang
Date: 25.FEB.2025 06:16:53

n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM QPSK_RB1@0
-37.78dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfamester Liang
Date: 25.FEB.2025 06:17:59

n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM QPSK_RB1@64
-37.26dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfamester Liang
Date: 25.FEB.2025 06:18:58

n38_25MHz_30kHz_2607.5MHz_DFT-s-OFDM QPSK_RB64@0
-36.17dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfamester Liang
Date: 25.FEB.2025 06:19:58

n38_30MHz_30kHz_2585MHz_DFT-s-OFDM QPSK_RB1@0
-36.67dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 25.FEB.2025 06:23:27

n38_30MHz_30kHz_2585MHz_DFT-s-OFDM QPSK_RB1@77
-36.87dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 25.FEB.2025 06:24:27

n38_30MHz_30kHz_2585MHz_DFT-s-OFDM QPSK_RB75@0
-36.90dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 25.FEB.2025 06:25:26

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB1@0
-37.40dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 25.FEB.2025 06:26:55

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB1@77
-37.39dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 25.FEB.2025 06:27:56

n38_30MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB75@0
-37.34dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 25.FEB.2025 06:28:57


n38_30MHz_30kHz_2605MHz_DFT-s-OFDM QPSK_RB1@0
-36.78dBm




n38_30MHz_30kHz_2605MHz_DFT-s-OFDM QPSK_RB1@77
-37.34dBm




n38_30MHz_30kHz_2605MHz_DFT-s-OFDM QPSK_RB75@0
-36.90dBm




n38_40MHz_30kHz_2590MHz_DFT-s-OFDM QPSK_RB1@0
-36.60dBm




n38_40MHz_30kHz_2590MHz_DFT-s-OFDM QPSK_RB1@105
-37dBm



n38_40MHz_30kHz_2590MHz_DFT-s-OFDM QPSK_RB100@0
-37.22dBm




n38_40MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB1@0
-37.03dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:38:54

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB1@105
-37.36dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:39:55

n38_40MHz_30kHz_2595MHz_DFT-s-OFDM QPSK_RB100@0
-37.16dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:40:55

n38_40MHz_30kHz_2600MHz_DFT-s-OFDM QPSK_RB1@0
-36.79dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:42:00

n38_40MHz_30kHz_2600MHz_DFT-s-OFDM QPSK_RB1@105
-37.33dBm



ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:43:00


n38_40MHz_30kHz_2600MHz_DFT-s-OFDM QPSK_RB100@0
-37.24dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 25.FEB.2025 06:43:59

n41


n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM QPSK_RB1@0
-37.59dBm




n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB1@23 -37.36dBm




n41_10MHz_30kHz_2501.01MHz_DFT-s-OFDM
QPSK_RB24@0 -36.58dBm



n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0
-37.07dBm



n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@23 -37.15dBm



n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB24@0 -37.08dBm

