



n41\_10MHz\_30kHz\_2685MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.35dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang  
Date: 24.FEB.2025 08:23:54

n41\_10MHz\_30kHz\_2685MHz\_DFT-s-OFDM QPSK\_RB1@23  
-36.79dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang  
Date: 24.FEB.2025 08:24:44

n41\_10MHz\_30kHz\_2685MHz\_DFT-s-OFDM QPSK\_RB24@0  
-37.33dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang  
Date: 24.FEB.2025 08:25:32

n41\_15MHz\_30kHz\_2503.5MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.33dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang  
Date: 24.FEB.2025 08:28:46

n41\_15MHz\_30kHz\_2503.5MHz\_DFT-s-OFDM QPSK\_RB1@37  
-37.08dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang  
Date: 24.FEB.2025 08:29:34

n41\_15MHz\_30kHz\_2503.5MHz\_DFT-s-OFDM QPSK\_RB36@0  
-37.31dBm




ProjectNo.: 2501P28739E-RF Tester: Kungfumeister Liang  
Date: 24.FEB.2025 08:30:21

n41\_15MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.07dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:31:17

n41\_15MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB1@37 -37.62dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:32:06

n41\_15MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB36@0 -37.20dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:32:54

n41\_15MHz\_30kHz\_2682.48MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.54dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:33:55

n41\_15MHz\_30kHz\_2682.48MHz\_DFT-s-OFDM  
QPSK\_RB1@37 -37.13dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:34:44

n41\_15MHz\_30kHz\_2682.48MHz\_DFT-s-OFDM  
QPSK\_RB36@0 -37.58dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:35:33

n41\_20MHz\_30kHz\_2506.02MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.51dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:38:43

n41\_20MHz\_30kHz\_2506.02MHz\_DFT-s-OFDM  
QPSK\_RB1@50 -37.44dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:39:32

n41\_20MHz\_30kHz\_2506.02MHz\_DFT-s-OFDM  
QPSK\_RB50@0 -37.59dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:40:21

n41\_20MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.68dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:41:16

n41\_20MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB1@50 -36.92dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:42:04

n41\_20MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB50@0 -37.62dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:42:53

n41\_20MHz\_30kHz\_2679.99MHz\_DFT-s-OFDM QPSK\_RB1@0  
-36.12dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:43:45

n41\_20MHz\_30kHz\_2679.99MHz\_DFT-s-OFDM  
QPSK\_RB1@50 -37.71dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:44:38

n41\_20MHz\_30kHz\_2679.99MHz\_DFT-s-OFDM  
QPSK\_RB50@0 -37.32dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:45:27

n41\_30MHz\_30kHz\_2511MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.72dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:48:36

n41\_30MHz\_30kHz\_2511MHz\_DFT-s-OFDM QPSK\_RB1@77  
-37.48dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:49:26

n41\_30MHz\_30kHz\_2511MHz\_DFT-s-OFDM QPSK\_RB75@0  
-37.52dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:50:16

n41\_30MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.22dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:51:10

n41\_30MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB1@77 -37.76dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:51:59

n41\_30MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB75@0 -37.19dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:52:45

n41\_30MHz\_30kHz\_2674.98MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.16dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:53:45

n41\_30MHz\_30kHz\_2674.98MHz\_DFT-s-OFDM  
QPSK\_RB1@77 -37.82dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:54:35

n41\_30MHz\_30kHz\_2674.98MHz\_DFT-s-OFDM  
QPSK\_RB75@0 -37.32dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:55:26

n41\_40MHz\_30kHz\_2516.01MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.13dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:58:35

n41\_40MHz\_30kHz\_2516.01MHz\_DFT-s-OFDM  
QPSK\_RB1@105 -37.29dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 08:59:25

n41\_40MHz\_30kHz\_2516.01MHz\_DFT-s-OFDM  
QPSK\_RB100@0 -37.28dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 09:00:15

n41\_40MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.73dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 09:01:10

n41\_40MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB1@105 -37.04dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 09:02:00

n41\_40MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB100@0 -37.60dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 09:02:50

n41\_40MHz\_30kHz\_2670MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.39dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 09:03:48

n41\_40MHz\_30kHz\_2670MHz\_DFT-s-OFDM QPSK\_RB1@105  
-36.93dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 09:04:38

n41\_40MHz\_30kHz\_2670MHz\_DFT-s-OFDM QPSK\_RB100@0  
-37.06dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 09:05:25

n41\_50MHz\_30kHz\_2521.02MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.60dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 09:06:50

n41\_50MHz\_30kHz\_2521.02MHz\_DFT-s-OFDM  
QPSK\_RB1@132 -36.41dBm



ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 09:09:43


n41\_50MHz\_30kHz\_2521.02MHz\_DFT-s-OFDM  
QPSK\_RB128@0 -36.22dBm



ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 09:10:35




n41\_50MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.17dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 09:11:31

n41\_50MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB1@132 -37.53dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 09:12:22

n41\_50MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB128@0 -37.56dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 09:13:13

n41\_50MHz\_30kHz\_2664.99MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.54dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 09:15:52

n41\_50MHz\_30kHz\_2664.99MHz\_DFT-s-OFDM  
QPSK\_RB1@132 -37.20dBm



ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 10:34:47


n41\_50MHz\_30kHz\_2664.99MHz\_DFT-s-OFDM  
QPSK\_RB128@0 -37.02dBm



ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 10:35:36




n41\_60MHz\_30kHz\_2526MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.56dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 10:38:55

n41\_60MHz\_30kHz\_2526MHz\_DFT-s-OFDM QPSK\_RB1@161  
-37.29dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 10:39:44

n41\_60MHz\_30kHz\_2526MHz\_DFT-s-OFDM QPSK\_RB162@0  
-37.23dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 10:40:32

n41\_60MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.23dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 10:41:27

n41\_60MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB1@161 -36.82dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 10:42:15

n41\_60MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB162@0 -37.07dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 10:43:03

n41\_60MHz\_30kHz\_2659.98MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.49dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang  
Date: 24.FEB.2025 10:43:57

n41\_60MHz\_30kHz\_2659.98MHz\_DFT-s-OFDM  
QPSK\_RB1@161 -36.93dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang  
Date: 24.FEB.2025 10:44:46

n41\_60MHz\_30kHz\_2659.98MHz\_DFT-s-OFDM  
QPSK\_RB162@0 -37.24dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang  
Date: 24.FEB.2025 10:45:35

n41\_80MHz\_30kHz\_2536.02MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.54dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang  
Date: 24.FEB.2025 10:48:53

n41\_80MHz\_30kHz\_2536.02MHz\_DFT-s-OFDM  
QPSK\_RB1@216 -37.66dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang  
Date: 24.FEB.2025 10:49:40

n41\_80MHz\_30kHz\_2536.02MHz\_DFT-s-OFDM  
QPSK\_RB216@0 -36.51dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang  
Date: 24.FEB.2025 10:50:29

n41\_80MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM QPSK\_RB1@0  
-36.91dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 10:51:22

n41\_80MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB1@216 -37.65dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 10:52:13

n41\_80MHz\_30kHz\_2592.99MHz\_DFT-s-OFDM  
QPSK\_RB216@0 -36.91dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 10:53:02

n41\_80MHz\_30kHz\_2649.99MHz\_DFT-s-OFDM QPSK\_RB1@0  
-37.53dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 10:53:56

n41\_80MHz\_30kHz\_2649.99MHz\_DFT-s-OFDM  
QPSK\_RB1@216 -37.20dBm



ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 10:54:46

n41\_80MHz\_30kHz\_2649.99MHz\_DFT-s-OFDM  
QPSK\_RB216@0 -37.04dBm



ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang  
Date: 24.FEB.2025 10:55:35