




n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-37.50dBm




n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@23
-37.51dBm




n78_1_10MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB24@0
-38.09dBm




n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@0
-37.62dBm




n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB1@23
-37.68dBm



n78_1_10MHz_30kHz_3545MHz_DFT-s-OFDM QPSK_RB24@0
-37.84dBm




n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@0 -38.11dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 15:58:20

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB1@37 -37.61dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 15:59:29

n78_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0 -37.35dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 16:00:37

n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-38.07dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 16:01:46

n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@37
-37.89dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 16:02:51

n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB36@0
-38.11dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 16:03:56

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.87dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 16:05:10

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB1@37 -37.28dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 15:06:15

n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0 -37.88dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 16:07:15

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB1@0
-36.74dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 15:08:31

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB1@50
-37.53dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 16:09:35

n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM QPSK_RB50@0
-37.94dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 15:10:40

n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-38.34dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 20.FEB.2025 16:11:53

n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@50
-37.92dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 20.FEB.2025 16:12:58

n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB50@0
-37.44dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 20.FEB.2025 16:14:02

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB1@0
-37.96dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 20.FEB.2025 16:15:15

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB1@50
-38.26dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 20.FEB.2025 16:16:20

n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM QPSK_RB50@0
-37.99dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeester Liang
Date: 20.FEB.2025 16:17:25

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB1@0
-37.88dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 16:18:36

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB1@77
-37.94dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 15:19:41

n78_1_30MHz_30kHz_3465MHz_DFT-s-OFDM QPSK_RB75@0
-37.89dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 16:20:46

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-37.80dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 15:21:55

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@77
-37.63dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 16:23:00

n78_1_30MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB75@0
-38.17dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 15:24:05

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB1@0
-38.03dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 16:25:14

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB1@77
-37.75dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 20.FEB.2025 15:26:19

n78_1_30MHz_30kHz_3535MHz_DFT-s-OFDM QPSK_RB75@0
-37.40dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:36:14

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM QPSK_RB1@0
-37.49dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:37:16

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB1@105 -36.95dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:38:09

n78_1_40MHz_30kHz_3470MHz_DFT-s-OFDM
QPSK_RB100@0 -38.26dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:39:03

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-38.29dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:40:08

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@105 -38.06dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:41:02

n78_1_40MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB100@0 -37.97dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:41:56

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM QPSK_RB1@0
-37.84dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:43:01

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB1@105 -37.77dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:43:55

n78_1_40MHz_30kHz_3530MHz_DFT-s-OFDM
QPSK_RB100@0 -37.96dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:44:48

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM QPSK_RB1@0
-37.15dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:45:51

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB1@132 -37.50dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:46:45

n78_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0 -38.14dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:47:38

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-37.40dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:48:37

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@132 -38.07dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:49:31

n78_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB128@0 -37.39dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:50:25

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM QPSK_RB1@0
-38.02dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:51:53

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB1@132 -37.67dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:52:47

n78_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0 -37.11dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:53:41

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM QPSK_RB1@0
-38.27dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:54:43

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB1@161 -37.43dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:55:37

n78_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0 -37.81dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:56:32

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-37.99dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:57:31

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@161 -37.77dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:58:25

n78_1_60MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB162@0 -38dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 02:59:15

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM QPSK_RB1@0
-37.77dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 03:00:18

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB1@161 -37.99dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 03:01:12

n78_1_60MHz_30kHz_3520MHz_DFT-s-OFDM
QPSK_RB162@0 -37.81dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 03:02:06

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM QPSK_RB1@0
-37.96dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 21.FEB.2025 03:03:05

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB1@188 -37.98dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 21.FEB.2025 03:04:04

n78_1_70MHz_30kHz_3485MHz_DFT-s-OFDM
QPSK_RB180@0 -37dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 21.FEB.2025 03:04:58

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM QPSK_RB1@0
-38.19dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 21.FEB.2025 03:05:57

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@188 -37.48dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 21.FEB.2025 03:06:51

n78_1_70MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB180@0 -37.39dBm




ProjectNo.: 2501P28739E-RF Testert:Kungfumeaster Liang
Date: 21.FEB.2025 03:07:46

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM QPSK_RB1@0
-37.65dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 03:08:46

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB1@188 -37.74dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 03:09:40

n78_1_70MHz_30kHz_3515MHz_DFT-s-OFDM
QPSK_RB180@0 -37.64dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 03:10:35

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM QPSK_RB1@0
-38.10dBm




ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 03:11:38

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB1@216 -37.05dBm



ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 03:12:32

n78_1_80MHz_30kHz_3490MHz_DFT-s-OFDM
QPSK_RB216@0 -38.10dBm



ProjectNo.: 2501P28739E-RF Tester: Kingfumeaster Liang
Date: 21.FEB.2025 03:13:27