## SUNVALLEYTEK INTERNATIONAL, INC. 46724 Lakeview Blvd, Fremont, CA 94538-6529

Federal Communications Commission 7345 Oakland Mills Road Columbia MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request for a Change in Identification per Section §2.933 of the FCC Rules

Reference: 2AFDGVA-BH007

## To The Commission:

This change in identification request applies for a new FCC ID as established in 47 CFR 2.933(b) for a currently approved device. This application by **SUNVALLEYTEK INTERNATIONAL, INC.** will establish a new FCC ID under **SUNVALLEYTEK INTERNATIONAL, INC.** grantee code for the purpose of marketing.

The original grant to **Tendo International Co.,Ltd.** with FCC ID: 2AMK5EB2011 will remain in effect.

An authorization letter by **Tendo International Co.,Ltd.** is attached.

Per 2.933(b)

- 1.) The original identification is: FCC ID: 2AMK5EB2011
- 2.) The original granted date is: 07/11/2017
- 3.) The equipment is electrically identical.
- 4.) The original test results are applicable and representative of this changed device
- 5.) External photographs incl. FCC ID label location info are included in this application.

The following files are electronically submitted as attachments:

- Cover Letter

- External Photos

- ID Lable and Location Info

Sincerely

Name: Lion Liao

Title: General Manager

Date: 07-27-2017