



B12, Normal

1.4MHz_Low_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:17:33

1.4MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:17:19

1.4MHz_Low_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:18:15

1.4MHz_Low_QPSK_6@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:18:29

1.4MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:19:10

1.4MHz_Middle_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:19:23

1.4MHz_Middle_QPSK_6@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:20:19

1.4MHz_Middle_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:20:05

1.4MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:21:01

1.4MHz_High_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:21:15

1.4MHz_High_QPSK_6@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:22:11

1.4MHz_High_QPSK_6@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:21:57

3MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:30:30

3MHz_Low_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:30:44

3MHz_Low_QPSK_15@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:31:39

3MHz_Low_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:31:25

3MHz_Middle_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:32:34

3MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:32:20

3MHz_Middle_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:33:17

3MHz_Middle_QPSK_15@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:33:31

3MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:34:13

3MHz_High_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:34:27

3MHz_High_QPSK_15@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:35:08

3MHz_High_QPSK_15@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:35:22

5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:36:30

5MHz_Low_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:36:44

5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:37:26

5MHz_Low_QPSK_25@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:37:40

5MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:38:22

5MHz_Middle_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:38:36

5MHz_Middle_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:39:18

5MHz_Middle_QPSK_25@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:39:32

5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:40:14

5MHz_High_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:40:28

5MHz_High_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:41:09

5MHz_High_QPSK_25@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:41:23

10MHz_Low_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:42:48

10MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:42:34

10MHz_Low_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:43:30

10MHz_Low_QPSK_50@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:43:44

10MHz_Middle_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:44:40

10MHz_Middle_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:44:26

10MHz_Middle_QPSK_50@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:45:22

10MHz_Middle_QPSK_50@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:45:36

10MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:46:18

10MHz_High_QPSK_1@0(1GHz~8.16GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:46:32

10MHz_High_QPSK_50@0(1GHz~8.16GHz)



ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:47:29


10MHz_High_QPSK_50@0(30MHz~1GHz)



ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:47:15


B13 , Normal

5MHz_Low_QPSK_1@0(1GHz~8.87GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:49:18

5MHz_Low_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:49:04

5MHz_Low_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 6.FEB.2025 20:44:18

5MHz_Low_QPSK_1@0(793MHz~806MHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 6.FEB.2025 20:44:24

5MHz_Low_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 6.FEB.2025 20:44:29

5MHz_Low_QPSK_25@0(1GHz~8.87GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:50:53

5MHz_Low_QPSK_25@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:50:39

5MHz_Low_QPSK_25@0(763MHz~775MHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 6.FEB.2025 20:55:45

5MHz_Low_QPSK_25@0(793MHz~806MHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 6.FEB.2025 20:44:46

5MHz_Low_QPSK_25@0(1559MHz~1610MHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 6.FEB.2025 20:55:51

5MHz_High_QPSK_1@0(1GHz~8.87GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:52:28

5MHz_High_QPSK_1@0(30MHz~1GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:52:14

5MHz_High_QPSK_1@0(763MHz~775MHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 6.FEB.2025 20:45:02

5MHz_High_QPSK_1@0(793MHz~806MHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 6.FEB.2025 20:45:08

5MHz_High_QPSK_1@0(1559MHz~1610MHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 6.FEB.2025 20:56:01

5MHz_High_QPSK_25@0(1GHz~8.87GHz)




ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:54:02

5MHz_High_QPSK_25@0(30MHz~1GHz)



ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 9.DEC.2024 01:53:48

5MHz_High_QPSK_25@0(763MHz~775MHz)



ProjectNo.:2401Z104941E-RF Tester:Usain Ou
Date: 6.FEB.2025 20:45:24