





Restrict Band NVNT ac20 5260MHz Ant1 Peak



Restrict Band NVNT ac20 5260MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5320MHz Ant1 Peak



Restrict Band NVNT ac20 5320MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5270MHz Ant1 Peak



Restrict Band NVNT ac40 5270MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5310MHz Ant1 Peak



Restrict Band NVNT ac40 5310MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz Ant1 Peak



Restrict Band NVNT ac80 5290MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz Ant1 Peak



Restrict Band NVNT ac80 5290MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



F.4 Restrict Band

Condition	Mode	Frequency (MHz)	Antenna	Spur Freq (MHz)	Power (dBm)	Gain (dBi)	Duty Factor (dB)	E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	a	5500	Ant1	5460	-49.54	5.68	-	51.37	Peak	68.2	Pass
NVNT	a	5500	Ant1	5460	-57.69	5.68	0.13	43.35	Average	54	Pass
NVNT	a	5500	Ant1	5468.6	-42.04	5.68	-	58.87	Peak	68.2	Pass
NVNT	a	5500	Ant1	5470	-56.12	5.68	0.13	44.92	Average	54	Pass
NVNT	a	5500	Ant1	5470	-46.09	5.68	-	54.82	Peak	68.2	Pass
NVNT	a	5500	Ant1	5470	-56.12	5.68	0.13	44.92	Average	54	Pass
NVNT	a	5700	Ant1	5725	-34.36	5.68	-	66.55	Peak	68.2	Pass
NVNT	a	5700	Ant1	5725	-53.53	5.68	0.19	47.57	Average	54	Pass
NVNT	a	5700	Ant1	5725	-34.36	5.68	-	66.55	Peak	68.2	Pass
NVNT	a	5700	Ant1	5726.8	-53.35	5.68	0.19	47.75	Average	54	Pass
NVNT	a	5700	Ant1	5735	-50.12	5.68	-	50.79	Peak	68.2	Pass
NVNT	a	5700	Ant1	5735	-57.56	5.68	0.19	43.54	Average	54	Pass
NVNT	n20	5500	Ant1	5460	-48.72	5.68	-	52.19	Peak	68.2	Pass
NVNT	n20	5500	Ant1	5460	-57.91	5.68	0.22	43.22	Average	54	Pass
NVNT	n20	5500	Ant1	5470	-42.82	5.68	-	58.09	Peak	68.2	Pass
NVNT	n20	5500	Ant1	5470	-55.13	5.68	0.22	46	Average	54	Pass
NVNT	n20	5500	Ant1	5470	-42.82	5.68	-	58.09	Peak	68.2	Pass
NVNT	n20	5500	Ant1	5470	-55.13	5.68	0.22	46	Average	54	Pass
NVNT	n20	5700	Ant1	5725	-38.41	5.68	-	62.5	Peak	68.2	Pass
NVNT	n20	5700	Ant1	5725	-49.48	5.68	0.23	51.66	Average	54	Pass
NVNT	n20	5700	Ant1	5725.8	-34.87	5.68	-	66.04	Peak	68.2	Pass
NVNT	n20	5700	Ant1	5725	-49.48	5.68	0.23	51.66	Average	54	Pass
NVNT	n20	5700	Ant1	5735	-48.8	5.68	-	52.11	Peak	68.2	Pass
NVNT	n20	5700	Ant1	5735	-56.86	5.68	0.23	44.28	Average	54	Pass
NVNT	n40	5510	Ant1	5460	-49.1	5.68	-	51.81	Peak	68.2	Pass
NVNT	n40	5510	Ant1	5460	-57.13	5.68	0.44	44.22	Average	54	Pass
NVNT	n40	5510	Ant1	5470	-35.48	5.68	-	65.43	Peak	68.2	Pass
NVNT	n40	5510	Ant1	5469.8	-52.68	5.68	0.44	48.67	Average	54	Pass
NVNT	n40	5510	Ant1	5470	-35.48	5.68	-	65.43	Peak	68.2	Pass
NVNT	n40	5510	Ant1	5470	-53.69	5.68	0.44	47.66	Average	54	Pass
NVNT	n40	5670	Ant1	5725	-48.74	5.68	-	52.17	Peak	68.2	Pass
NVNT	n40	5670	Ant1	5725	-57.48	5.68	0.44	43.87	Average	54	Pass
NVNT	n40	5670	Ant1	5731	-47.52	5.68	-	53.39	Peak	68.2	Pass
NVNT	n40	5670	Ant1	5730	-57.12	5.68	0.44	44.23	Average	54	Pass
NVNT	n40	5670	Ant1	5735	-51.49	5.68	-	49.42	Peak	68.2	Pass
NVNT	n40	5670	Ant1	5735	-57.85	5.68	0.44	43.5	Average	54	Pass
NVNT	ac20	5500	Ant1	5460	-49.79	5.68	-	51.12	Peak	68.2	Pass
NVNT	ac20	5500	Ant1	5460	-57.67	5.68	0.22	43.46	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac20	5500	Ant1	5469.6	-39.39	5.68	-	61.52	Peak	68.2	Pass
NVNT	ac20	5500	Ant1	5469.6	-55.41	5.68	0.22	45.72	Average	54	Pass
NVNT	ac20	5500	Ant1	5470	-41.74	5.68	-	59.17	Peak	68.2	Pass
NVNT	ac20	5500	Ant1	5470	-55.67	5.68	0.22	45.46	Average	54	Pass
NVNT	ac20	5700	Ant1	5725	-38.85	5.68	-	62.06	Peak	68.2	Pass
NVNT	ac20	5700	Ant1	5725	-51.93	5.68	0.22	49.2	Average	54	Pass
NVNT	ac20	5700	Ant1	5725.6	-35.85	5.68	-	65.06	Peak	68.2	Pass
NVNT	ac20	5700	Ant1	5725.4	-51.93	5.68	0.22	49.2	Average	54	Pass
NVNT	ac20	5700	Ant1	5735	-45.4	5.68	-	55.51	Peak	68.2	Pass
NVNT	ac20	5700	Ant1	5735	-56.72	5.68	0.22	44.41	Average	54	Pass
NVNT	ac40	5510	Ant1	5460	-49.48	5.68	-	51.43	Peak	68.2	Pass
NVNT	ac40	5510	Ant1	5460	-57.01	5.68	0.43	44.33	Average	54	Pass
NVNT	ac40	5510	Ant1	5468.6	-40.66	5.68	-	60.25	Peak	68.2	Pass
NVNT	ac40	5510	Ant1	5469.6	-53.46	5.68	0.43	47.88	Average	54	Pass
NVNT	ac40	5510	Ant1	5470	-42.38	5.68	-	58.53	Peak	68.2	Pass
NVNT	ac40	5510	Ant1	5470	-53.49	5.68	0.43	47.85	Average	54	Pass
NVNT	ac40	5670	Ant1	5725	-47.98	5.68	-	52.93	Peak	68.2	Pass
NVNT	ac40	5670	Ant1	5725	-57.63	5.68	0.44	43.72	Average	54	Pass
NVNT	ac40	5670	Ant1	5726.4	-47.79	5.68	-	53.12	Peak	68.2	Pass
NVNT	ac40	5670	Ant1	5725.8	-57.05	5.68	0.44	44.3	Average	54	Pass
NVNT	ac40	5670	Ant1	5735	-49.33	5.68	-	51.58	Peak	68.2	Pass
NVNT	ac40	5670	Ant1	5735	-57.48	5.68	0.44	43.87	Average	54	Pass
NVNT	ac80	5530	Ant1	5460	-44.95	5.68	-	55.96	Peak	68.2	Pass
NVNT	ac80	5530	Ant1	5460	-54.86	5.68	0.83	46.88	Average	54	Pass
NVNT	ac80	5530	Ant1	5467.2	-39.78	5.68	-	61.13	Peak	68.2	Pass
NVNT	ac80	5530	Ant1	5470	-52.99	5.68	0.83	48.75	Average	54	Pass
NVNT	ac80	5530	Ant1	5470	-41.66	5.68	-	59.25	Peak	68.2	Pass
NVNT	ac80	5530	Ant1	5470	-52.99	5.68	0.83	48.75	Average	54	Pass
NVNT	ac80	5610	Ant1	5725	-50.97	5.68	-	49.94	Peak	68.2	Pass
NVNT	ac80	5610	Ant1	5725	-58.45	5.68	0.83	43.29	Average	54	Pass
NVNT	ac80	5610	Ant1	5729.465	-47.73	5.68	-	53.18	Peak	68.2	Pass
NVNT	ac80	5610	Ant1	5729.465	-57.27	5.68	0.83	44.47	Average	54	Pass
NVNT	ac80	5610	Ant1	5735	-49.05	5.68	-	51.86	Peak	68.2	Pass
NVNT	ac80	5610	Ant1	5735	-58.73	5.68	0.83	43.01	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Test Graphs

Restrict Band NVNT a 5500MHz Ant1 Peak



Restrict Band NVNT a 5500MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT a 5700MHz Ant1 Peak



Restrict Band NVNT a 5700MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5500MHz Ant1 Peak



Restrict Band NVNT n20 5500MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5700MHz Ant1 Peak



Restrict Band NVNT n20 5700MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5510MHz Ant1 Peak



Restrict Band NVNT n40 5510MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5670MHz Ant1 Peak



Restrict Band NVNT n40 5670MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5500MHz Ant1 Peak



Restrict Band NVNT ac20 5500MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5700MHz Ant1 Peak



Restrict Band NVNT ac20 5700MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5510MHz Ant1 Peak



Restrict Band NVNT ac40 5510MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5670MHz Ant1 Peak



Restrict Band NVNT ac40 5670MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5530MHz Ant1 Peak



Restrict Band NVNT ac80 5530MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5610MHz Ant1 Peak



Restrict Band NVNT ac80 5610MHz Ant1 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Condition	Mode	Frequency (MHz)	Antenna	Spur Freq (MHz)	Power (dBm)	Gain (dBi)	Duty Factor (dB)	E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	a	5500	Ant2	5460	-49.33	2	-	47.9	Peak	68.2	Pass
NVNT	a	5500	Ant2	5460	-56.91	2	0.19	40.51	Average	54	Pass
NVNT	a	5500	Ant2	5467.4	-45.33	2	-	51.9	Peak	68.2	Pass
NVNT	a	5500	Ant2	5468	-55.96	2	0.19	41.46	Average	54	Pass
NVNT	a	5500	Ant2	5470	-45.9	2	-	51.33	Peak	68.2	Pass
NVNT	a	5500	Ant2	5470	-57.37	2	0.19	40.05	Average	54	Pass
NVNT	a	5700	Ant2	5725	-38	2	-	59.23	Peak	68.2	Pass
NVNT	a	5700	Ant2	5725	-53.86	2	0.19	43.56	Average	54	Pass
NVNT	a	5700	Ant2	5725.8	-34	2	-	63.23	Peak	68.2	Pass
NVNT	a	5700	Ant2	5727	-53.48	2	0.19	43.94	Average	54	Pass
NVNT	a	5700	Ant2	5735	-49.07	2	-	48.16	Peak	68.2	Pass
NVNT	a	5700	Ant2	5735	-57.24	2	0.19	40.18	Average	54	Pass
NVNT	n20	5500	Ant2	5460	-50.57	2	-	46.66	Peak	68.2	Pass
NVNT	n20	5500	Ant2	5460	-57.99	2	0.23	39.47	Average	54	Pass
NVNT	n20	5500	Ant2	5468.2	-43.27	2	-	53.96	Peak	68.2	Pass
NVNT	n20	5500	Ant2	5469.6	-54.73	2	0.23	42.73	Average	54	Pass
NVNT	n20	5500	Ant2	5470	-44.21	2	-	53.02	Peak	68.2	Pass
NVNT	n20	5500	Ant2	5470	-55.97	2	0.23	41.49	Average	54	Pass
NVNT	n20	5700	Ant2	5725	-39.09	2	-	58.14	Peak	68.2	Pass
NVNT	n20	5700	Ant2	5725	-51.8	2	0.23	45.66	Average	54	Pass
NVNT	n20	5700	Ant2	5726.2	-34.45	2	-	62.78	Peak	68.2	Pass
NVNT	n20	5700	Ant2	5725.6	-51.78	2	0.23	45.68	Average	54	Pass
NVNT	n20	5700	Ant2	5735	-47.51	2	-	49.72	Peak	68.2	Pass
NVNT	n20	5700	Ant2	5735	-57.75	2	0.23	39.71	Average	54	Pass
NVNT	n40	5510	Ant2	5460	-46.48	2	-	50.75	Peak	68.2	Pass
NVNT	n40	5510	Ant2	5460	-57.22	2	0.40	40.41	Average	54	Pass
NVNT	n40	5510	Ant2	5469.2	-40.28	2	-	56.95	Peak	68.2	Pass
NVNT	n40	5510	Ant2	5470	-52.9	2	0.40	44.73	Average	54	Pass
NVNT	n40	5510	Ant2	5470	-44.14	2	-	53.09	Peak	68.2	Pass
NVNT	n40	5510	Ant2	5470	-52.9	2	0.40	44.73	Average	54	Pass
NVNT	n40	5670	Ant2	5725	-48.14	2	-	49.09	Peak	68.2	Pass
NVNT	n40	5670	Ant2	5725	-58	2	0.44	39.67	Average	54	Pass
NVNT	n40	5670	Ant2	5729.8	-47.97	2	-	49.26	Peak	68.2	Pass
NVNT	n40	5670	Ant2	5728.4	-56.95	2	0.44	40.72	Average	54	Pass
NVNT	n40	5670	Ant2	5735	-49.91	2	-	47.32	Peak	68.2	Pass
NVNT	n40	5670	Ant2	5735	-57.77	2	0.44	39.9	Average	54	Pass
NVNT	ac20	5500	Ant2	5460	-50.45	2	-	46.78	Peak	68.2	Pass
NVNT	ac20	5500	Ant2	5460	-57.89	2	0.22	39.56	Average	54	Pass
NVNT	ac20	5500	Ant2	5469.4	-43.64	2	-	53.59	Peak	68.2	Pass
NVNT	ac20	5500	Ant2	5469.2	-55.72	2	0.22	41.73	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac20	5500	Ant2	5470	-45.3	2	-	51.93	Peak	68.2	Pass
NVNT	ac20	5500	Ant2	5470	-55.91	2	0.22	41.54	Average	54	Pass
NVNT	ac20	5700	Ant2	5725	-39.67	2	-	57.56	Peak	68.2	Pass
NVNT	ac20	5700	Ant2	5725	-52.65	2	0.22	44.8	Average	54	Pass
NVNT	ac20	5700	Ant2	5726.4	-36.28	2	-	60.95	Peak	68.2	Pass
NVNT	ac20	5700	Ant2	5725.2	-51.02	2	0.22	46.43	Average	54	Pass
NVNT	ac20	5700	Ant2	5735	-49.93	2	-	47.3	Peak	68.2	Pass
NVNT	ac20	5700	Ant2	5735	-56.62	2	0.22	40.83	Average	54	Pass
NVNT	ac40	5510	Ant2	5460	-50.1	2	-	47.13	Peak	68.2	Pass
NVNT	ac40	5510	Ant2	5460	-57.28	2	0.43	40.38	Average	54	Pass
NVNT	ac40	5510	Ant2	5467	-37.56	2	-	59.67	Peak	68.2	Pass
NVNT	ac40	5510	Ant2	5469.8	-53.15	2	0.43	44.51	Average	54	Pass
NVNT	ac40	5510	Ant2	5470	-46.13	2	-	51.1	Peak	68.2	Pass
NVNT	ac40	5510	Ant2	5470	-53.72	2	0.43	43.94	Average	54	Pass
NVNT	ac40	5670	Ant2	5725	-48.64	2	-	48.59	Peak	68.2	Pass
NVNT	ac40	5670	Ant2	5725	-57.29	2	0.43	40.37	Average	54	Pass
NVNT	ac40	5670	Ant2	5733.8	-47.08	2	-	50.15	Peak	68.2	Pass
NVNT	ac40	5670	Ant2	5727.2	-56.95	2	0.43	40.71	Average	54	Pass
NVNT	ac40	5670	Ant2	5735	-50.54	2	-	46.69	Peak	68.2	Pass
NVNT	ac40	5670	Ant2	5735	-58.07	2	0.43	39.59	Average	54	Pass
NVNT	ac80	5530	Ant2	5460	-47.56	2	-	49.67	Peak	68.2	Pass
NVNT	ac80	5530	Ant2	5460	-54.73	2	0.83	43.33	Average	54	Pass
NVNT	ac80	5530	Ant2	5469.6	-40.52	2	-	56.71	Peak	68.2	Pass
NVNT	ac80	5530	Ant2	5467.8	-52.82	2	0.83	45.24	Average	54	Pass
NVNT	ac80	5530	Ant2	5470	-41.58	2	-	55.65	Peak	68.2	Pass
NVNT	ac80	5530	Ant2	5470	-54.48	2	0.83	43.58	Average	54	Pass
NVNT	ac80	5610	Ant2	5725	-49.71	2	-	47.52	Peak	68.2	Pass
NVNT	ac80	5610	Ant2	5725	-58.26	2	0.83	39.8	Average	54	Pass
NVNT	ac80	5610	Ant2	5729.26	-47.65	2	-	49.58	Peak	68.2	Pass
NVNT	ac80	5610	Ant2	5728.44	-57.27	2	0.83	40.79	Average	54	Pass
NVNT	ac80	5610	Ant2	5735	-50.43	2	-	46.8	Peak	68.2	Pass
NVNT	ac80	5610	Ant2	5735	-57.75	2	0.83	40.31	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Test Graphs

Restrict Band NVNT a 5500MHz Ant2 Peak



Restrict Band NVNT a 5500MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT a 5700MHz Ant2 Peak



Restrict Band NVNT a 5700MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5500MHz Ant2 Peak



Restrict Band NVNT n20 5500MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5700MHz Ant2 Peak



Restrict Band NVNT n20 5700MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5510MHz Ant2 Peak



Restrict Band NVNT n40 5510MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5670MHz Ant2 Peak



Restrict Band NVNT n40 5670MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5500MHz Ant2 Peak



Restrict Band NVNT ac20 5500MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5700MHz Ant2 Peak



Restrict Band NVNT ac20 5700MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5510MHz Ant2 Peak



Restrict Band NVNT ac40 5510MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5670MHz Ant2 Peak



Restrict Band NVNT ac40 5670MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5530MHz Ant2 Peak



Restrict Band NVNT ac80 5530MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5610MHz Ant2 Peak



Restrict Band NVNT ac80 5610MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



MIMO

Condition	Mode	Frequency (MHz)	Spur Freq (MHz)	Ant1 Power (dBm)	Ant2 Power (dBm)	Gain (dBi)	E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	n20	5500	5460	-48.72	-50.57	7.04	55.73	Peak	68.2	Pass
NVNT	n20	5500	5460	-57.91	-57.99	7.04	47.33	Average	54	Pass
NVNT	n20	5500	5470	-42.82	-43.27	7.04	62.24	Peak	68.2	Pass
NVNT	n20	5500	5470	-55.13	-54.73	7.04	50.35	Average	54	Pass
NVNT	n20	5500	5470	-42.82	-44.21	7.04	61.82	Peak	68.2	Pass
NVNT	n20	5500	5470	-55.13	-55.97	7.04	49.75	Average	54	Pass
NVNT	n20	5700	5725	-38.41	-39.09	7.04	66.54	Peak	68.2	Pass
NVNT	n20	5700	5725	-51.48	-53.8	7.04	52.79	Average	54	Pass
NVNT	n20	5700	5725.8	-37.87	-37.45	7.04	67.63	Peak	68.2	Pass
NVNT	n20	5700	5725	-51.48	-53.78	7.04	52.80	Average	54	Pass
NVNT	n20	5700	5735	-48.8	-47.51	7.04	57.17	Peak	68.2	Pass
NVNT	n20	5700	5735	-56.86	-57.75	7.04	48.00	Average	54	Pass
NVNT	n40	5510	5460	-49.1	-46.48	7.04	57.68	Peak	68.2	Pass
NVNT	n40	5510	5460	-57.13	-57.22	7.04	48.11	Average	54	Pass
NVNT	n40	5510	5470	-36.48	-41.28	7.04	67.03	Peak	68.2	Pass
NVNT	n40	5510	5469.8	-53.68	-53.9	7.04	52.49	Average	54	Pass
NVNT	n40	5510	5470	-36.48	-45.14	7.04	66.34	Peak	68.2	Pass
NVNT	n40	5510	5470	-53.69	-52.9	7.04	52.00	Average	54	Pass
NVNT	n40	5670	5725	-48.74	-48.14	7.04	56.85	Peak	68.2	Pass
NVNT	n40	5670	5725	-57.48	-58	7.04	47.55	Average	54	Pass
NVNT	n40	5670	5731	-47.52	-47.97	7.04	57.54	Peak	68.2	Pass
NVNT	n40	5670	5730	-57.12	-56.95	7.04	48.25	Average	54	Pass
NVNT	n40	5670	5735	-51.49	-49.91	7.04	54.65	Peak	68.2	Pass
NVNT	n40	5670	5735	-57.85	-57.77	7.04	47.47	Average	54	Pass
NVNT	ac20	5500	5460	-49.79	-50.45	7.04	55.17	Peak	68.2	Pass
NVNT	ac20	5500	5460	-57.67	-57.89	7.04	47.50	Average	54	Pass
NVNT	ac20	5500	5469.6	-39.39	-43.64	7.04	64.27	Peak	68.2	Pass
NVNT	ac20	5500	5469.6	-55.41	-55.72	7.04	49.72	Average	54	Pass
NVNT	ac20	5500	5470	-41.74	-45.3	7.04	62.12	Peak	68.2	Pass
NVNT	ac20	5500	5470	-55.67	-55.91	7.04	49.49	Average	54	Pass
NVNT	ac20	5700	5725	-38.85	-39.67	7.04	66.04	Peak	68.2	Pass
NVNT	ac20	5700	5725	-51.93	-52.65	7.04	53.01	Average	54	Pass
NVNT	ac20	5700	5725.6	-35.85	-38.28	7.04	67.22	Peak	68.2	Pass
NVNT	ac20	5700	5725.4	-52.93	-52.02	7.04	52.83	Average	54	Pass
NVNT	ac20	5700	5735	-45.4	-49.93	7.04	58.18	Peak	68.2	Pass
NVNT	ac20	5700	5735	-56.72	-56.62	7.04	48.61	Average	54	Pass
NVNT	ac40	5510	5460	-49.48	-50.1	7.04	55.50	Peak	68.2	Pass
NVNT	ac40	5510	5460	-57.01	-57.28	7.04	48.14	Average	54	Pass
NVNT	ac40	5510	5468.6	-40.66	-37.56	7.04	66.44	Peak	68.2	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac40	5510	5469.6	-53.46	-53.15	7.04	51.98	Average	54	Pass
NVNT	ac40	5510	5470	-42.38	-46.13	7.04	61.42	Peak	68.2	Pass
NVNT	ac40	5510	5470	-53.49	-53.72	7.04	51.68	Average	54	Pass
NVNT	ac40	5670	5725	-47.98	-48.64	7.04	56.98	Peak	68.2	Pass
NVNT	ac40	5670	5725	-57.63	-57.29	7.04	47.82	Average	54	Pass
NVNT	ac40	5670	5726.4	-47.79	-47.08	7.04	57.86	Peak	68.2	Pass
NVNT	ac40	5670	5725.8	-57.05	-56.95	7.04	48.28	Average	54	Pass
NVNT	ac40	5670	5735	-49.33	-50.54	7.04	55.39	Peak	68.2	Pass
NVNT	ac40	5670	5735	-57.48	-58.07	7.04	47.52	Average	54	Pass
NVNT	ac80	5530	5460	-44.95	-47.56	7.04	59.22	Peak	68.2	Pass
NVNT	ac80	5530	5460	-54.86	-54.73	7.04	50.49	Average	54	Pass
NVNT	ac80	5530	5467.2	-39.78	-40.52	7.04	65.15	Peak	68.2	Pass
NVNT	ac80	5530	5470	-52.99	-52.82	7.04	52.38	Average	54	Pass
NVNT	ac80	5530	5470	-41.66	-41.58	7.04	63.66	Peak	68.2	Pass
NVNT	ac80	5530	5470	-52.99	-54.48	7.04	51.61	Average	54	Pass
NVNT	ac80	5610	5725	-50.97	-49.71	7.04	54.99	Peak	68.2	Pass
NVNT	ac80	5610	5725	-58.45	-58.26	7.04	46.93	Average	54	Pass
NVNT	ac80	5610	5729.465	-47.73	-47.65	7.04	57.59	Peak	68.2	Pass
NVNT	ac80	5610	5729.465	-57.27	-57.27	7.04	48.01	Average	54	Pass
NVNT	ac80	5610	5735	-49.05	-50.43	7.04	55.59	Peak	68.2	Pass
NVNT	ac80	5610	5735	-58.73	-57.75	7.04	47.07	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



F.5 Frequency Stability

Condition	Mode	Frequency (MHz)	Antenna	Measured Frequency (MHz)	Frequency Error (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
NVNT	a	5500	Ant1	5499.98	-20000	-3.64	25	Pass
NVNT	a	5580	Ant1	5579.98	-20000	-3.58	25	Pass
NVNT	a	5700	Ant1	5699.98	-20000	-3.51	25	Pass
NVNT	n20	5500	Ant1	5500	0	0	25	Pass
NVNT	n20	5580	Ant1	5580	0	0	25	Pass
NVNT	n20	5700	Ant1	5699.98	-20000	-3.51	25	Pass
NVNT	n40	5510	Ant1	5510	0	0	25	Pass
NVNT	n40	5550	Ant1	5550	0	0	25	Pass
NVNT	n40	5670	Ant1	5669.96	-40000	-7.05	25	Pass
NVNT	ac20	5500	Ant1	5499.98	-20000	-3.64	25	Pass
NVNT	ac20	5580	Ant1	5579.98	-20000	-3.58	25	Pass
NVNT	ac20	5700	Ant1	5699.98	-20000	-3.51	25	Pass
NVNT	ac40	5510	Ant1	5509.96	-40000	-7.26	25	Pass
NVNT	ac40	5550	Ant1	5550	0	0	25	Pass
NVNT	ac40	5670	Ant1	5670	0	0	25	Pass
NVNT	ac80	5530	Ant1	5530	0	0	25	Pass
NVNT	ac80	5610	Ant1	5610	0	0	25	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Test Graphs

Freq. Stability NVNT a 5500MHz Ant1



Freq. Stability NVNT a 5580MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT a 5700MHz Ant1



Freq. Stability NVNT n20 5500MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT n20 5580MHz Ant1



Freq. Stability NVNT n20 5700MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT n40 5510MHz Ant1



Freq. Stability NVNT n40 5550MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT n40 5670MHz Ant1



Freq. Stability NVNT ac20 5500MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac20 5580MHz Ant1



Freq. Stability NVNT ac20 5700MHz Ant1



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity