

 Mercedes-Benz

A910 900 21 00 / 001

Seriennummer: XD10100030

HW: A910 901 02 00 ZGS 001
SW-GW: A910 902 04 00
SW-IO: A910 902 13 00

Stand: 19/20
Stand: 19/24/00
Stand: 19/24/00

CE

QXX

Diagnose Kennung: 0x000001

MAC: XD10100001

FCC ID: 2ASIZ-00001

XTRONIC GMBH Herrenberger Str. 56, 71034 Böblingen

MN: MBAC EM V001

19Txxx

IC: 24737-00001



 Mercedes-Benz

A910 900 22 00 / 001

Seriennummer: XD10100103

Date-Matrix-
Code



HW:	A910 901 03 00	ZGS 001	Stand:19/20
SW-GW:	A910 902 04 00		Stand:19/24/00
SW-IO:	A910 902 13 00		Stand:19/24/00
SW-PC:	A910 902 12 00		Stand:19/24/00
Diagnose Kennung:	0x000001		MN: MBAC BM V001
MAC:	XD10100002		19Txxx
FCC ID:	2ASIZ-00001		IC: 24737-00001
XTRONIC GMBH Herrenberger Str. 56, 71034 Böblingen			

QXX

