




9. SETUP PHOTOS



RF CONDUCTED MEASUREMENT SETUP



RF RADIATED MEASUREMENT SETUP, 9 kHz - 30 MHz



RF RADIATED MEASUREMENT SETUP, 30 - 1000 MHz



END OF REPORT