



RC-TGU Label specification



1

TGU - 5GWIFI6(GLOBAL) DEVELON
 PN : 300611-02665

IMEI :
 ICCID :
 WIFI MAC :

Removing this terminal may cause significant damage to the equipment. Contact service representative for assistance.

MLNR0WG524A0001

5G 6G

CE FC

41.5

84

TGU - 5GWIFI6(GLOBAL) - Station DEVELON
 PN : 300611-02665

IMEI :
 ICCID :
 WIFI MAC :

Removing this terminal may cause significant damage to the equipment. Contact service representative for assistance.

MLNR0WG524A0001

5G 6G

CE FC

41.5

84

2

Product Name : RC-TGU
 Model No. : RC-TGU (300611-02665)
 Input : 12/24V = 1.22/0.61A
 Manufacturer : DASAN NETWORKS, Inc.
 Country of Origin : KOREA

26.5

83

Product Name : RC-TGU
 Model No. : RC-TGU (300611-02665)
 Input : 12/24V = 1.22/0.61A
 Manufacturer : DASAN NETWORKS, Inc.
 Country of Origin : KOREA

26.5

83

3

FC

PMN: RC-TGU Model: RC-TGU (300611-02665)
 FCCID: 2AXDMTGU5GWIF6
 IC: 26419-TGU5GWIF6

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:
 (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

16.5

83

FC

PMN: RC-TGU Model: RC-TGU (300611-02665)
 FCCID: 2AXDMTGU5GWIF6
 IC: 26419-TGU5GWIF6

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:
 (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

16.5

83

* The label content can be changed depending on the customer's request.

PMN: RC-TGU Model: RC-TGU (300611-02665)
 FCCID: 2AXDMTGU5GWIF6
 IC: 26419-TGU5GWIF6

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:
 (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.