







Frequency Stability NVNT_ANT1_802_11ac(VHT20)_5180




Frequency Stability NVNT_ANT2_802_11ac(VHT20)_5180




Frequency Stability NVNT_ANT1_802_11ac(VHT20)_5200




Frequency Stability NVNT_ANT2_802_11ac(VHT20)_5200




Frequency Stability NVNT_ANT1_802_11ac(VHT20)_5240




Frequency Stability NVNT_ANT2_802_11ac(VHT20)_5240




Frequency Stability NVNT_ANT1_802_11ax(HE20)_5180




Frequency Stability NVNT_ANT2_802_11ax(HE20)_5180




Frequency Stability NVNT_ANT1_802_11ax(HE20)_5200




Frequency Stability NVNT_ANT2_802_11ax(HE20)_5200





Frequency Stability NVNT_ANT1_802_11ax(HE20)_5240




Frequency Stability NVNT_ANT2_802_11ax(HE20)_5240









Frequency Stability NVNT_ANT1_802_11ac(VHT40)_5190




Frequency Stability NVNT_ANT2_802_11ac(VHT40)_5190




Frequency Stability NVNT_ANT1_802_11ac(VHT40)_5230




Frequency Stability NVNT_ANT2_802_11ac(VHT40)_5230




Frequency Stability NVNT_ANT1_802_11ax(HE40)_5190




Frequency Stability NVNT_ANT2_802_11ax(HE40)_5190




Frequency Stability NVNT_ANT1_802_11ax(HE40)_5230




Frequency Stability NVNT_ANT2_802_11ax(HE40)_5230




Frequency Stability NVNT_ANT1_802_11ac(VHT80)_5210



Frequency Stability NVNT_ANT2_802_11ac(VHT80)_5210



Frequency Stability NVNT_ANT1_802_11ax(HE80)_5210



Frequency Stability NVNT_ANT2_802_11ax(HE80)_5210

