





Restrict Band NVNT ac40 5310MHz Ant2 Peak



Restrict Band NVNT ac40 5310MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz Ant2 Peak



Restrict Band NVNT ac80 5290MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz Ant2 Peak



Restrict Band NVNT ac80 5290MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax20 5260MHz Ant2 Peak



Restrict Band NVNT ax20 5260MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax20 5320MHz Ant2 Peak



Restrict Band NVNT ax20 5320MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5270MHz Ant2 Peak



Restrict Band NVNT ax40 5270MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5310MHz Ant2 Peak



Restrict Band NVNT ax40 5310MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax80 5290MHz Ant2 Peak



Restrict Band NVNT ax80 5290MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax80 5290MHz Ant2 Peak



Restrict Band NVNT ax80 5290MHz Ant2 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Condition	Mode	Frequency (MHz)	Antenna	Spur Freq (MHz)	Power (dBm)	Gain (dBi)	Duty Factor (dB)	E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	a	5260	Ant3	4500	-51.36	3.59	-	47.46	Peak	68.2	Pass
NVNT	a	5260	Ant3	4500	-59.4	3.59	0.24	39.66	Average	54	Pass
NVNT	a	5260	Ant3	4611.54	-46.6	3.59	-	52.22	Peak	68.2	Pass
NVNT	a	5260	Ant3	4787.82	-56.05	3.59	0.24	43.01	Average	54	Pass
NVNT	a	5260	Ant3	5150	-48.56	3.59	-	50.26	Peak	68.2	Pass
NVNT	a	5260	Ant3	5150	-56.65	3.59	0.24	42.41	Average	54	Pass
NVNT	a	5320	Ant3	5350	-43.4	3.59	-	55.42	Peak	68.2	Pass
NVNT	a	5320	Ant3	5350	-54.58	3.59	0.24	44.48	Average	54	Pass
NVNT	a	5320	Ant3	5350.2	-40	3.59	-	58.82	Peak	68.2	Pass
NVNT	a	5320	Ant3	5352.6	-54.36	3.59	0.24	44.70	Average	54	Pass
NVNT	a	5320	Ant3	5460	-51.59	3.59	-	47.23	Peak	68.2	Pass
NVNT	a	5320	Ant3	5460	-58.07	3.59	0.24	40.99	Average	54	Pass
NVNT	n20	5260	Ant3	4500	-49.77	3.59	-	49.05	Peak	68.2	Pass
NVNT	n20	5260	Ant3	4500	-59.57	3.59	0.28	39.53	Average	54	Pass
NVNT	n20	5260	Ant3	5047.56	-46.49	3.59	-	52.33	Peak	68.2	Pass
NVNT	n20	5260	Ant3	4773	-56.14	3.59	0.28	42.96	Average	54	Pass
NVNT	n20	5260	Ant3	5150	-49.85	3.59	-	48.97	Peak	68.2	Pass
NVNT	n20	5260	Ant3	5150	-57.24	3.59	0.28	41.86	Average	54	Pass
NVNT	n20	5320	Ant3	5350	-45.2	3.59	-	53.62	Peak	68.2	Pass
NVNT	n20	5320	Ant3	5350	-54.08	3.59	0.28	45.02	Average	54	Pass
NVNT	n20	5320	Ant3	5351.8	-38.88	3.59	-	59.94	Peak	68.2	Pass
NVNT	n20	5320	Ant3	5350.4	-52.79	3.59	0.28	46.31	Average	54	Pass
NVNT	n20	5320	Ant3	5460	-49.14	3.59	-	49.68	Peak	68.2	Pass
NVNT	n20	5320	Ant3	5460	-58.23	3.59	0.28	40.87	Average	54	Pass
NVNT	n40	5270	Ant3	4500	-51.05	3.59	-	47.77	Peak	68.2	Pass
NVNT	n40	5270	Ant3	4500	-59.61	3.59	0.12	39.33	Average	54	Pass
NVNT	n40	5270	Ant3	4805.37	-45.97	3.59	-	52.85	Peak	68.2	Pass
NVNT	n40	5270	Ant3	4806.99	-54.7	3.59	0.12	44.24	Average	54	Pass
NVNT	n40	5270	Ant3	5150	-49.11	3.59	-	49.71	Peak	68.2	Pass
NVNT	n40	5270	Ant3	5150	-57.01	3.59	0.12	41.93	Average	54	Pass
NVNT	n40	5310	Ant3	5350	-41.52	3.59	-	57.30	Peak	68.2	Pass
NVNT	n40	5310	Ant3	5350	-52.88	3.59	0.12	46.06	Average	54	Pass
NVNT	n40	5310	Ant3	5351.2	-36.79	3.59	-	62.03	Peak	68.2	Pass
NVNT	n40	5310	Ant3	5351	-52.44	3.59	0.12	46.50	Average	54	Pass
NVNT	n40	5310	Ant3	5460	-50.38	3.59	-	48.44	Peak	68.2	Pass
NVNT	n40	5310	Ant3	5460	-57.43	3.59	0.12	41.51	Average	54	Pass
NVNT	ac20	5260	Ant3	4500	-51.33	3.59	-	47.49	Peak	68.2	Pass
NVNT	ac20	5260	Ant3	4500	-59.5	3.59	0.28	39.60	Average	54	Pass





NVNT	ac20	5260	Ant3	4786.26	-46.95	3.59	-	51.87	Peak	68.2	Pass
NVNT	ac20	5260	Ant3	4772.22	-56.39	3.59	0.28	42.71	Average	54	Pass
NVNT	ac20	5260	Ant3	5150	-48.55	3.59	-	50.27	Peak	68.2	Pass
NVNT	ac20	5260	Ant3	5150	-57	3.59	0.28	42.10	Average	54	Pass
NVNT	ac20	5320	Ant3	5350	-40.44	3.59	-	58.38	Peak	68.2	Pass
NVNT	ac20	5320	Ant3	5350	-53.35	3.59	0.28	45.75	Average	54	Pass
NVNT	ac20	5320	Ant3	5352	-33.56	3.59	-	65.26	Peak	68.2	Pass
NVNT	ac20	5320	Ant3	5350.6	-52.32	3.59	0.28	46.78	Average	54	Pass
NVNT	ac20	5320	Ant3	5460	-50.26	3.59	-	48.56	Peak	68.2	Pass
NVNT	ac20	5320	Ant3	5460	-58.02	3.59	0.28	41.08	Average	54	Pass
NVNT	ac40	5270	Ant3	4500	-50	3.59	-	48.82	Peak	68.2	Pass
NVNT	ac40	5270	Ant3	4500	-59.17	3.59	0.12	39.77	Average	54	Pass
NVNT	ac40	5270	Ant3	4807.8	-44.56	3.59	-	54.26	Peak	68.2	Pass
NVNT	ac40	5270	Ant3	4806.99	-54.06	3.59	0.12	44.88	Average	54	Pass
NVNT	ac40	5270	Ant3	5150	-48.58	3.59	-	50.24	Peak	68.2	Pass
NVNT	ac40	5270	Ant3	5150	-57.01	3.59	0.12	41.93	Average	54	Pass
NVNT	ac40	5310	Ant3	5350	-38.49	3.59	-	60.33	Peak	68.2	Pass
NVNT	ac40	5310	Ant3	5350	-52.34	3.59	0.12	46.60	Average	54	Pass
NVNT	ac40	5310	Ant3	5460	-51.09	3.59	-	47.73	Peak	68.2	Pass
NVNT	ac40	5310	Ant3	5460	-57.75	3.59	0.12	41.19	Average	54	Pass
NVNT	ac40	5310	Ant3	5350	-38.49	3.59	-	60.33	Peak	68.2	Pass
NVNT	ac40	5310	Ant3	5350	-52.34	3.59	0.12	46.60	Average	54	Pass
NVNT	ac80	5290	Ant3	4500	-51.17	3.59	-	47.65	Peak	68.2	Pass
NVNT	ac80	5290	Ant3	4500	-58.8	3.59	0.25	40.27	Average	54	Pass
NVNT	ac80	5290	Ant3	5035.92	-46.31	3.59	-	52.51	Peak	68.2	Pass
NVNT	ac80	5290	Ant3	5054.19	-56.69	3.59	0.25	42.38	Average	54	Pass
NVNT	ac80	5290	Ant3	5150	-49	3.59	-	49.82	Peak	68.2	Pass
NVNT	ac80	5290	Ant3	5150	-57.08	3.59	0.25	41.99	Average	54	Pass
NVNT	ac80	5290	Ant3	5350	-42.03	3.59	-	56.79	Peak	68.2	Pass
NVNT	ac80	5290	Ant3	5350	-53.43	3.59	0.25	45.64	Average	54	Pass
NVNT	ac80	5290	Ant3	5363.25	-40.53	3.59	-	58.29	Peak	68.2	Pass
NVNT	ac80	5290	Ant3	5351.25	-52.8	3.59	0.25	46.27	Average	54	Pass
NVNT	ac80	5290	Ant3	5460	-47.33	3.59	-	51.49	Peak	68.2	Pass
NVNT	ac80	5290	Ant3	5460	-57.63	3.59	0.25	41.44	Average	54	Pass
NVNT	ax20	5260	Ant3	4500	-51.18	3.59	-	47.64	Peak	68.2	Pass
NVNT	ax20	5260	Ant3	4500	-59.38	3.59	0.28	39.72	Average	54	Pass
NVNT	ax20	5260	Ant3	4666.92	-46.74	3.59	-	52.08	Peak	68.2	Pass
NVNT	ax20	5260	Ant3	4787.82	-56.51	3.59	0.28	42.59	Average	54	Pass
NVNT	ax20	5260	Ant3	5150	-48.59	3.59	-	50.23	Peak	68.2	Pass
NVNT	ax20	5260	Ant3	5150	-56.56	3.59	0.28	42.54	Average	54	Pass
NVNT	ax20	5320	Ant3	5350	-36.53	3.59	-	62.29	Peak	68.2	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




NVNT	ax20	5320	Ant3	5350	-51.86	3.59	0.28	47.24	Average	54	Pass
NVNT	ax20	5320	Ant3	5350.2	-35.71	3.59	-	63.11	Peak	68.2	Pass
NVNT	ax20	5320	Ant3	5350.2	-51.72	3.59	0.28	47.38	Average	54	Pass
NVNT	ax20	5320	Ant3	5460	-50.25	3.59	-	48.57	Peak	68.2	Pass
NVNT	ax20	5320	Ant3	5460	-57.85	3.59	0.28	41.25	Average	54	Pass
NVNT	ax40	5270	Ant3	4500	-51.72	3.59	-	47.10	Peak	68.2	Pass
NVNT	ax40	5270	Ant3	4500	-59.09	3.59	0.12	39.85	Average	54	Pass
NVNT	ax40	5270	Ant3	4807.8	-45.12	3.59	-	53.70	Peak	68.2	Pass
NVNT	ax40	5270	Ant3	4806.99	-54.39	3.59	0.12	44.55	Average	54	Pass
NVNT	ax40	5270	Ant3	5150	-48.55	3.59	-	50.27	Peak	68.2	Pass
NVNT	ax40	5270	Ant3	5150	-57.29	3.59	0.12	41.65	Average	54	Pass
NVNT	ax40	5310	Ant3	5350	-39.85	3.59	-	58.97	Peak	68.2	Pass
NVNT	ax40	5310	Ant3	5350	-52.41	3.59	0.12	46.53	Average	54	Pass
NVNT	ax40	5310	Ant3	5350.8	-36.78	3.59	-	62.04	Peak	68.2	Pass
NVNT	ax40	5310	Ant3	5350.2	-52.4	3.59	0.12	46.54	Average	54	Pass
NVNT	ax40	5310	Ant3	5460	-50.72	3.59	-	48.10	Peak	68.2	Pass
NVNT	ax40	5310	Ant3	5460	-57.85	3.59	0.12	41.09	Average	54	Pass
NVNT	ax80	5290	Ant3	5350	-44.06	3.59	-	54.76	Peak	68.2	Pass
NVNT	ax80	5290	Ant3	5350	-52.88	3.59	0.25	46.19	Average	54	Pass
NVNT	ax80	5290	Ant3	5350.5	-42.98	3.59	-	55.84	Peak	68.2	Pass
NVNT	ax80	5290	Ant3	5350	-52.88	3.59	0.25	46.19	Average	54	Pass
NVNT	ax80	5290	Ant3	5460	-49.37	3.59	-	49.45	Peak	68.2	Pass
NVNT	ax80	5290	Ant3	5460	-57.73	3.59	0.25	41.34	Average	54	Pass
NVNT	ax80	5290	Ant3	4500	-51.61	3.59	-	47.21	Peak	68.2	Pass
NVNT	ax80	5290	Ant3	4500	-58.7	3.59	0.25	40.37	Average	54	Pass
NVNT	ax80	5290	Ant3	5129.01	-45.62	3.59	-	53.20	Peak	68.2	Pass
NVNT	ax80	5290	Ant3	5119.44	-56.61	3.59	0.25	42.46	Average	54	Pass
NVNT	ax80	5290	Ant3	5150	-48.72	3.59	-	50.10	Peak	68.2	Pass
NVNT	ax80	5290	Ant3	5150	-57.15	3.59	0.25	41.92	Average	54	Pass






Test Graphs

Restrict Band NVNT a 5260MHz Ant3 Peak



Restrict Band NVNT a 5260MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT a 5320MHz Ant3 Peak



Restrict Band NVNT a 5320MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5260MHz Ant3 Peak



Restrict Band NVNT n20 5260MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5320MHz Ant3 Peak



Restrict Band NVNT n20 5320MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5270MHz Ant3 Peak



Restrict Band NVNT n40 5270MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Restrict Band NVNT n40 5310MHz Ant3 Peak



Restrict Band NVNT n40 5310MHz Ant3 Average




Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China


Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity






Restrict Band NVNT ac20 5260MHz Ant3 Peak



Restrict Band NVNT ac20 5260MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5320MHz Ant3 Peak



Restrict Band NVNT ac20 5320MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5270MHz Ant3 Peak



Restrict Band NVNT ac40 5270MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5310MHz Ant3 Peak



Restrict Band NVNT ac40 5310MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz Ant3 Peak



Restrict Band NVNT ac80 5290MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz Ant3 Peak



Restrict Band NVNT ac80 5290MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax20 5260MHz Ant3 Peak



Restrict Band NVNT ax20 5260MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax20 5320MHz Ant3 Peak



Restrict Band NVNT ax20 5320MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5270MHz Ant3 Peak



Restrict Band NVNT ax40 5270MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5310MHz Ant3 Peak



Restrict Band NVNT ax40 5310MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax80 5290MHz Ant3 Peak



Restrict Band NVNT ax80 5290MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax80 5290MHz Ant3 Peak



Restrict Band NVNT ax80 5290MHz Ant3 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Condition	Mode	Frequency (MHz)	Antenna	Spur Freq (MHz)	Power (dBm)	Gain (dBi)	Duty Factor (dB)	E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	a	5260	Ant4	4500	-51.29	3.59	-	47.56	Peak	68.2	Pass
NVNT	a	5260	Ant4	4500	-58.46	3.59	0	40.39	Average	54	Pass
NVNT	a	5260	Ant4	5056.92	-46.96	3.59	-	51.89	Peak	68.2	Pass
NVNT	a	5260	Ant4	5051.46	-56.77	3.59	0	42.08	Average	54	Pass
NVNT	a	5260	Ant4	5150	-48.66	3.59	-	50.19	Peak	68.2	Pass
NVNT	a	5260	Ant4	5150	-57.43	3.59	0	41.42	Average	54	Pass
NVNT	a	5320	Ant4	5350	-47.88	3.59	-	50.97	Peak	68.2	Pass
NVNT	a	5320	Ant4	5350	-57.43	3.59	0	41.42	Average	54	Pass
NVNT	a	5320	Ant4	5433.4	-46.67	3.59	-	52.18	Peak	68.2	Pass
NVNT	a	5320	Ant4	5351.4	-56.9	3.59	0	41.95	Average	54	Pass
NVNT	a	5320	Ant4	5460	-49.02	3.59	-	49.83	Peak	68.2	Pass
NVNT	a	5320	Ant4	5460	-57.92	3.59	0	40.93	Average	54	Pass
NVNT	n20	5260	Ant4	4500	-49.33	3.59	-	49.52	Peak	68.2	Pass
NVNT	n20	5260	Ant4	4500	-58.92	3.59	0	39.93	Average	54	Pass
NVNT	n20	5260	Ant4	4952.4	-47.1	3.59	-	51.75	Peak	68.2	Pass
NVNT	n20	5260	Ant4	5028.84	-56.92	3.59	0	41.93	Average	54	Pass
NVNT	n20	5260	Ant4	5150	-50.28	3.59	-	48.57	Peak	68.2	Pass
NVNT	n20	5260	Ant4	5150	-57.29	3.59	0	41.56	Average	54	Pass
NVNT	n20	5320	Ant4	5350	-47.87	3.59	-	50.98	Peak	68.2	Pass
NVNT	n20	5320	Ant4	5350	-57.05	3.59	0	41.80	Average	54	Pass
NVNT	n20	5320	Ant4	5352	-44.06	3.59	-	54.79	Peak	68.2	Pass
NVNT	n20	5320	Ant4	5352.4	-56.72	3.59	0	42.13	Average	54	Pass
NVNT	n20	5320	Ant4	5460	-50.39	3.59	-	48.46	Peak	68.2	Pass
NVNT	n20	5320	Ant4	5460	-58.25	3.59	0	40.60	Average	54	Pass
NVNT	n40	5270	Ant4	4500	-50.48	3.59	-	48.37	Peak	68.2	Pass
NVNT	n40	5270	Ant4	4500	-59.26	3.59	0	39.59	Average	54	Pass
NVNT	n40	5270	Ant4	5148	-46.67	3.59	-	52.18	Peak	68.2	Pass
NVNT	n40	5270	Ant4	5060.52	-56.76	3.59	0	42.09	Average	54	Pass
NVNT	n40	5270	Ant4	5150	-47.99	3.59	-	50.86	Peak	68.2	Pass
NVNT	n40	5270	Ant4	5150	-57.43	3.59	0	41.42	Average	54	Pass
NVNT	n40	5310	Ant4	5350	-47.79	3.59	-	51.06	Peak	68.2	Pass
NVNT	n40	5310	Ant4	5350	-56.99	3.59	0	41.86	Average	54	Pass
NVNT	n40	5310	Ant4	5351.2	-44.19	3.59	-	54.66	Peak	68.2	Pass
NVNT	n40	5310	Ant4	5353.4	-56.8	3.59	0	42.05	Average	54	Pass
NVNT	n40	5310	Ant4	5460	-50.06	3.59	-	48.79	Peak	68.2	Pass
NVNT	n40	5310	Ant4	5460	-57.74	3.59	0	41.11	Average	54	Pass
NVNT	ac20	5260	Ant4	4500	-51.08	3.59	-	47.77	Peak	68.2	Pass
NVNT	ac20	5260	Ant4	4500	-58.96	3.59	0	39.89	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac20	5260	Ant4	4952.4	-46.43	3.59	-	52.42	Peak	68.2	Pass
NVNT	ac20	5260	Ant4	5057.7	-56.94	3.59	0	41.91	Average	54	Pass
NVNT	ac20	5260	Ant4	5150	-48.73	3.59	-	50.12	Peak	68.2	Pass
NVNT	ac20	5260	Ant4	5150	-58.09	3.59	0	40.76	Average	54	Pass
NVNT	ac20	5320	Ant4	5350	-45.16	3.59	-	53.69	Peak	68.2	Pass
NVNT	ac20	5320	Ant4	5350	-57.09	3.59	0	41.76	Average	54	Pass
NVNT	ac20	5320	Ant4	5350.4	-44.5	3.59	-	54.35	Peak	68.2	Pass
NVNT	ac20	5320	Ant4	5351.2	-56.37	3.59	0	42.48	Average	54	Pass
NVNT	ac20	5320	Ant4	5460	-49.76	3.59	-	49.09	Peak	68.2	Pass
NVNT	ac20	5320	Ant4	5460	-57.82	3.59	0	41.03	Average	54	Pass
NVNT	ac40	5270	Ant4	4500	-50.26	3.59	-	48.59	Peak	68.2	Pass
NVNT	ac40	5270	Ant4	4500	-59	3.59	0	39.85	Average	54	Pass
NVNT	ac40	5270	Ant4	5062.14	-46.8	3.59	-	52.05	Peak	68.2	Pass
NVNT	ac40	5270	Ant4	5088.87	-56.99	3.59	0	41.86	Average	54	Pass
NVNT	ac40	5270	Ant4	5150	-48.66	3.59	-	50.19	Peak	68.2	Pass
NVNT	ac40	5270	Ant4	5150	-57.87	3.59	0	40.98	Average	54	Pass
NVNT	ac40	5310	Ant4	5350	-46.9	3.59	-	51.95	Peak	68.2	Pass
NVNT	ac40	5310	Ant4	5350	-55.96	3.59	0	42.89	Average	54	Pass
NVNT	ac40	5310	Ant4	5352.4	-43.09	3.59	-	55.76	Peak	68.2	Pass
NVNT	ac40	5310	Ant4	5350	-55.96	3.59	0	42.89	Average	54	Pass
NVNT	ac40	5310	Ant4	5460	-48.99	3.59	-	49.86	Peak	68.2	Pass
NVNT	ac40	5310	Ant4	5460	-57.39	3.59	0	41.46	Average	54	Pass
NVNT	ac80	5290	Ant4	4500	-50.36	3.59	-	48.49	Peak	68.2	Pass
NVNT	ac80	5290	Ant4	4500	-58.78	3.59	0	40.07	Average	54	Pass
NVNT	ac80	5290	Ant4	5112.48	-46.43	3.59	-	52.42	Peak	68.2	Pass
NVNT	ac80	5290	Ant4	5125.53	-56.64	3.59	0	42.21	Average	54	Pass
NVNT	ac80	5290	Ant4	5150	-49.58	3.59	-	49.27	Peak	68.2	Pass
NVNT	ac80	5290	Ant4	5150	-57.53	3.59	0	41.32	Average	54	Pass
NVNT	ac80	5290	Ant4	5350	-48.49	3.59	-	50.36	Peak	68.2	Pass
NVNT	ac80	5290	Ant4	5350	-57.33	3.59	0	41.52	Average	54	Pass
NVNT	ac80	5290	Ant4	5352.75	-46.15	3.59	-	52.70	Peak	68.2	Pass
NVNT	ac80	5290	Ant4	5351.75	-56.71	3.59	0	42.14	Average	54	Pass
NVNT	ac80	5290	Ant4	5460	-50.61	3.59	-	48.24	Peak	68.2	Pass
NVNT	ac80	5290	Ant4	5460	-57.84	3.59	0	41.01	Average	54	Pass
NVNT	ax20	5260	Ant4	4500	-51.4	3.59	-	47.45	Peak	68.2	Pass
NVNT	ax20	5260	Ant4	4500	-59.39	3.59	0	39.46	Average	54	Pass
NVNT	ax20	5260	Ant4	4969.56	-47.12	3.59	-	51.73	Peak	68.2	Pass
NVNT	ax20	5260	Ant4	5138.04	-56.74	3.59	0	42.11	Average	54	Pass
NVNT	ax20	5260	Ant4	5150	-49.22	3.59	-	49.63	Peak	68.2	Pass
NVNT	ax20	5260	Ant4	5150	-57.08	3.59	0	41.77	Average	54	Pass
NVNT	ax20	5320	Ant4	5350	-48.13	3.59	-	50.72	Peak	68.2	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




NVNT	ax20	5320	Ant4	5350	-57.5	3.59	0	41.35	Average	54	Pass
NVNT	ax20	5320	Ant4	5457.2	-45.87	3.59	-	52.98	Peak	68.2	Pass
NVNT	ax20	5320	Ant4	5351.6	-56.42	3.59	0	42.43	Average	54	Pass
NVNT	ax20	5320	Ant4	5460	-50.79	3.59	-	48.06	Peak	68.2	Pass
NVNT	ax20	5320	Ant4	5460	-58.19	3.59	0	40.66	Average	54	Pass
NVNT	ax40	5270	Ant4	4500	-50.57	3.59	-	48.28	Peak	68.2	Pass
NVNT	ax40	5270	Ant4	4500	-59.42	3.59	0	39.43	Average	54	Pass
NVNT	ax40	5270	Ant4	5148.81	-47.22	3.59	-	51.63	Peak	68.2	Pass
NVNT	ax40	5270	Ant4	5089.68	-56.98	3.59	0	41.87	Average	54	Pass
NVNT	ax40	5270	Ant4	5150	-48.9	3.59	-	49.95	Peak	68.2	Pass
NVNT	ax40	5270	Ant4	5150	-58.36	3.59	0	40.49	Average	54	Pass
NVNT	ax40	5310	Ant4	5350	-43.6	3.59	-	55.25	Peak	68.2	Pass
NVNT	ax40	5310	Ant4	5350	-56.72	3.59	0	42.13	Average	54	Pass
NVNT	ax40	5310	Ant4	5350	-43.6	3.59	-	55.25	Peak	68.2	Pass
NVNT	ax40	5310	Ant4	5350.8	-56.47	3.59	0	42.38	Average	54	Pass
NVNT	ax40	5310	Ant4	5460	-49.64	3.59	-	49.21	Peak	68.2	Pass
NVNT	ax40	5310	Ant4	5460	-57.55	3.59	0	41.30	Average	54	Pass
NVNT	ax80	5290	Ant4	5350	-49.63	3.59	-	49.22	Peak	68.2	Pass
NVNT	ax80	5290	Ant4	5350	-57.16	3.59	0	41.69	Average	54	Pass
NVNT	ax80	5290	Ant4	5401	-46.34	3.59	-	52.51	Peak	68.2	Pass
NVNT	ax80	5290	Ant4	5351	-56.05	3.59	0	42.80	Average	54	Pass
NVNT	ax80	5290	Ant4	5460	-48.38	3.59	-	50.47	Peak	68.2	Pass
NVNT	ax80	5290	Ant4	5460	-57.38	3.59	0	41.47	Average	54	Pass
NVNT	ax80	5290	Ant4	4500	-50.75	3.59	-	48.10	Peak	68.2	Pass
NVNT	ax80	5290	Ant4	4500	-58.51	3.59	0	40.34	Average	54	Pass
NVNT	ax80	5290	Ant4	5011.56	-46.38	3.59	-	52.47	Peak	68.2	Pass
NVNT	ax80	5290	Ant4	5086.38	-56.64	3.59	0	42.21	Average	54	Pass
NVNT	ax80	5290	Ant4	5150	-47.94	3.59	-	50.91	Peak	68.2	Pass
NVNT	ax80	5290	Ant4	5150	-57.38	3.59	0	41.47	Average	54	Pass






Test Graphs

Restrict Band NVNT a 5260MHz Ant4 Peak



Restrict Band NVNT a 5260MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT a 5320MHz Ant4 Peak



Restrict Band NVNT a 5320MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5260MHz Ant4 Peak



Restrict Band NVNT n20 5260MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n20 5320MHz Ant4 Peak



Restrict Band NVNT n20 5320MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5270MHz Ant4 Peak



Restrict Band NVNT n40 5270MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT n40 5310MHz Ant4 Peak



Restrict Band NVNT n40 5310MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5260MHz Ant4 Peak



Restrict Band NVNT ac20 5260MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac20 5320MHz Ant4 Peak



Restrict Band NVNT ac20 5320MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5270MHz Ant4 Peak



Restrict Band NVNT ac40 5270MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac40 5310MHz Ant4 Peak



Restrict Band NVNT ac40 5310MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz Ant4 Peak



Restrict Band NVNT ac80 5290MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ac80 5290MHz Ant4 Peak



Restrict Band NVNT ac80 5290MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax20 5260MHz Ant4 Peak



Restrict Band NVNT ax20 5260MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax20 5320MHz Ant4 Peak



Restrict Band NVNT ax20 5320MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5270MHz Ant4 Peak



Restrict Band NVNT ax40 5270MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax40 5310MHz Ant4 Peak



Restrict Band NVNT ax40 5310MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax80 5290MHz Ant4 Peak



Restrict Band NVNT ax80 5290MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Restrict Band NVNT ax80 5290MHz Ant4 Peak



Restrict Band NVNT ax80 5290MHz Ant4 Average



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



Ant2+Ant3+Ant4:

Condition	Mode	Frequency (MHz)	Spur Freq (MHz)	Ant2 Power (dBm)	Ant3 Power (dBm)	Ant4 Power (dBm)	Ant2+Ant3+ Ant4	Gain (dBi)	E (dBuV/m)	Detector	Limit (dBuV/m)	Verdict
NVNT	n20	5260	4500	-48.65	-49.77	-49.33	-44.45	8.36	59.14	Peak	68.2	Pass
NVNT	n20	5260	4500	-58.97	-59.57	-58.92	-54.37	8.36	49.22	Average	54	Pass
NVNT	n20	5260	4773.78	-44.46	-46.49	-47.1	-41.09	8.36	62.50	Peak	68.2	Pass
NVNT	n20	5260	4772.22	-54.08	-56.14	-56.92	-50.77	8.36	52.82	Average	54	Pass
NVNT	n20	5260	5150	-47.92	-49.85	-50.28	-44.45	8.36	59.14	Peak	68.2	Pass
NVNT	n20	5260	5150	-57.21	-57.24	-57.29	-52.48	8.36	51.11	Average	54	Pass
NVNT	n20	5320	5350	-45.03	-45.2	-47.87	-41.08	8.36	62.51	Peak	68.2	Pass
NVNT	n20	5320	5350	-55.11	-54.08	-57.05	-50.47	8.36	53.12	Average	54	Pass
NVNT	n20	5320	5352.4	-40.28	-38.88	-44.06	-35.81	8.36	67.78	Peak	68.2	Pass
NVNT	n20	5320	5350	-55.11	-52.79	-56.72	-49.8	8.36	53.79	Average	54	Pass
NVNT	n20	5320	5460	-47.26	-49.14	-50.39	-43.97	8.36	59.62	Peak	68.2	Pass
NVNT	n20	5320	5460	-58.11	-58.23	-58.25	-53.43	8.36	50.16	Average	54	Pass
NVNT	n40	5270	4500	-51.92	-51.05	-50.48	-46.34	8.36	57.25	Peak	68.2	Pass
NVNT	n40	5270	4500	-59.33	-59.61	-59.26	-54.63	8.36	48.96	Average	54	Pass
NVNT	n40	5270	4806.99	-41.49	-45.97	-46.67	-39.29	8.36	64.30	Peak	68.2	Pass
NVNT	n40	5270	4806.99	-50.7	-54.7	-56.76	-49.74	8.36	53.85	Average	54	Pass
NVNT	n40	5270	5150	-49.39	-49.11	-47.99	-44.02	8.36	59.57	Peak	68.2	Pass
NVNT	n40	5270	5150	-57.41	-57.01	-57.43	-52.51	8.36	51.08	Average	54	Pass
NVNT	n40	5310	5350	-43.23	-41.52	-47.79	-38.71	8.36	64.88	Peak	68.2	Pass
NVNT	n40	5310	5350	-53.83	-52.88	-56.99	-49.67	8.36	53.92	Average	54	Pass
NVNT	n40	5310	5350.4	-38.84	-36.79	-44.19	-35.62	8.36	67.97	Peak	68.2	Pass
NVNT	n40	5310	5351.4	-52.75	-52.44	-56.8	-49.62	8.36	53.97	Average	54	Pass
NVNT	n40	5310	5460	-49.33	-50.38	-50.06	-45.13	8.36	58.46	Peak	68.2	Pass
NVNT	n40	5310	5460	-57.83	-57.43	-57.74	-52.89	8.36	50.70	Average	54	Pass
NVNT	ac20	5260	4500	-50.75	-51.33	-51.08	-46.28	8.36	57.31	Peak	68.2	Pass
NVNT	ac20	5260	4500	-59.45	-59.5	-58.96	-54.53	8.36	49.06	Average	54	Pass
NVNT	ac20	5260	4787.82	-44.33	-46.95	-46.43	-40.98	8.36	62.61	Peak	68.2	Pass
NVNT	ac20	5260	4787.82	-53.36	-56.39	-56.94	-50.49	8.36	53.10	Average	54	Pass
NVNT	ac20	5260	5150	-49.32	-48.55	-48.73	-44.08	8.36	59.51	Peak	68.2	Pass
NVNT	ac20	5260	5150	-57.13	-57	-58.09	-52.61	8.36	50.98	Average	54	Pass
NVNT	ac20	5320	5350	-39.6	-40.44	-45.16	-36.37	8.36	67.22	Peak	68.2	Pass
NVNT	ac20	5320	5350	-54.41	-53.35	-57.09	-49.91	8.36	53.68	Average	54	Pass
NVNT	ac20	5320	5350.8	-37.94	-33.56	-44.5	-35.46	8.36	68.13	Peak	68.2	Pass
NVNT	ac20	5320	5351.4	-54.36	-52.32	-56.37	-49.61	8.36	53.98	Average	54	Pass
NVNT	ac20	5320	5460	-49.54	-50.26	-49.76	-45.07	8.36	58.52	Peak	68.2	Pass
NVNT	ac20	5320	5460	-58.05	-58.02	-57.82	-53.19	8.36	50.40	Average	54	Pass
NVNT	ac40	5270	4500	-50.31	-50	-50.26	-45.42	8.36	58.17	Peak	68.2	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ac40	5270	4500	-59.31	-59.17	-59	-54.39	8.36	49.20	Average	54	Pass
NVNT	ac40	5270	4806.99	-43.71	-44.56	-46.8	-40.07	8.36	63.52	Peak	68.2	Pass
NVNT	ac40	5270	4806.99	-52.42	-54.06	-56.99	-49.64	8.36	53.95	Average	54	Pass
NVNT	ac40	5270	5150	-49.95	-48.58	-48.66	-44.25	8.36	59.34	Peak	68.2	Pass
NVNT	ac40	5270	5150	-57.89	-57.01	-57.87	-52.8	8.36	50.79	Average	54	Pass
NVNT	ac40	5310	5350	-44.72	-38.49	-46.9	-37.08	8.36	66.51	Peak	68.2	Pass
NVNT	ac40	5310	5350	-55.7	-52.34	-55.96	-49.66	8.36	53.93	Average	54	Pass
NVNT	ac40	5310	5350.2	-43.25	-51.09	-43.09	-39.82	8.36	63.77	Peak	68.2	Pass
NVNT	ac40	5310	5350.2	-55.58	-57.75	-55.96	-51.56	8.36	52.03	Average	54	Pass
NVNT	ac40	5310	5460	-50.72	-38.49	-48.99	-37.89	8.36	65.70	Peak	68.2	Pass
NVNT	ac40	5310	5460	-57.73	-52.34	-57.39	-50.29	8.36	53.30	Average	54	Pass
NVNT	ac80	5290	4500	-52.04	-51.17	-50.36	-46.36	8.36	57.23	Peak	68.2	Pass
NVNT	ac80	5290	4500	-59.05	-58.8	-58.78	-54.1	8.36	49.49	Average	54	Pass
NVNT	ac80	5290	5133.36	-46.23	-46.31	-46.43	-41.55	8.36	62.04	Peak	68.2	Pass
NVNT	ac80	5290	5146.41	-56.21	-56.69	-56.64	-51.74	8.36	51.85	Average	54	Pass
NVNT	ac80	5290	5150	-48.76	-49	-49.58	-44.33	8.36	59.26	Peak	68.2	Pass
NVNT	ac80	5290	5150	-56.35	-57.08	-57.53	-52.19	8.36	51.40	Average	54	Pass
NVNT	ac80	5290	5350	-43.31	-42.03	-48.49	-39.08	8.36	64.51	Peak	68.2	Pass
NVNT	ac80	5290	5350	-54.89	-53.43	-57.33	-50.16	8.36	53.43	Average	54	Pass
NVNT	ac80	5290	5351	-40.28	-40.53	-46.15	-36.85	8.36	66.74	Peak	68.2	Pass
NVNT	ac80	5290	5350	-54.89	-52.8	-56.71	-49.74	8.36	53.85	Average	54	Pass
NVNT	ac80	5290	5460	-50.05	-47.33	-50.61	-44.31	8.36	59.28	Peak	68.2	Pass
NVNT	ac80	5290	5460	-58.38	-57.63	-57.84	-53.17	8.36	50.42	Average	54	Pass
NVNT	ax20	5260	4500	-50.18	-51.18	-51.4	-46.12	8.36	57.47	Peak	68.2	Pass
NVNT	ax20	5260	4500	-59.4	-59.38	-59.39	-54.62	8.36	48.97	Average	54	Pass
NVNT	ax20	5260	4773	-45.06	-46.74	-47.12	-41.44	8.36	62.15	Peak	68.2	Pass
NVNT	ax20	5260	4787.82	-53.63	-56.51	-56.74	-50.61	8.36	52.98	Average	54	Pass
NVNT	ax20	5260	5150	-49.95	-48.59	-49.22	-44.45	8.36	59.14	Peak	68.2	Pass
NVNT	ax20	5260	5150	-57.06	-56.56	-57.08	-52.12	8.36	51.47	Average	54	Pass
NVNT	ax20	5320	5350	-42.8	-36.53	-48.13	-35.47	8.36	68.12	Peak	68.2	Pass
NVNT	ax20	5320	5350	-53.38	-51.86	-57.5	-49.83	8.36	53.76	Average	54	Pass
NVNT	ax20	5320	5350.8	-40.26	-35.71	-45.87	-35.86	8.36	67.73	Peak	68.2	Pass
NVNT	ax20	5320	5350.8	-52.6	-51.72	-56.42	-49.74	8.36	53.85	Average	54	Pass
NVNT	ax20	5320	5460	-48.43	-50.25	-50.79	-44.93	8.36	58.66	Peak	68.2	Pass
NVNT	ax20	5320	5460	-57.47	-57.85	-58.19	-53.06	8.36	50.53	Average	54	Pass
NVNT	ax40	5270	4500	-51.14	-51.72	-50.57	-46.35	8.36	57.24	Peak	68.2	Pass
NVNT	ax40	5270	4500	-58.74	-59.09	-59.42	-54.3	8.36	49.29	Average	54	Pass
NVNT	ax40	5270	4806.18	-42.23	-45.12	-47.22	-39.6	8.36	63.99	Peak	68.2	Pass
NVNT	ax40	5270	4806.99	-51.12	-54.39	-56.98	-49.69	8.36	53.90	Average	54	Pass
NVNT	ax40	5270	5150	-48.96	-48.55	-48.9	-44.03	8.36	59.56	Peak	68.2	Pass
NVNT	ax40	5270	5150	-57.54	-57.29	-58.36	-52.94	8.36	50.65	Average	54	Pass



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity



NVNT	ax40	5310	5350	-40.82	-39.85	-43.6	-36.38	8.36	67.21	Peak	68.2	Pass
NVNT	ax40	5310	5350	-55.89	-52.41	-56.72	-49.81	8.36	53.78	Average	54	Pass
NVNT	ax40	5310	5350	-40.82	-36.78	-43.6	-35.43	8.36	68.16	Peak	68.2	Pass
NVNT	ax40	5310	5350.2	-55.35	-52.4	-56.47	-49.62	8.36	53.97	Average	54	Pass
NVNT	ax40	5310	5460	-49.24	-50.72	-49.64	-45.05	8.36	58.54	Peak	68.2	Pass
NVNT	ax40	5310	5460	-58	-57.85	-57.55	-53.02	8.36	50.57	Average	54	Pass
NVNT	ax80	5290	5350	-44.3	-44.06	-49.63	-40.59	8.36	63.00	Peak	68.2	Pass
NVNT	ax80	5290	5350	-54.9	-52.88	-57.16	-49.87	8.36	53.72	Average	54	Pass
NVNT	ax80	5290	5351.25	-42.27	-42.98	-46.34	-38.77	8.36	64.82	Peak	68.2	Pass
NVNT	ax80	5290	5351.25	-54.19	-52.88	-56.05	-49.61	8.36	53.98	Average	54	Pass
NVNT	ax80	5290	5460	-50.75	-49.37	-48.38	-44.62	8.36	58.97	Peak	68.2	Pass
NVNT	ax80	5290	5460	-58.36	-57.73	-57.38	-53.03	8.36	50.56	Average	54	Pass
NVNT	ax80	5290	4500	-51.19	-51.61	-50.75	-46.4	8.36	57.19	Peak	68.2	Pass
NVNT	ax80	5290	4500	-58.65	-58.7	-58.51	-53.85	8.36	49.74	Average	54	Pass
NVNT	ax80	5290	5141.19	-46.24	-45.62	-46.38	-41.3	8.36	62.29	Peak	68.2	Pass
NVNT	ax80	5290	5149.02	-56.24	-56.61	-56.64	-51.72	8.36	51.87	Average	54	Pass
NVNT	ax80	5290	5150	-48.83	-48.72	-47.94	-43.71	8.36	59.88	Peak	68.2	Pass
NVNT	ax80	5290	5150	-56.74	-57.15	-57.83	-57.38	8.36	49.21	Average	54	Pass





E.5 Frequency Stability


Condition	Mode	Frequency (MHz)	Antenna	Measured Frequency (MHz)	Frequency Error (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
NVNT	ac20	5260	Ant2	5260	0	0	25	Pass
NVNT	ac20	5300	Ant2	5300	0	0	25	Pass
NVNT	ac20	5320	Ant2	5320.02	20000	3.76	25	Pass
NVNT	ac40	5270	Ant2	5269.96	-40000	-7.59	25	Pass
NVNT	ac40	5310	Ant2	5310	0	0	25	Pass
NVNT	ac80	5290	Ant2	5290	0	0	25	Pass
NVNT	ax20	5260	Ant2	5260.02	20000	3.8	25	Pass
NVNT	ax20	5300	Ant2	5300	0	0	25	Pass
NVNT	ax20	5320	Ant2	5320	0	0	25	Pass
NVNT	ax40	5270	Ant2	5270	0	0	25	Pass
NVNT	ax40	5310	Ant2	5310	0	0	25	Pass
NVNT	ax80	5290	Ant2	5290	0	0	25	Pass






Test Graphs

Freq. Stability NVNT ac20 5260MHz Ant2



Freq. Stability NVNT ac20 5300MHz Ant2



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac20 5320MHz Ant2



Freq. Stability NVNT ac40 5270MHz Ant2



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac40 5310MHz Ant2



Freq. Stability NVNT ac80 5290MHz Ant2



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax20 5260MHz Ant2



Freq. Stability NVNT ax20 5300MHz Ant2



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax20 5320MHz Ant2



Freq. Stability NVNT ax40 5270MHz Ant2



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ax40 5310MHz Ant2



Freq. Stability NVNT ax80 5290MHz Ant2



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity




Condition	Mode	Frequency (MHz)	Antenna	Measured Frequency (MHz)	Frequency Error (Hz)	Deviation (ppm)	Limit (ppm)	Verdict
NVNT	a	5260	Ant3	5259.98	-20000	-3.8	25	Pass
NVNT	a	5300	Ant3	5300	0	0	25	Pass
NVNT	a	5320	Ant3	5319.98	-20000	-3.76	25	Pass
NVNT	n20	5260	Ant3	5259.98	-20000	-3.8	25	Pass
NVNT	n20	5300	Ant3	5299.98	-20000	-3.77	25	Pass
NVNT	n20	5320	Ant3	5319.98	-20000	-3.76	25	Pass
NVNT	n40	5270	Ant3	5269.96	-40000	-7.59	25	Pass
NVNT	n40	5310	Ant3	5310	0	0	25	Pass
NVNT	ac20	5260	Ant3	5260	0	0	25	Pass
NVNT	ac20	5300	Ant3	5300.02	20000	3.77	25	Pass
NVNT	ac20	5320	Ant3	5319.98	-20000	-3.76	25	Pass
NVNT	ac40	5270	Ant3	5270	0	0	25	Pass
NVNT	ac40	5310	Ant3	5309.96	-40000	-7.53	25	Pass
NVNT	ac80	5290	Ant3	5290	0	0	25	Pass
NVNT	ax20	5260	Ant3	5260	0	0	25	Pass
NVNT	ax20	5300	Ant3	5299.98	-20000	-3.77	25	Pass
NVNT	ax20	5320	Ant3	5319.98	-20000	-3.76	25	Pass
NVNT	ax40	5270	Ant3	5270	0	0	25	Pass
NVNT	ax40	5310	Ant3	5310	0	0	25	Pass
NVNT	ax80	5290	Ant3	5290	0	0	25	Pass






Test Graphs

Freq. Stability NVNT a 5260MHz Ant3



Freq. Stability NVNT a 5300MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT a 5320MHz Ant3



Freq. Stability NVNT n20 5260MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT n20 5300MHz Ant3



Freq. Stability NVNT n20 5320MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT n40 5270MHz Ant3



Freq. Stability NVNT n40 5310MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac20 5260MHz Ant3



Freq. Stability NVNT ac20 5300MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.


Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com


Scan code to check authenticity



Freq. Stability NVNT ac20 5320MHz Ant3



Freq. Stability NVNT ac40 5270MHz Ant3



Shenzhen LCS Compliance Testing Laboratory Ltd.

Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen, 518000, China

Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com

Scan code to check authenticity