


PAXA GM2Pro

True Wireless Earphones



Manual

Please read all instructions carefully and retain for future use

Usage Instruction

1. (Don't attempt to disassemble the unit and charge any part except where it is operation method mentioned in the manual.

2. (Don't expose the unit to liquid, moisture or humidity, since it is not a waterproof product.

3. (Disconnect the unit with your ID card and move it to the software if it is liquid get inside the unit.

4. (Don't assemble or disassemble the unit to avoid electric shock that is water on your hands.

5. (Don't expose the unit to extremely high temperature or disposed the unit in fire as well result in an explosion.

6. (Don't place the unit in an electromagnetic interference environment to avoid malfunction.

Product specification

Bluetooth version: V4.0

Transmission distance: 10M

Bluetooth capacity: 20M (headphones)

Standby time: approximately 5.5 hours (headphones)

Charging time: approximately 1 hour (for headphones)

Rated input: 5V/20mA

Charging case specification

Battery capacity: 300mAh

Charging time: approximately 1.5 hours

Rated output: 5V/300mA

[All technical information is subject to actual performance]

Charge the charging box

Connect the charging box to the 5V power adapter with the Type-C charging cable.

(Friendly reminder: When opening or closing the charging case, if the blue light flashes, please charge the case promptly.)

Product operating instructions

1. Turn on the computer

Method 1: Take it out from the charging compartment and turn on the headset automatically.

Method 2: Press and hold the headphones to touch the headphones for 5 seconds to turn on the headphones.

2. Shut down

Method 1: Put the headset back to the charging compartment, and turn off the headset.

Method 2: Auto shutdown after 3 minutes if no connection while powered on.


Packing list




Headphone X 2



Charging case X 1



User manual X 1



Type-C X 1

Product schematic description



Indicator light



Type-C

LED Indicator Status

1. Green light is light for 1 second

2. Red light is light for 1 second

3. Flashing light is the device connected successfully, and the secondary headphones turn off

4. The headset and the device connected successfully, the light of headphones turn off

5. The main headset's blue light flashes quickly, and the secondary headphones turn off

6. Low battery, blue flashing

7. When the headset light remains solid for 1 second

Headset Indicator Light

Charging bin digital display



Indicator light



Type-C

Product operating instructions

1. Turn on the computer

Method 1: Take it out from the charging compartment and turn on the headset automatically.

Method 2: Press and hold the headphones to touch the headphones for 5 seconds to turn on the headphones.

2. Shut down

Method 1: Put the headset back to the charging compartment, and turn off the headset.

Method 2: Auto shutdown after 3 minutes if no connection while powered on.


Packing list




Headphone X 2



Charging case X 1



User manual X 1



Type-C X 1

Product schematic description



Indicator light



Type-C

LED Indicator Status

1. Green light is light for 1 second

2. Red light is light for 1 second

3. Flashing light is the device connected successfully, and the secondary headphones turn off

4. The headset and the device connected successfully, the light of headphones turn off

5. The main headset's blue light flashes quickly, and the secondary headphones turn off

6. Low battery, blue flashing

7. When the headset light remains solid for 1 second

Headset Indicator Light

Charging bin digital display



Indicator light



Type-C

Product operating instructions

1. Turn on the computer

Method 1: Take it out from the charging compartment and turn on the headset automatically.

Method 2: Press and hold the headphones to touch the headphones for 5 seconds to turn on the headphones.

2. Shut down

Method 1: Put the headset back to the charging compartment, and turn off the headset.

Method 2: Auto shutdown after 3 minutes if no connection while powered on.


Packing list




Headphone X 2



Charging case X 1



User manual X 1



Type-C X 1

Product schematic description



Indicator light



Type-C

LED Indicator Status

1. Green light is light for 1 second

2. Red light is light for 1 second

3. Flashing light is the device connected successfully, and the secondary headphones turn off

4. The headset and the device connected successfully, the light of headphones turn off

5. The main headset's blue light flashes quickly, and the secondary headphones turn off

6. Low battery, blue flashing

7. When the headset light remains solid for 1 second

Headset Indicator Light

Charging bin digital display



Indicator light



Type-C

Product operating instructions

1. Turn on the computer

Method 1: Take it out from the charging compartment and turn on the headset automatically.

Method 2: Press and hold the headphones to touch the headphones for 5 seconds to turn on the headphones.

2. Shut down

Method 1: Put the headset back to the charging compartment, and turn off the headset.

Method 2: Auto shutdown after 3 minutes if no connection while powered on.


Packing list




Headphone X 2



Charging case X 1



User manual X 1



Type-C X 1

Product schematic description



Indicator light



Type-C

LED Indicator Status

1. Green light is light for 1 second</

[illegible][illegible][illegible][illegible]

文件名称	PAXA GM2Pro 说明书			材料	70g书写纸		单位	mm	厂商物料编号	变更履历	修改		日期	
文件尺寸	80X100mm (单P尺寸)			工艺	1C印刷 风琴折		公差	±0.5mm			审核		日期	
设计日期	2025/4/23	文件版本	V02				比例	1:1			批准		日期	