

Photographs of the Device

Internal Front View –Receiver, Exciter, and Control Modules (“Cluster”)




APPLICANT: MOTOROLA

EQUIPMENT TYPE: ABZ89FC3795


Photographs of the Device

Internal Front View – Control Module with Housing, Top View




Photographs of the Device

Internal Front View – Control Board, Top View



Photographs of the Device

Internal Front View – Exciter Board, Top View




APPLICANT: MOTOROLA

EQUIPMENT TYPE: ABZ89FC3795

Photographs of the Device


Internal Front View –Receiver Board, Top View



Photographs of the Device

Internal Front View – Power Amplifier Module

Inside View



Photographs of the Device


Internal Front View – Power Amplifier Module, Cover Removed



Photographs of the Device

Internal Front View – Power Supply Module


Inside View




Photographs of the Device

Internal Front View – Backplane

Front View



Rear View




Photographs of the Device

Internal Back View – Receiver, Exciter, and Control Modules (“Cluster”), Disassembled




Photographs of the Device

Internal Back View – Control Board, Bottom View



Photographs of the Device

Internal Back View – Exciter Board, Bottom View



Photographs of the Device

Internal Back View – Receiver Board, Bottom View



Photographs of the Device

Internal Back View – Power Amplifier Module


Outside View



Photographs of the Device

Internal Back View – Power Supply Module

Outside View



Photographs of the Device

Internal Back View – Backplane

