

Photographs of the Device

Internal Front View –Receiver, Exciter, and Control Modules (“Cluster”)




APPLICANT: MOTOROLA

EQUIPMENT TYPE: ABZ89FC5817

Photographs of the Device

Internal Front View – Control Module with Housing, Top View



Photographs of the Device

Internal Front View – Control Board, Top View



Photographs of the Device

Internal Front View – Exciter Board, Top View




APPLICANT: MOTOROLA

EQUIPMENT TYPE: ABZ89FC5817

Photographs of the Device

Internal Front View –Receiver Board, Top View



Photographs of the Device

Internal Front View – Power Amplifier Module



Photographs of the Device

Internal Front View – Power Amplifier Module, Cover Removed



Photographs of the Device

Internal Front View – Power Supply Module





Photographs of the Device

Internal Front View – Power Supply Module, Circuit Board, Top View



Photographs of the Device

Internal Front View – Backplane




Photographs of the Device

Internal Back View – Receiver, Exciter, and Control Modules (“Cluster”), Disassembled



Photographs of the Device

Internal Back View – Control Board, Bottom View




APPLICANT: MOTOROLA

EQUIPMENT TYPE: ABZ89FC5817

Photographs of the Device

Internal Back View – Exciter Board, Bottom View



Photographs of the Device

Internal Back View – Receiver Board, Bottom View



Photographs of the Device

Internal Back View – Power Amplifier Module




Photographs of the Device

Internal Back View – Power Supply Module



Photographs of the Device

Internal Back View – Power Supply Module, Circuit Board, Back View



Photographs of the Device

Internal Back View – Backplane

