



**MOTOROLA**

Motorola Solutions, Inc.  
1299 E. Algonquin Road  
Schaumburg, IL 60196  
U.S.A.

June 1, 2011

Federal Communications Commission  
Office of Engineering Technology

Subject: FCC ID: ABZ89FT7638 Attestation Letter  
Model: 5480BH

To Whom It May Concern:

Canopy device FCC ID: ABZ89FT7638 does not transmit in the TDWR band (5600MHz-5650MHz).

Software version R10.7 notches the TDWR band and, therefore, prevents transmissions from 5600MHz to 5650MHz.

Sincerely,

A handwritten signature in black ink, appearing to read 'SMP', followed by a horizontal line.

Steven M. Payne  
RF Principal Staff Engineer  
Canopy Regulatory Engineering  
Motorola Solutions, Inc.