

November 23, 2010

To: Elite Electronic Engineering
Re: Identification Change for *iDEN Multi-Carrier– Standard Capacity Transmitter*

Per CFR 47, Paragraph 2.933, Motorola respectfully requests a change in identification for the indicated transmitter.

The affected transmitter is as follows:

Existing FCC ID	Lower (MHz)	Upper (MHz)	New FCC ID
PURMCSERIESSC	851.0125	868.9875	ABZMCSERIESSC

(1) The original identification used

The original identification used for the transmitter is *PURMCSERIESSC*. This is a multi-carrier transmitter that is used in *iDEN* systems.

(2) The date of the original grant

The date of the original grant of equipment authorization is *02/28/2008*.

(3) How the equipment bearing the modified identification differs from the original equipment


The change requested is in identification only. There is no change in design, circuitry, or construction of the unit other than company logos and labeling. The front panels on the equipment have the Motorola logos rather than the RadioFrame Networks logos. The identification label also contains 'Motorola' as well as the updated FCC identification number, *ABZMCSERIESSC*.

(4) Whether the original test results continue to be representative / applicable

All original test results currently on file with the commission are applicable and are representative of current and future shipping product. The equipment will be completely compatible and interchangeable with the existing equipment previously shipped by RFN. The form, fit, and function of the equipment is identical.

(5) Exterior appearance photographs

An image of the new label is shown below. The FCC ID label goes on the inside surface of the bulkhead at the top of the rack. External photographs of the unit are shown on the following page.



APPLICANT: MOTOROLA

EQUIPMENT TYPE: ABZMCSERIESSC



(Front View)



(Back View)

iDEN Multi-Carrier Transmitter – ABZMCSERIESHP10